Branch maintenance form

Unit no.	LFT-83926	**Date of visit**	20 Oct 2026
Site address	2 Quarry Road, Eastbrook	**Engineer**	Diego Vidal

Pos.	Component	Observation	Units
1	Unintended car movement detector	out of adjustment, car top	1
2	Car top inspection box	corroded, car	1
3	CAR EMERG LIGHT	LSE, car	1
4	Governor tension pulley	corroded, pit	1
5	Hydraulic oil	damaged, machine room	40 l
6	CAR OP PANEL PUSH BTN	FLTY, car	4
7	LDG DR CLOSER SPRING	FLTY, floor 3	1
8	Machine room socket	corroded, machine room	2

Pos.	Component	Observation	Units
9	Braille floor plate	out of adjustment, floor 3	4
10	Hydraulic oil	faulty, machine room	50 l