Periodic inspection findings

Lift no. LFT-44133

Address 19 Beacon Hill, Southcliff

Date 04/09/2026

Inspector Pablo Molina

Ref	Finding
F-01	machine room: Hydraulic cylinder packing faulty (qty 1)
F-02	floor 0: CAR DR CONT BRKN (qty 1)
F-03	floor 4: Landing door hanger broken (qty 1)
F-04	floor 7: OVERLOAD IND LSE (qty 1)
F-05	pit: Shaft lighting fitting out of adjustment (qty 2)
F-06	car: Car position indicator loose (qty 1)
F-07	machine room: BRAKE COIL NOT WKG (qty 2)
F-08	car top: Final limit switch faulty (qty 1)
F-09	building: Stairwell lighting out next to the landing door (qty 1)
F-10	building: Water ingress in the pit from the building drainage (qty 1)
F-11	floor 5: LIGHT CURTAIN NOT WKG (qty 1)
F-12	building: Owner asks for an extra stop at the basement (qty 1)
F-13	pit: Pit ladder out of adjustment (qty 1)
F-14	pit: Governor tension pulley out of adjustment (qty 1)
F-15	pit: Buffer loose (qty 2)
F-16	machine room: Load weighing sensor not working (qty 1)

Ref	Finding
F-17	pit: Governor rope, 6 mm corroded (qty 60 m)