Branch maintenance form

Unit no.		**Date of visit**	02 Sep 2026
Site address	115 Chapel Row, Fairholm	**Engineer**	Luis Campos

Pos.	Component	Observation	Units
1	Inverter cooling fan	not working, machine room	2
2	Control board relay	out of adjustment, machine room	1
3	OVERSPEED GOV REPL	REQUIRED, car top	1
4	Machine room window glass cracked	building	1
5	Car position indicator, TFT colour	out of adjustment, car	1
6	Car guide shoe insert, sliding	worn, car	3
7	Car ventilation fan	worn, car	1
8	Car handrail, aluminium	faulty, car	2

Pos.	Component	Observation	Units
9	Car LED ceiling panel, 600 x 600 mm	corroded, car	1
10	Car floor covering, rubber	out of adjustment, car	2 m2
11	Overspeed governor, replacement	required, car top	1
12	Traction sheave, regrooving	required, machine room	1
13	LIGHT CURTAIN SINGLE-SIDE	WRN, floor 4	1