Branch maintenance form

Unit no.	LFT-19540	**Date of visit**	13 Sep 2026
Site address	106 Mill Lane, Ashdale	**Engineer**	Ana Ferrer

Pos.	Component	Observation	Units
1	Shaft lighting fitting	out of adjustment, pit	1
2	Hall position indicator, TFT colour	corroded, floor 5	1
3	HALL LANTERN	NOT WKG, floor 4	4
4	Stairwell lighting out next to the landing door	building	1
5	Car door contact	faulty, floor 0	2
6	Car position indicator	damaged, car	1
7	Buffer	loose, pit	2
8	Floor levelling sensor, optical	damaged, machine room	1

Pos.	Component	Observation	Units
9	Safety gear adjustment	required, car top	1
10	DEFLECTOR PULLEY BRG	OUT OF ADJ, machine room	2
11	EMERG TEL GSM MODULE	BRKN, car top	1
12	Water ingress in the pit from the building drainage	building	1
13	Fuse, 16 A	loose, machine room	3
14	CAR APRON	BRKN, car	1
15	GOV ROPE 6 MM	DMGD, pit	70 m
16	Floor levelling sensor, magnetic	out of adjustment, machine room	2
17	LDG CALL BTN UP AND DOWN	CORR, floor 1	3
18	Landing door interlock, mechanical lock	not working, floor 4	2

Pos.	Component	Observation	Units
19	CAR POS IND TFT COLOUR	OUT OF ADJ, car	1
20	Motor encoder, absolute	out of adjustment, machine room	1