```
        " Name:ABS Origin Search
        " Func:ABS Origin Serach Control
        " From:MPM011

        VAR;
00000       LONG Axis_IDX1 = 0                                  " Axis Index1
00001       LONG Axis_IDX2 = 0                                  " Axis Index2
00002       LONG Axis_IDX3 = 0                                  " Axis Index3
00003       LONG L1_PW = 0,                                     " Line1 Axis Word Offset
00004       LONG L1_PL = 0,                                     " Line1 Axis Word Offset

00005       LONG Axis_IO_Chuck1 = 0;
00006       LONG Axis_IO_B_Chuck1 = 0;
00007       LONG Axis_IO_Chuck2 = 0;
00008       LONG Axis_IO_B_Chuck2 = 0
        END_VAR;

00009       MW00061 = MW02782                                   "  Axis Index Copy

00010       UFC GET_TYPE MW02782,,DB0000F DB00008 DW00001 MW00060 MW00062 MW00063;

00011       Axis_IDX1 = MW00061 - 1;
00012       Axis_IDX2 = MW00062 - 1;
00013       Axis_IDX3 = MW00063 - 1;

00014       MB102100[Axis_IDX1] = 1                             " ABS Search Start
00015       IF MW00060 == 2;
00016           MB102100[Axis_IDX2] = 1                         " ABS Search Start
00017       IEND;
00018       IF MW00060 == 3;
00019           MB102100[Axis_IDX2] = 1                         " ABS Search Start
00020           MB102100[Axis_IDX3] = 1                         " ABS Search Star
00021       IEND;

00022       MB101200[Axis_IDX1] = 1                             " While Zero Returning
00023       IF MW00060 == 2;
00024           MB101200[Axis_IDX2] = 1                         " While Zero Returning
00025       IEND;
00026       IF MW00060 == 3;
00027           MB101200[Axis_IDX2] = 1                         " While Zero Returning
00028           MB101200[Axis_IDX3] = 1                         " While Zero Returning
00029       IEND;

00030       SFORK   DW00001 == 0 ? Label0,                      " Address Reset
                    DW00001 == 1 ? Label1,                      " Sensor Search
                    DW00001 == 2 ? Label2,                      " Sensor Search(GantryType)
                    DW00001 == 3 ? Label3,                      " PERR Search (1 Direction)
                    DW00001 == 4 ? Label4,                      " PERR Search (2 Direction)
                    DW00001 == 5 ? Label5,                      " Torque Search (1 Direction)
                    DW00001 == 6 ? Label6,                      " Torque Search (2 Direction)
                    DW00001 == 7 ? Label7,                      " Torque Search (Shift Axis)
                    DW00001 == 8 ? Label8,                      " Torque Search (IAI
                    DEFAULT ? LabelD;

00031       Label0:
                " Address Reset

00032           MSEE MPS114;                                    " Abs Origin Reset
00033           MB102400[Axis_IDX1] = 1                         " ABS Offset 0reset Ind
00034           IF MW00060 == 2;
00035               MB102400[Axis_IDX2] = 1                     " ABS Offset 0reset Ind
00036           IEND;
00037           IOW MB02700F == 1                               " Wait Address 0Reset

00038           JOINTO LabelX;

00039       Label1:
                " Sensor Search

00040           L1_PW = (MW02782-1) * 100                       " Parameter Index
00041           L1_PL = (MW02782-1) * 100 / 2                   " Parameter Index

                " SoftLimit Break
00042           ML00066 = 2147483647;
00043           ML00068 = -2147483648;
00044           MSEE MPS115;

                " High Speed Search
00045           MB026002 = DB00008                              " Moving direction(JOG/STEP)
00046           ML02612 = ML40008[L1_PL]                        " Speed reference setting

00047           MW02610 = 7;                                    " Motion command <- STEP COMMAND
00048           IOW (MB027010 | MB027011) == 1                  " ABS ORG Input or OT Sensor
00049           MW02610 = 0;                                    " Motion command <- 0 Clear
00050           IOW MB027009 == 1                               " Motion command response code is 0

```

```
        TIM T100;

        " OT센서 감지시 원점센서 감지될때까지 반대로 이동
        IF MB027011 == 1                              " OT센서
            MB026002 = !DB00008                       " Moving direction(JOG/STEP)
            ML02612 = ML40008[L1_PL]                  " Speed reference setting
            MW02610 = 7;                              " Motion command <- STEP COMMAND

            IOW MB027010 == 1                         " ABS ORG Input or OT Sensor
            MW02610 = 0;                              " Motion command <- 0 Clear
            IOW MB027009 == 1                         " Motion command response code is 0

            TIM T30;

            MB026002 = !DB00008                       " Moving direction(JOG/STEP)
            ML02612 = ML40008[L1_PL]                  " Speed reference setting

            MW02610 = 7;                              " Motion command <- STEP COMMAND
            IOW MB027010 == 0                         " ABS ORG Input or OT Sensor
            MW02610 = 0;                              " Motion command <- 0 Clear
            IOW MB027009 == 1                         " Motion command response code is 0

            TIM T30;

            MB026002 = DB00008                        " Moving direction(JOG/STEP)
            ML02612 = ML40008[L1_PL]                  " Speed reference setting
            MW02610 = 7;                              " Motion command <- STEP COMMAND

            IOW MB027010 == 1                         " ABS ORG Input or OT Sensor
            MW02610 = 0;                              " Motion command <- 0 Clear
            IOW MB027009 == 1                         " Motion command response code is 0
        IEND;

        " Low Speed Search
        MB026002 = !DB00008                           " Moving direction(JOG/STEP)
        ML02612 = ML40010[L1_PL]                      " Speed reference setting

        MW02610 = 7;                                  " Motion command <- STEP COMMAND
        IOW MB027010 == 0;
        MW02610 = 0;                                  " Motion command <- 0 Clear
        IOW MB027009 == 1                             " Motion command response code is 0

        TIM T100;

        " Step Search
        MB026002 = DB00008                            " Moving direction(JOG/STEP)
        ML02612 = ML40010[L1_PL]                      " Speed reference setting
        ML02624 = 3;                                  " Step travel distance

        DB00000E = 0;
        WHILE DB00000E == 0;
            IF MB027010 == 1;
                DB00000E = 1;
            ELSE;
                MW02610 = 8;                          " Motion command <- STEP COMMAND
                IOW MB02700B == 1                     " Motion command response code not 0
                IOW MB027008 == 1                     " Motion command execution completed
                MW02610 = 0;                          " Motion command <- 0 Clear
                IOW MB027009 == 1                     " Motion command response code is 0
            IEND;
            EOX;
        WEND;

        MSEE MPS114;                                  " Abs Origin Reset

        MB102400[Axis_IDX1] = 1                       " ABS Offset 0reset Ind
        IF MW00060 == 2                               " 2 Axis Gentry
            MB102400[Axis_IDX2] = 1                   " ABS Offset 0reset Ind
        IEND;

        IF MW00060 == 3                               " 3 Axis Gentry
            MB102400[Axis_IDX2] = 1                   " ABS Offset 0reset Ind
            MB102400[Axis_IDX3] = 1                   " ABS Offset 0reset In
        IEND;

        " SoftLimit Update
        ML00066 = ML40094[L1_PL];
        ML00068 = ML40098[L1_PL];
        MSEE MPS115;

        JOINTO LabelX;

    Label2:
        " Sensor Search(GantryType)

        L1_PW = (MW02782-1) * 100                     " Parameter Index
        L1_PL = (MW02782-1) * 100 / 2                 " Parameter Index
```

```
        " SoftLimit Break
        ML00066 = 2147483647;
        ML00068 = -2147483648;
        MSEE MPS115;

        " High Speed Search
        MB026002 = DB00008                                                   " Moving direction(JOG/STEP)
        ML02612 = ML40008[L1_PL]                                             " Speed reference setting

        MW02610 = 7;                                                         " Motion command <- STEP COMMAND
        IOW (MB027010 | MB027011 | MB027017 | MB027018 | MB027019 | MB02701A) ==   " ABS ORG Input or OT Sensor
        MW02610 = 0;                                                         " Motion command <- 0 Clear
        IOW MB027009 == 1                                                    " Motion command response code is

        TIM T100;

        " OT센서 감지시 원점센서 감지될때까지 반대로 이동
        IF (MB027011 | MB027018 | MB02701A) ==               " OT Sensor On Check
            " High Speed Search
            MB026002 = !DB00008                              " Moving direction(JOG/STEP)
            ML02612 = ML40008[L1_PL]                         " Speed reference setting
            ML02624 = 40000                                  " Step travel distance

            MW02610 = 8;                                     " Motion command <- STEP COMMAND
            IOW MB02700B == 1                                " Motion command response code not 0
            IOW MB027008 == 1                                " Motion command execution completed
            MW02610 = 0;                                     " Motion command <- 0 Clear
            IOW MB027009 == 1                                " Motion command response code is 0
        IEND;

        MB02600F = 1;                                        " ABS 실행중(Gantry)
        PFORK Line1 Line2 Line3;

        Line1:
            " High Speed Search
            MB026002 = DB00008                               " Moving direction(JOG/STEP)
            ML02612 = ML40008[L1_PL]                         " Speed reference setting

            MW02610 = 7;                                     " Motion command <- STEP COMMAND
            IOW MB027010 == 1                                " ABS ORG Input
            MW02610 = 0;                                     " Motion command <- 0 Clear
            IOW MB027009 == 1                                " Motion command response code is 0


            JOINTO LabelX1;
        Line2:
            " High Speed Search
            MB020002 = DB00008                               " Moving direction(JOG/STEP)
            ML02012 = ML40008[L1_PL]                         " Speed reference setting

            MW02010 = 7;                                     " Motion command <- STEP COMMAND
            IOW MB027017 == 1                                " ABS ORG Input
            MW02010 = 0;                                     " Motion command <- 0 Clear
            IOW MB021009 == 1                                " Motion command response code is 0


            JOINTO LabelX1;

        Line3:
            " High Speed Search
            MB022002 = DB00008                               " Moving direction(JOG/STEP)
            ML02212 = ML40008[L1_PL]                         " Speed reference setting

            MW02210 = 7;                                     " Motion command <- STEP COMMAND
            IOW MB027019 == 1                                " ABS ORG Input
            MW02210 = 0;                                     " Motion command <- 0 Clear
            IOW MB023009 == 1                                " Motion command response code is 0


            JOINTO LabelX1,

        LabelX1: PJOINT
        MB02600F = 0;                                        " ABS 실행중(Gantry)

        " Low Speed Search
        MB026002 = !DB00008                                  " Moving direction(JOG/STEP)
        ML02612 = ML40010[L1_PL]                             " Speed reference setting

        MW02610 = 7;                                         " Motion command <- STEP COMMAND
        IOW (MB027010 | MB027017 | MB027019) ==              " ABS ORG Input
```

```
        MW02610 = 0;                                    " Motion command <- 0 Clear
        IOW MB027009 == 1                               " Motion command response code is 0

        TIM T100;

        MB02600F = 1;                                   " ABS 실행중(Gantry)
        PFORK Line4 Line5 Line6;

        Line4:
            " Step Search
            MB026002 = DB00008                          " Moving direction(JOG/STEP)
            ML02612 = ML40010[L1_PL]                    " Speed reference setting
            ML02624 = 3;                                " Step travel distance

            DB00000E = 0;
            WHILE DB00000E == 0;
                IF MB027010 == 1                        " ABS ORG Input
                    DB00000E = 1;
                ELSE;
                    EOX;
                    MW02610 = 8;                        " Motion command <- STEP COMMAND
                    IOW MB02700B == 1                   " Motion command response code not 0
                    IOW MB027008 == 1                   " Motion command execution completed
                    MW02610 = 0;                        " Motion command <- 0 Clear
                    IOW MB027009 == 1                   " Motion command response code is 0
                IEND;
                EOX;
            WEND;

            JOINTO LabelX2;

        Line5:
            " Step Search
            MB020002 = DB00008                          " Moving direction(JOG/STEP)
            ML02012 = ML40010[L1_PL]                    " Speed reference setting
            ML02024 = 3;                                " Step travel distance

            DB00000D = 0;
            WHILE DB00000D == 0;
                IF MB027017 == 1                        " ABS ORG Input
                    DB00000D = 1;
                ELSE;
                    EOX;
                    MW02010 = 8;                        " Motion command <- STEP COMMAND
                    IOW MB02100B == 1                   " Motion command response code not 0
                    IOW MB021008 == 1                   " Motion command execution completed
                    MW02010 = 0;                        " Motion command <- 0 Clear
                    IOW MB021009 == 1                   " Motion command response code is 0
                IEND;
                EOX;
            WEND;

            JOINTO LabelX2;

        Line6:
            " Step Search
            MB022002 = DB00008                          " Moving direction(JOG/STEP)
            ML02212 = ML40010[L1_PL]                    " Speed reference setting
            ML02224 = 3;                                " Step travel distance

            DB00000A = 0;
            WHILE DB00000A == 0;
                IF MB027019 == 1                        " ABS ORG Input
                    DB00000A = 1;
                ELSE;
                    EOX;
                    MW02210 = 8;                        " Motion command <- STEP COMMAND
                    IOW MB02300B == 1                   " Motion command response code not 0
                    IOW MB023008 == 1                   " Motion command execution completed
                    MW02210 = 0;                        " Motion command <- 0 Clear
                    IOW MB023009 == 1                   " Motion command response code is 0
                IEND;
                EOX;
            WEND;

            JOINTO LabelX2;

        LabelX2: PJOINT;
        MB02600F = 0;                                   " ABS 실행중(Gantry)

        MSEE MPS114;                                    " Abs Origin Reset

        MB102400[Axis_IDX1] = 1                         " ABS Offset 0reset Ind
        IF MW00060 == 2                                 " 2 Axis Gentry
            MB102400[Axis_IDX2] = 1                     " ABS Offset 0reset Ind
        IEND;
```

```
        IF MW00060 == 3                                         " 3 Axis Gentry
            MB102400[Axis_IDX2] = 1                             " ABS Offset Oreset Ind
            MB102400[Axis_IDX3] = 1                             " ABS Offset Oreset In
        IEND;

        " SoftLimit Update
        ML00066 = ML40094[L1_PL];
        ML00068 = ML40098[L1_PL];
        MSEE MPS115;

    JOINTO LabelX;

    Label3:
        " PERR Search (1 Direction)

        MW00060 = 1;
        L1_PW = (MW02782-1) * 100                               " Parameter Index
        L1_PL = (MW02782-1) * 100 / 2                           " Parameter Index

        " SoftLimit Break
        ML00066 = 2147483647;
        ML00068 = -2147483648;
        MSEE MPS115;

        IF MB000181 == 1; "SCT Use
            OLA114 = 11000;                                     " CZ
        IEND;

        IF MB000182 | MB000183 == 1; "CCT USE
            OLA114 = 11000;                                     " LCZ
            OLB114 = 11000;                                     " RCZ
        IEND;

        " Position reference setting
        ML02612 = ML40010[L1_PL]                                " Speed reference setting
        ML02614 = ML02712 - 1000000;

        MB026005 = 1;                                           " Position refarance type <- Absplut
e Value
        MW02610 = 1;                                            " Motion command <- STEP COMMAND
        IOW MB027012 == 1                                       " PERR 200um OVER
        ML02614 = ML02712;                                      " Calibration PERR
        IOW MB027007 == 1                                       " Motion command execution completed
        MB026005 = 0;                                           " Position refarance type <- Increme
ntal Value
        MW02610 = 0;                                            " Motion command <- 0 Clear
        IOW MB027009 == 1                                       " Motion command response code is 0

        MSEE MPS114;                                            " Abs Origin Reset

        " SoftLimit Update
        ML00066 = ML40094[L1_PL];
        ML00068 = ML40098[L1_PL];
        MSEE MPS115;

        TIM T100;

        MB026002 = !DB00008                                     " Moving direction(JOG/STEP)
        ML02612 = ML40012[L1_PL]                                " Speed reference setting
        ML02624 = ML40030[L1_PL]                                " Step travel distance

        MW02610 = 8;                                            " Motion command <- STEP COMMAND
        IOW MB02700B == 1                                       " Motion command response code not 0
        IOW MB027008 == 1                                       " Motion command execution completed
        MW02610 = 0;                                            " Motion command <- 0 Clear
        IOW MB027009 == 1                                       " Motion command response code is 0

        JOINTO LabelX;

    Label4:
        " PERR Search (2 Direction)

        MW00060 = 1;
        L1_PW = (MW02782-1) * 100                               " Parameter Index
        L1_PL = (MW02782-1) * 100 / 2                           " Parameter Index

        " SoftLimit Break
        ML00066 = 2147483647;
        ML00068 = -2147483648;
        MSEE MPS115;

        " Position reference setting
        ML02612  = ML40010[L1_PL]                               " Speed reference setting
        ML02614  = ML02712 - 1000000

        MB026005 = 1;                                           " Position refarance type <- Absplut
e Value
```

```
00284         MW02610 = 1;                               " Motion command <- STEP COMMAND
00285         IOW MB027012 == 1                          " PERR 200um OVER
00286         ML02614  = ML02712;                        " Calibration PERR
00287         IOW MB027007 == 1                          " Motion command execution completed
00288         MB026005 = 0;                              " Position refarence type <- Incremental Value
00289         MW02610 = 0;                               " Motion command <- 0 Clear
00290         IOW MB027009 == 1                          " Motion command response code is 0
00291         DL00020 = ML02712                          " Save - Direction Limit Pos

              " Position reference settir
00292         ML02612  = ML40010[L1_PL]                  " Speed reference setting
00293         ML02614  = ML02712 + 1000000;

00294         MB026005 = 1;                              " Position refarence type <- Absplute Value
00295         MW02610 = 1;                               " Motion command <- STEP COMMAND
00296         IOW MB027012 == 1                          " PERR 200um OVER
00297         ML02614  = ML02712;                        " Calibration PERR
00298         IOW MB027007 == 1                          " Motion command execution completed
00299         MB026005 = 0;                              " Position refarence type <- Incremental Value
00300         MW02610 = 0;                               " Motion command <- 0 Clear
00301         IOW MB027009 == 1                          " Motion command response code is 0
00302         DL00022 = ML02712                          " Save + Direction Limit Pos

              " Move Center
00303         ML02614  = (DL00020 + DL00022)/2;
00304         MB026005 = 1;                              " Position refarence type <- Absplute Value
00305         MW02610 = 1;                               " Motion command <- STEP COMMAND
00306         IOW MB027007 == 0                          " Motion command execution completed
00307         IOW MB027007 == 1                          " Motion command execution completed
00308         MB026005 = 0;                              " Position refarence type <- Incremental Value
00309         MW02610 = 0;                               " Motion command <- 0 Clear
00310         IOW MB027009 == 1                          " Motion command response code is 0

00311         MSEE MPS114;                               " Abs Origin Reset

              " SoftLimit Update
00312         ML00066 = ML40094[L1_PL];
00313         ML00068 = ML40098[L1_PL];
00314         MSEE MPS115;

00315         JOINTO LabelX;

00316     Label5:
              " Torque Search (1 Direction)

00317         MW00060 = 1;
00318         L1_PW = (MW02782-1) * 100                  " Parameter Index
00319         L1_PL = (MW02782-1) * 100 / 2              " Parameter Index

              " SoftLimit Break
00320         ML00066 = 2147483647;
00321         ML00068 = -2147483648;
00322         MSEE MPS115;

              " Position reference setting
00323         ML02612  = ML40010[L1_PL]                  " Speed reference setting
00324         ML02614  = ML02712 - 1000000;

00325         MB026005 = 1;                              " Position refarence type <- Absplute Value
00326         MW02610 = 1;                               " Motion command <- STEP COMMAND
00327         IOW MB027013 == 1                          " Torque Over
00328         ML02614  = ML02712;                        " Calibration PERR
00329         IOW MB027007 == 1                          " Motion command execution completed
00330         MB026005 = 0;                              " Position refarence type <- Incremental Value
00331         MW02610 = 0;                               " Motion command <- 0 Clear
00332         IOW MB027009 == 1                          " Motion command response code is 0
00333         DL00020 = ML02712                          " Save - Direction Limit Pos

00334         MSEE MPS114;                               " Abs Origin Reset

              " SoftLimit Update
00335         ML00066 = ML40094[L1_PL];
00336         ML00068 = ML40098[L1_PL];
00337         MSEE MPS115;

00338         TIM T100;

00339         MB026002 = !DB00008                        " Moving direction(JOG/STEP)
00340         ML02612 = ML40012[L1_PL]                   " Speed reference setting
00341         ML02624 = ML40030[L1_PL]                   " Step travel distance
```

```
        MW02610 = 8;                                    " Motion command <- STEP COMMAND
        IOW MB02700B == 1                               " Motion command response code not 0
        IOW MB027008 == 1                               " Motion command execution completed
        MW02610 = 0;                                    " Motion command <- 0 Clear
        IOW MB027009 == 1                               " Motion command response code is 0

    JOINTO LabelX;

    Label6:
        " Torque Search (2 Direction)

        MW00060 = 1;
        L1_PW = (MW02782-1) * 100                       " Parameter Index
        L1_PL = (MW02782-1) * 100 / 2                   " Parameter Index

        " SoftLimit Break
        ML00066 = 2147483647;
        ML00068 = -2147483648;
        MSEE MPS115;

        " Position reference setting
        ML02612 = ML40010[L1_PL]                        " Speed reference setting
        ML02614 = ML02712 - 1000000;

        MB026005 = 1;                                   " Position refarance type <- Absplute Value
        MW02610 = 1;                                    " Motion command <- STEP COMMAND
        IOW MB027013 == 1                               " Torque Over
        ML02614 = ML02712 + 30,                         " Calibration PERR
        IOW MB027007 == 1                               " Motion command execution completed
        MB026005 = 0;                                   " Position refarance type <- Incremental Value
        MW02610 = 0;                                    " Motion command <- 0 Clear
        IOW MB027009 == 1                               " Motion command response code is 0

        DL00020 = ML02712                               " Save - Direction Limit Pos

        " Position reference setting
        ML02612 = ML40010[L1_PL]                        " Speed reference setting
        ML02614 = ML02712 + 1000000;

        MB026005 = 1;                                   " Position refarance type <- Absplute Value
        MW02610 = 1;                                    " Motion command <- STEP COMMAND
        IOW MB027013 == 1                               " Torque Over
        ML02614 = ML02712 - ML02714                     " Calibration PERR
        IOW MB027007 == 1                               " Motion command execution completed
        MB026005 = 0;                                   " Position refarance type <- Incremental Value
        MW02610 = 0;                                    " Motion command <- 0 Clear
        IOW MB027009 == 1                               " Motion command response code is 0

        DL00022 = ML02712                               " Save + Direction Limit P

        " Move Center
        ML02614 = (DL00020 + DL00022)/2;
        MB026005 = 1;                                   " Position refarance type <- Absplute Value
        MW02610 = 1;                                    " Motion command <- STEP COMMAND
        IOW MB027007 == 0                               " Motion command execution completed
        IOW MB027007 == 1                               " Motion command execution completed
        MB026005 = 0;                                   " Position refarance type <- Incremental Value
        MW02610 = 0;                                    " Motion command <- 0 Clear
        IOW MB027009 == 1                               " Motion command response code is 0

        MSEE MPS114;                                    " Abs Origin Reset

        " SoftLimit Update
        ML00066 = ML40094[L1_PL];
        ML00068 = ML40098[L1_PL];
        MSEE MPS115;

        JOINTO LabelX;

    Label7:
        " Torque Search (Shift Axis>

        L1_PW = (MW02782-1) * 100                       " Parameter Index
        L1_PL = (MW02782-1) * 100 / 2                   " Parameter Index

        " SoftLimit Break
        ML00066 = 2147483647;
        ML00068 = -2147483648;
        MSEE MPS115;
```

```
        " Position reference setting
        ML02612 = ML40010[L1_PL]                                " Speed reference setting
        ML02614 = ML02712 - 50000;
        MB026005 = 1;                                           " Position refarence type <- Absplute Value

        MW02610 = 1;                                            " Motion command <- STEP COMMAND
        IOW MB027013 == 1                                       " Torque Over

        ML02614  = ML02712;                                     " Calibration PERR
        IOW MB027007 == 1                                       " Motion command execution completed

        MW02610 = 0;                                            " Motion command <- 0 Clear
        MB026005 = 0;                                           " Position refarence type <- Incremental Value
        IOW MB027009 == 1                                       " Motion command response code is 0

        TIM T100;

        " 쉬프트축 현재위치 0으로 만들기 위해 [기존ABS OFFSET 저장량 - 현재위치](ML53920번지는 현재위치 모니터 영역)
        " 값을 저장해놓고 0 좌표리셋을 해야 현재좌표가 0으로 바뀜.
        DL00080 = ML31000[Axis_IDX1] - ML53920[Axis_IDX1];

        MSEE MPS114;                                            " Abs Origin Reset
        MB102200[Axis_IDX1] = 1                                 " ABS Search Complete

        " 저장해뒀던 값을 [기존ABS OFFSET 저장량]에 입력. 현재좌표 0으로 변경
        ML31000[Axis_IDX1] = DL00080;

        TIM T30;

        MB026002 = !DB00008                                     " Moving direction(JOG/STEP)
        ML02612 = ML40012[L1_PL]                                " Speed reference setting

        IF MB000181 == 1; "SCT Us
            IF MW00061 == 36                                    " CS
                ML02624 = ML26374 - ML26376                     " 스텝량(쉬프트 중심위치 + 쉬프트 원점OFFSET)
            IEND;
        IEND;

        IF MB000182 | MB00183 == 1; "CCT U
            IF MW00061 == 36                                    " LCS
                ML02624 = ML26374 - ML26376                     " 스텝량(쉬프트 중심위치 + 쉬프트 원점OFFSET)
            IEND;
            IF MW00061 == 68                                    " RCS
                ML02624 = ML26974 - ML26976                     " 스텝량(쉬프트 중심위치 + 쉬프트 원점OFFSET)
            IEND;
        IEND;
        MW02610 = 8;                                            " Motion command <- STEP COMMAND
        IOW MB02700B == 1                                       " Motion command response code not 0
        IOW MB027008 == 1                                       " Motion command execution completed
        MW02610 = 0;                                            " Motion command <- 0 Clear
        IOW MB027009 == 1                                       " Motion command response code is 0

        TIM T50;

        " 다시 현재좌표 리셋
        DL00080 = ML31000[Axis_IDX1] - ML53920[Axis_IDX1];

        MSEE MPS114;                                            " Abs Origin Reset
        MB102200[Axis_IDX1] = 1                                 " ABS Search Complet

        ML31000[Axis_IDX1] = DL00080;

        " SoftLimit Update
        ML00066 = ML40094[L1_PL];
        ML00068 = ML40098[L1_PL];
        MSEE MPS115;

        JOINTO LabelX;

    Label8:
        " Torque Search (IAI
        PFORK Line7 Line8;

        Line7:

            Axis_IO_Chuck1 = (Axis_IDX1 - 96) * 12
            Axis_IO_B_Chuck1 = Axis_IO_Chuck1 * 1 ;

            OBC0061[Axis_IO_B_Chuck1] = (
            EOX;
```

```
                OBC0061[Axis_IO_B_Chuck1] = 1
                EOX;
                IOW IBC0299[Axis_IO_B_Chuck1] == 1
                EOX;

                TIM T300;

                OBC0061[Axis_IO_B_Chuck1] = 0;

                JOINTO LabelX3;

            Line8:

                IF MW00060 == 2;
                    Axis_IO_Chuck2 = (Axis_IDX2 - 96) * 12
                    Axis_IO_B_Chuck2 = Axis_IO_Chuck2 * 1 ;

                    OBC0061[Axis_IO_B_Chuck2] = 0
                    EOX;

                    OBC0061[Axis_IO_B_Chuck2] = 1
                    EOX;
                    IOW IBC0299[Axis_IO_B_Chuck2] == 1
                    EOX;

                    TIM T300;

                    OBC0061[Axis_IO_B_Chuck2] = 0;
                IEND;

                JOINTO LabelX3;
            LabelX3: PJOINT;

            TIM T300;

            MSEE MPS114;                                            " ABS Origin Reset

            JOINTO LabelX;

        LabelD:
            JOINTO LabelX;
        LabelX: SJOINT;

        MB102200[Axis_IDX1] = 1                                     " ABS Search Complet
        IF MW00060 == 2                                             " Type : 2 Axis Gentry ABS Search
            MB102200[Axis_IDX2] = 1                                 " ABS Search Complete
        IEND;
        IF MW00060 == 3                                             " Type : 3 Axis Gentry ABS Search
            MB102200[Axis_IDX2] = 1                                 " ABS Search Complet
            MB102200[Axis_IDX3] = 1                                 " ABS Search Complete
        IEND;

    RET;
```