

H10.11: Unit1 Input Sensor

* DL Register Area - 120Word

* DW00000 - DW00009 (PLS Use)

* DW00010 - DW00039 (Bit Use)

* DW00040 - DW00089 (Word Use)

* DW00090 - DW00400 (Timer)

#####

Program Name : Sensor In_Unit 1

#

Function :

#

Call Program : H10

#

Sub Program :

#

Function Program :

#####

Sensor NoUse Setting : Sensor (A) = 0, Sensor (B) = 1

Sensor Input (ORG Sensor)

0

UNIT

EXPRESSON

'DB000100' = 0
DB000100 = 0; // Unit 1 Axis 01 ORG On (MB040900)
'DB000101' = 0
DB000101 = 0; // Unit 1 Axis 02 ORG On (MB040901)
'DB000102' = 0
DB000102 = 0; // Unit 1 Axis 03 ORG On (MB040902)
'DB000103' = 0
DB000103 = 0; // Unit 1 Axis 04 ORG On (MB040903)
'DB000104' = 0
DB000104 = 0; // Unit 1 Axis 05 ORG On (MB040904)
'DB000105' = 0
DB000105 = 0; // Unit 1 Axis 06 ORG On (MB040905)
'DB000106' = 0
DB000106 = 0; // Unit 1 Axis 07 ORG On (MB040906)
'DB000107' = 0
DB000107 = 0; // Unit 1 Axis 08 ORG On (MB040907)
'DB000108' = 0
DB000108 = 0; // Unit 1 Axis 09 ORG On (MB040908)
'DB000109' = 0
DB000109 = 0; // Unit 1 Axis 10 ORG On (MB040909)
'DB00010A' = 0
DB00010A = 0; // Unit 1 Axis 11 ORG On (MB04090A)
'DB00010B' = 0
DB00010B = 0; // Unit 1 Axis 12 ORG On (MB04090B)
'DB00010C' = 0
DB00010C = 0; // Unit 1 Axis 13 ORG On (MB04090C)
'DB00010D' = 0
DB00010D = 0; // Unit 1 Axis 14 ORG On (MB04090D)
'DB00010E' = 0
DB00010E = 0; // Unit 1 Axis 15 ORG On (MB04090E)
'DB00010F' = 0
DB00010F = 0; // Unit 1 Axis 16 ORG On (MB04090F)

1

1/48

EXPRESSON

'DB000110' = 0
DB000110 = 0; // Unit 1 Axis 17 ORG On (MB040910)
'DB000111' = 0
DB000111 = 0; // Unit 1 Axis 18 ORG On (MB040911)
'DB000112' = 0
DB000112 = 0; // Unit 1 Axis 19 ORG On (MB040912)
'DB000113' = 0
DB000113 = 0; // Unit 1 Axis 20 ORG On (MB040913)
'DB000114' = 0
DB000114 = 0; // Unit 1 Axis 21 ORG On (MB040914)
'DB000115' = 0
DB000115 = 0; // Unit 1 Axis 22 ORG On (MB040915)
'DB000116' = 0
DB000116 = 0; // Unit 1 Axis 23 ORG On (MB040916)
'DB000117' = 0
DB000117 = 0; // Unit 1 Axis 24 ORG On (MB040917)
'DB000118' = 0
DB000118 = 0; // Unit 1 Axis 25 ORG On (MB040918)
'DB000119' = 0
DB000119 = 0; // Unit 1 Axis 26 ORG On (MB040919)
'DB00011A' = 0
DB00011A = 0; // Unit 1 Axis 27 ORG On (MB04091A)
'DB00011B' = 0
DB00011B = 0; // Unit 1 Axis 28 ORG On (MB04091B)
'DB00011C' = 0
DB00011C = 0; // Unit 1 Axis 29 ORG On (MB04091C)
'DB00011D' = 0
DB00011D = 0; // Unit 1 Axis 30 ORG On (MB04091D)
'DB00011E' = 0
DB00011E = 0; // Unit 1 Axis 31 ORG On (MB04091E)
'DB00011F' = 0
DB00011F = 0; // Unit 1 Axis 32 ORG On (MB04091F)

2

2/48

FOR

[W]Var
DW00040

[W]Init
00000

[W]Max
00031

[W]Step
00001

3

3/100

EXPRESSON

'I' = 'DW00040'
I = DW00040;

4

4/102

DB000100i

NL

2

TON[10ms]

[W]Set
00000

[W]Count
DW00090i

MB040900i

Unit1 Axis 1
Home (Sens
or)

5

7/106


END_FOR

H10.11 : Sensor In_Unit1 (SP)

P00001

Sensor Input (+OT Sensor)									
6	8/107								
EXPRESSION 'DB000120' = 0 DB000120 = 0; // Unit 1 Axis 01 +OT On (MB040920) 'DB000121' = 0 DB000121 = 0; // Unit 1 Axis 02 +OT On (MB040921) 'DB000122' = 0 DB000122 = 0; // Unit 1 Axis 03 +OT On (MB040922) 'DB000123' = 0 DB000123 = 0; // Unit 1 Axis 04 +OT On (MB040923) 'DB000124' = 0 DB000124 = 0; // Unit 1 Axis 05 +OT On (MB040924) 'DB000125' = 0 DB000125 = 0; // Unit 1 Axis 06 +OT On (MB040925) 'DB000126' = 0 DB000126 = 0; // Unit 1 Axis 07 +OT On (MB040926) 'DB000127' = 0 DB000127 = 0; // Unit 1 Axis 08 +OT On (MB040927) 'DB000128' = 0 DB000128 = 0; // Unit 1 Axis 09 +OT On (MB040928) 'DB000129' = 0 DB000129 = 0; // Unit 1 Axis 10 +OT On (MB040929) 'DB00012A' = 0 DB00012A = 0; // Unit 1 Axis 11 +OT On (MB04092A) 'DB00012B' = 0 DB00012B = 0; // Unit 1 Axis 12 +OT On (MB04092B) 'DB00012C' = 0 DB00012C = 0; // Unit 1 Axis 13 +OT On (MB04092C) 'DB00012D' = 0 DB00012D = 0; // Unit 1 Axis 14 +OT On (MB04092D) 'DB00012E' = 0 DB00012E = 0; // Unit 1 Axis 15 +OT On (MB04092E) 'DB00012F' = 0 DB00012F = 0; // Unit 1 Axis 16 +OT On (MB04092F)									
7	9/133								
EXPRESSION 'DB000130' = 0 DB000130 = 0; // Unit 1 Axis 17 +OT On (MB040930) 'DB000131' = 0 DB000131 = 0; // Unit 1 Axis 18 +OT On (MB040931) 'DB000132' = 0 DB000132 = 0; // Unit 1 Axis 19 +OT On (MB040932) 'DB000133' = 0 DB000133 = 0; // Unit 1 Axis 20 +OT On (MB040933) 'DB000134' = 0 DB000134 = 0; // Unit 1 Axis 21 +OT On (MB040934) 'DB000135' = 0 DB000135 = 0; // Unit 1 Axis 22 +OT On (MB040935) 'DB000136' = 0 DB000136 = 0; // Unit 1 Axis 23 +OT On (MB040936) 'DB000137' = 0 DB000137 = 0; // Unit 1 Axis 24 +OT On (MB040937) 'DB000138' = 0 DB000138 = 0; // Unit 1 Axis 25 +OT On (MB040938) 'DB000139' = 0 DB000139 = 0; // Unit 1 Axis 26 +OT On (MB040939) 'DB00013A' = 0 DB00013A = 0; // Unit 1 Axis 27 +OT On (MB04093A) 'DB00013B' = 0 DB00013B = 0; // Unit 1 Axis 28 +OT On (MB04093B) 'DB00013C' = 0 DB00013C = 0; // Unit 1 Axis 29 +OT On (MB04093C) 'DB00013D' = 0 DB00013D = 0; // Unit 1 Axis 30 +OT On (MB04093D) 'DB00013E' = 0 DB00013E = 0; // Unit 1 Axis 31 +OT On (MB04093E) 'DB00013F' = 0 DB00013F = 0; // Unit 1 Axis 32 +OT On (MB04093F)									
8	10/203	FOR	[W]Var DW00040 ---	[W]Init 00000	[W]Max 00031	[W]Step 00001			
9	11/207	NL 2							
EXPRESSION 'I' = 'DW00040' I = DW00040;									
10	12/239	NL 2	DB000120i ---						MB040920i Unit1 Axis 1 OT+ (Sensor)
11	14/211	NL 2	MB040920i Unit1 Axis 1 OT+ (Sensor) MB040410i Lv2 Unit1 Ax is01 OT+ Ala rm	MB000001 Stopping	TON[10ms]	[W]Set CW00103 ---	[W]Count DW00122i ---	MB00005C Running AB S Search	[MB040920] .../0211i [MB040410] .../0215i
MB000059 Jog Driving MB027841 Jog MB00006F Pls:Reset MB000001 Stopping MB040410i Lv2 Unit1 Ax is01 OT+ Ala rm									
12	20/223		END_FOR						

L90.21/1117



[MB040940]
.../0328i

[MB040430]
.../0332i

L90.21/0887