

H30:Work information									
0						SEE	Name H30.10 Tracking Data		
1						SEE	Name H30.11 Glass Data UI Display		
2						SEE	Name H30.12 Work Status Data		
3						SEE	Name H30.15 Panel Existence Alarm		
4						SEE	Name H30.20 Work Management		
5						SEE	Name H30.21 Work Data Delete		
6						SEE	Name H30.22 Work Data Force Set		
7						SEE	Name H30.23 Glass Tracking Data Move		
8						SEE	Name H30.24 ScribeLineSelect		
9						SEE	Name H30.50 Reset Bit Management		
10					END				