










[MB045137]
.../0674w
[MB045139]
.../0298
[MB04513A]
.../0299
H99.02/1451
L80.22/0738

.../0680w
H70.22/0283w
H99.02/1468


H99.02/1450
H70.22/0307w
L20.40/0184







26	222/397	MB030039	DB000073	MB000181						MB070850	[MB070850] H50.17/0162w L10.57/0009i L20.47/0261	H50.47/0813 L10.67/0158i	L10.57/0008iw L10.67/0199i
				SCT Use						Reverse Top Vacuum Are a 1 Off	[MB070851] H50.17/0163w [MB070852] H50.17/0164w [MB070853] H50.17/0165w	H50.47/0824	L20.47/0269
										MB070851		H50.47/0835	L20.47/0277
										Reverse Top Vacuum Are a 2 Off		H50.47/0846	L20.47/0285
										MB070852			
										Reverse Top Vacuum Are a 3 Off			
										MB070853			
										Reverse Top Vacuum Are a 4 Off			
27	223/404	MB000001	DB000014										
		Stopping	Pls										
		MB000002	DB000015										
		All Servo On	Pls										
										EXPRESSION			
										'[MCTAG]Load Calib. Executeing' = 0 MB210149 = 0;			
										EXPRESSION			
										'MB21014B' = 0 MB21014B = 0;			
28	235/422	MB000001	DB000016										
		Stopping	Pls										
										EXPRESSION			
										'CZ Pressure Check' = 0 MB15420B = 0;			
										EXPRESSION			
										'MB17420B' = 0 MB17420B = 0;			
29	241/435	MB000001	DB000017										
		Stopping	Pls										
										EXPRESSION			
										'Break Motion Code' = 0 MW04844 = 0;			
										EXPRESSION			
										'MW05344' = 0 MW05344 = 0;			
30	248/452	MB030036	DB000018										
		P Work : Break Table [SCT]	Pls										
		MB030035	MB030036	DB00002C									
		P Work : Scribe Chuck Y [SCT]	P Work : Break Table [SCT]	Pls									
										EXPRESSION			
										'Table Carry Out Standby Comp' = 0 MB045724 = 0;			
31	252/462	MB030039	DB000078	MB000181									
				SCT Use									
		MB030038	MB030039	DB00008C									
										EXPRESSION			
										'MB050724' = 0 MB050724 = 0;			
32	259/476	MB045709	==	[WLFQD]SrcA MW04518 SC → Scribe Chuck Command Code	[WLFQD]SrcB 00000	DB000019	STORE	[WLFQD]Src 00010	[WLFQD]Dest MW04518 SC → Scribe Chuck Command Code	[MW04518] .../0473	.../0523w		
		All Stop Request Reset				Pls							
33	263/486	MB045709	==	[WLFQD]SrcA MW04514	[WLFQD]SrcB 00000	DB00001A	STORE	[WLFQD]Src 00012	[WLFQD]Dest MW04514	[MW04514] .../0483 H99.02/1070 H99.02/1099 H99.02/1166 H99.02/1280 H99.02/1316	H99.02/1070 H99.02/1137 H99.02/1181 H99.02/1296 H99.02/1319	H99.02/1084 H99.02/1151 H99.02/1277 H99.02/1299	
		All Stop Request Reset				Pls							
H30.50 : Reset Bit Management										P00006			



.../0666

.../0686

