

L40:Axis Control										
0						SEE	Name L40.01 Gantry AxisParameter Copy			
1						SEE	Name L40.40 Jog/Step Enable			
2						SEE	Name L40.41 ABS Enable			
3						SEE	Name L40.60 Multi-turn limit processing			
4	END									