

	L60.23:Step Btn Enable(6 Circuit)								
0	0/0	MB00000F Debug					DB000000 ---	[DB000000] .../0012 .../0018 .../0024 .../0030 .../0057 .../0093 .../0099 .../0105 .../0132	.../0014 .../0020 .../0026 .../0032 .../0089 .../0095 .../0101 .../0107
1	2/2			SETW	[W]Dest MW90404 ---	[W]Data HFFFF	[W]Width 00016	[MW90404] .../0139w	L40.40/0221i
2	3/3			SETW	[W]Dest MW90532 ---	[W]Data HFFFF	[W]Width 00016	[MW90532] .../0142w	L40.40/0296i
		Step(-) Enable 조건 49 Axis (SCHY1) DL00010 ~ DL00018							
3	4/6	MB071003 MTR Y Carry Out Pos MB071003 MTR Y Carry Out Pos	MB071020 MTR Z Standby Pos				MB904040 ---		
		50 Axis (SCHY2) DL00020 ~ DL00028							
4	8/12	DB000000 ---					MB904050 ---		
		51 Axis (SP) DL00030 ~ DL00038							
5	10/14	DB000000 ---					MB904060 ---		
		52 Axis (SCH1Z) DL00040 ~ DL00048							
6	12/16	DB000000 ---					MB904070 ---		
		53 Axis (SCH2Z) DL00050 ~ DL00058							
7	14/18	DB000000 ---					MB904080 ---		
		54 Axis (SCH3Z) DL00060 ~ DL00068							
8	16/20	DB000000 ---					MB904090 ---		
		55 Axis (SCH4Z) DL00070 ~ DL00078							
9	18/22	DB000000 ---					MB904100 ---		
		56 Axis (SCH5Z) DL00080 ~ DL00088							
10	20/24	DB000000 ---					MB904110 ---		
		57 Axis (SCH6Z) DL00090 ~ DL00098							
11	22/26	DB000000 ---					MB904120 ---		
		58 Axis (SCH7Z) DL000100 ~ DL000108							
12	24/28	DB000000 ---					MB904130 ---		
		59 Axis (SCH8Z) DL000110 ~ DL000118							
13	26/30	DB000000 ---					MB904140 ---		
		60 Axis (SP) DL000120 ~ DL000128							
14	28/32	DB000000 ---					MB904150 ---		
		61 Axis (SP) DL000130 ~ DL000138							
15	30/34	DB000000 ---					MB904160 ---		
				L60.23 : Step Btn Enable(6 Circuit) - SC,MTR,SBT					P00001





