

	L60.36:ABS Btn Enable (9 Circuit)						
0	MB00000F						DB000000
	Debug						---
1				SETW	[W]Dest MW90708 ---	[W]Data HFFFF	[W]Width 00016
	ABS Enable 조건 97 Axis (SP) DL00010 ~ DL00018						
2	DB000000						MB907080
	---						---
	98 Axis (SP) DL00020 ~ DL00028						
3	DB000000						MB907090
	---						---
	99 Axis (SP) DL00030 ~ DL00038						
4	DB000000						MB907100
	---						---
	100 Axis (SP) DL00040 ~ DL00048						
5	DB000000						MB907110
	---						---
	101 Axis (SP) DL00050 ~ DL00058						
6	DB000000						MB907120
	---						---
	102 Axis (SP) DL00060 ~ DL00068						
7	DB000000						MB907130
	---						---
	103 Axis (SP) DL00070 ~ DL00078						
8	DB000000						MB907140
	---						---
	104 Axis (SP) DL00080 ~ DL00088						
9	DB000000						MB907150
	---						---
	105 Axis (SP) DL00090 ~ DL00098						
10	DB000000						MB907160
	---						---
	106 Axis (SP) DL00100 ~ DL00108						
11	DB000000						MB907170
	---						---
	107 Axis (SP) DL00110 ~ DL00118						
12	DB000000						MB907180
	---						---
	108 Axis (SP) DL00120 ~ DL00128						
13	DB000000						MB907190
	---						---
	109 Axis (SP) DL00130 ~ DL00138						
14	DB000000						MB907200
	---						---
	110 Axis (SP) DL00140 ~ DL00148						
15	DB000000						MB907210
	---						---
	111 Axis (SP) DL00150 ~ DL00158						
16	DB000000						MB907220
	---						---

[DB000000]
.../0005
.../0011
.../0017
.../0023
.../0029
.../0035
[MW90708]
.../0042w

.../0007
.../0013
.../0019
.../0025
.../0031

.../0009
.../0015
.../0021
.../0027
.../0033

L40.41/0052i

