

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : SC Home
00011 "# Function :
00012 "# Call Program : H70.1
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 " Scribe Cutter
00018 00000 LONG IDX_CX = 32;
00019 00001 LONG IDX_CAMX = 33;
00020 " Scribe Shift
00021 00002 LONG IDX_CS = 35;
00022 " Scribe Chuck
00023 00003 LONG IDX_SCHY1 = 48;
00024 00004 LONG IDX_SCHY2 = 49;
00025 " Scribe Camera
00026 00005 LONG IDX_LCAMY = 37;
00027 00006 LONG IDX_LCAMZ = 38
00028 00007 LONG IDX_RCAMY = 39
00029 00008 LONG IDX_RCAMZ = 40;
00030 END_VAR;
00031
00032 " Code Reset
00033 " Chuck Code Reset
00034 00009 MW04518 = 0;
00035 " Cutter X Code Reset
00036 00010 MW04514 = 0;
00037 " All Stop Request Reset
00038 00011 MB045709 = 0;
00039 " Scribe Recipe Data Updata Waiting
00040 00012 MB045241 = 0;
00041 " Scribe Unit Home Complete
00042 00013 MB045240 = 0;
00043
00044 " Recipe Data Reading
00045 00014 MB214602 = 1;
00046 00015 IOW MB205202 == 1
00047 00016 MB214604 = 1;
00048 00017 IOW MB205204 == 1
00049 00018 MB21462B = 1;
00050 00019 ) IOW MB20522B == 1
00051 00020 EOX;
00052
00053 " Get Parts No.
00054 00021 MSEE MPS160;
00055 " Scribe Data Calc
00056 00022 MSEE MPS163;
00057 " Break Pusher Bar Data Calc
00058 00023 MSEE MPS168;
00059 " Break Table Data Calc
00060 00024 MSEE MPS169;
00061 " Axis Current Position Update
00062 00025 MSEE MPS150;
00063
00064 " Scribe Recipe Data UpData Waiting
00065 00026 MB045241 = 1;
00066
00067 " [Request] Break Table All Vacuum Break Off
00068 00027 MB05587F = 1;
00069 00028 IOW MB05687F == 1;
00070
00071 " Scribe Cutter Z
00072 " Cutter Z Waiting Position
00073 00029 IF MB045740 == 0
00074 00030 MW04842 = 41;
00075 00031 MSEE MPS198;
00076 00032 MW04842 = 0;
00077 00033 IOW MW04842 == 0;
00078 " Cutter Z Waiting Position Check
00079 00034 IOW MB045740 == 1;
00080 00035 IEND;
00081
00082 " Fix Table Brush Up Status
00083 00036 IF MB090140 | MB090141 == 0;
00084 " Fix Table Brush Brush Up Status
00085 00037 MB090400 = 0;
00086 00038 MB090401 = 0;

```

```

00087 00039      TIM T100;
00088 00040      MB090440 = 1;
00089 00041      MB090441 = 1;
00090 00042      IOW MB090140 & MB090141 == 1;
00091 00043      IEND;
00092
00093      // " Cutting Table Brush Up Status
00094      // IF MB090142 | MB090143 == 0;
00095      // " Cutting Table Brush Brush Up Status
00096      // MB090402 = 0;
00097      // MB090403 = 0;
00098      // TIM T100;
00099      // MB090442 = 1;
00100      // MB090443 = 1;
00101      // IOW MB090142 & MB090143 == 1;
00102      // IEND;
00103
00104      " Cutting Table Brush Up Status
00105 00044      IF !MB09014E == 1;
00106      " Cutting Table Brush Brush Up Status
00107 00045      MB09040E = 0;
00108 00046      MB09044E = 1;
00109 00047      IOW MB09014E == 1;
00110 00048      IEND;
00111
00112      " PTP
00113 00049      PFORK Line01 Line02 Line03;
00114
00115      Line01:
00116      " Cutter X, Cutter Shift Y Waiting Position
00117 00050      IF !MB045741 | !MB46030 == 1;
00118 00051      IOW MW04514 == 0;
00119 00052      IF MB045745 == 1
00120 00053          MW04514 = 11;
00121 00054      ELSE;
00122 00055          MW04514 = 1;
00123 00056      IEND;
00124 00057      MB045150 = 1;
00125 00058      IOW MB045151 == 1
00126 00059      MB045150 = 0;
00127 00060      IOW MB045151 == 0
00128 00061      IEND;
00129
00130      " Cutter X, Cutter Shift Y Waiting Position Check
00131 00062      IOW MB045741 == 1;
00132 00063      JOINTO Label0X;
00133
00134      Line02:
00135 00064      IF MB030034 == 1
00136          " [Request] Vacuum Position
00137 00065      MW04820 = 41;
00138 00066      MSEE MPS256;
00139 00067      IOW MB04574B == 1
00140          " All SCHZ Vacuum Pos Check
00141 00068      IOW MB49440 == 0;
00142 00069      MB49440 = 1;
00143 00070      MW04846 = 10;
00144 00071      MW04848 = 10;
00145 00072      MW04946 = 1;
00146 00073      MW04948 = 2;
00147 00074      MSEE MPS259;
00148 00075      MB49440 = 0;
00149 00076      ELSE;
00150 00077      IF MB071023 & MB030032 == 1;
00151 00078      IOW MB49440 == 0;
00152 00079      MB49440 = 1;
00153 00080      MW04846 = 10;
00154 00081      MW04848 = 10;
00155 00082      MW04946 = 2;
00156 00083      MW04948 = 1;
00157 00084      MSEE MPS259;
00158 00085      MB49440 = 0;
00159 00086      IEND;
00160 00087      IEND;
00161
00162      " Scribe Chuck Y
00163 00088      IF MB030035 == 1;
00164 00089      IF MB09018E | MB000800 == 1
00165          " [Request] Moving Position
00166 00090      MW04820 = 40;
00167 00091      MSEE MPS256;
00168 00092      IOW MB04574C == 1
00169 00093      ELSE;
00170          " [Request] Vacuum Position
00171 00094      MW04820 = 41;
00172 00095      MSEE MPS256;
00173 00096      IOW MB04574B == 1

```

```

00174
00175 00097          MB09048E = 1;          " [Sol] SCT Scribe Chuck All Vacuum On
00176 00098          IOW MB09018E == 1      " [Sensor] SCT Scribe Chuck All Vacuum On
00177
00178          " [Request] Moving Position
00179 00099          MW04820 = 40;
00180 00100          MSEE MPS256;
00181 00101          IOW MB04574C == 1      " All SCHZ Moving Pos Check
00182 00102          IEND;
00183 00103      ELSE;
00184
00185 00104          MB09052E = 1;          " [Sol] SCT Scribe Chuck All Vacuum Off
00186 00105          MB090560 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blow On
00187 00106          IOW MB09022E & MB090260 == 1      " [Sensor] SCT Scribe Chuck All Vacuum Off
00188          " [Sensor] SCT Scribe Chuck 1,2,3,4 Blow On
00189 00107          TIM TMW26214;          " Scribe Chuck Vacuum Break Complete Timer
00190 00108          MB090600 = 1;          " [Sol] SCT Scribe Chuck 1,2,3,4 Blow Off
00191 00109          MB090560 = 0;
00192 00110          IOW MB090300 == 1      " [Sensor] SCT Scribe Chuck 1,2,3,4 Blow Off
00193
00194
00195          " [Request] Standby Position
00196 00111          MW04820 = 39;
00197 00112          MSEE MPS256;
00198 00113          IOW MB04574A == 1      " All SCHZ Standby Pos Check
00199 00114          IEND;
00200
00201 00115          IF CB000099 == 1;
00202 00116              IOW MB045741 == 1;
00203 00117          IEND;
00204
00205          " Cutter Z Waiting Position Check
00206 00118          IOW MB045740 == 1;
00207
00208          " Scribe Chuck Y Step Process Set
00209 00119          IF MB30035 == 1;
00210              " Chuck Y Don't Move
00211 00120              IF MB04524A | MB030034 == 1;
00212 00121              ELSE;
00213                  " [Scribe Chuck] Command Set
00214                  " [Chuck] Waiting Position
00215 00122                  MW04518 = 1;          " Scribe Chuck Command Code Setting
00216 00123                  MB045190 = 1;          " Scribe Chuck Command Execute Bit On
00217 00124                  IOW MB045191 == 1      " Scribe Chuck Command Complete Bit On
00218 00125                  MB045190 = 0;          " Scribe Chuck Command Execute Bit Off
00219 00126                  IOW MB045191 == 0      " Scribe Chuck Command Complete Bit On
00220 00127          IEND;
00221 00128      ELSE;
00222          " [Scribe Chuck] Command Set
00223          " [Chuck] Waiting Position
00224 00129          MW04518 = 1;          " Scribe Chuck Command Code Setting
00225 00130          MB045190 = 1;          " Scribe Chuck Command Execute Bit On
00226 00131          IOW MB045191 == 1      " Scribe Chuck Command Complete Bit On
00227 00132          MB045190 = 0;          " Scribe Chuck Command Execute Bit Off
00228 00133          IOW MB045191 == 0      " Scribe Chuck Command Complete Bit On
00229 00134          IEND;
00230 00135      JOINTO Label0X;
00231
00232      Line03:
00233          " Scribe Camera StandBy Position
00234 00136          PLD [LCAMY][LCAMZ][RCAMY][RCAMZ]
00235 00137          MOV [LCAMY]ML43730 [LCAMZ]ML43930 [RCAMY]ML43830 [RCAMZ]ML44030;
00236 00138          JOINTO Label0X;
00237 00139      Label0X: PJOINT;
00238
00239          " Scribe Unit Home Complete
00240 00140          MB045240 = 1;
00241
00242          " Break Table Standby or Carry Out Position or Break Unit Step Continue Permission
00243 00141          IOW (MB56000 & MB56020 & MB56050) | (MB56005 & MB56025 & MB56050) | MB04524A == 1;
00244
00245          " Break Pusher Bar Waiting Position
00246 00142          IOW (MB51000 & MB51020) | MB04524A == 1;
00247
00248          " ChcuK Break & Table Break Not Continue Step Select
00249 00143          IF MB04524A == 0;
00250              " Scribe Operation Step #1 (Scribe, Pitch Data Update)
00251 00144              MW04511 = 1;          " Action Recipe Comp ID
00252 00145          ELSE;
00253 00146              IF MB053100 == 1          " Last Chuck Break Use
00254 00147                  IF !MB045132 == 1      " Scribe Comp
00255                      " Scribe Operation Step #3 (Alignment 1 Cycle)
00256 00148                      MW04511 = 3;          " Action Recipe Comp ID
00257 00149              IEND;
00258 00150          IEND;
00259 00151      IEND;

```

```
00260
00261 00152      MB045006 = 1;
00262 00153      MB045011 = 1;
00263
00264 00154  END;
00265
```

" Home Complete
" Auto Ready Complete

			MPM030 : SC Home	P00004
--	--	--	------------------	--------