

```

00001      ** DL Register Area - 120Word
00002      **
00003      ** DW00000 - DW00009 (PLS Use)
00004      ** DW00010 - DW00039 (Bit Use)
00005      ** DW00040 - DW00089 (Word Use)
00006      ** DW00090 - DW00119 (Timer)
00007      ****
00008
00009      "# Program Name      : Load Measurement
00010      "# Functionior      :
00011      "# Call Program     :
00012      "# Sub Program      :
00013      "# Func Program     :
00014
00015      VAR;
00016 00000      LONG Axis_CZ_IDX = 34;
00017      END_VAR;
00018
00019 00001      IF MB045740 == 0;                                " All Cutter Z Wait Position
00020 00002          MW04842 = 41;
00021 00003          MSEE MPS198;
00022 00004          MW04842 = 0;
00023 00005          IOW MW04842 == 0;
00024 00006      IEND;
00025
00026          " Push front position and push position acquisition(Modify)
00027
00028 00007      MSEE MPS150;                                " SC Axis Setting (PLD, Speed)
00029
00030 00008      MB154240 = 1;                                " Load Measurement
00031 00009      ML23696 = 0;                                " Load Measurement Update Axis Request
00032
00033
00034          ****
00035          " Head X Moving
00036          ****
00037 00010      MW04825 = 0;                                " Load Measurement Select (0 : Cutter, 1
: Roller)
00038
00039          " [Cutter X] Cutter Z Load Calibration/Measurement Position
00040 00011      IOW MW04514 == 0;
00041 00012      MW04514 = 4;                                " Scribe Req Scribe Cutter Command Code
Setting
00042 00013      MB045150 = 1;                                " Scribe Req Scribe Cutter Command Execu
te Bit ON
00043 00014      IOW MB045151 == 1                                " Scribe Res Scribe Cutter Command Comp
lete Bit ON
00044 00015      MB045150 = 0;                                " Scribe Req Scribe Cutter Command Execu
te Bit OFF
00045 00016      IOW MB045151 == 0                                " Scribe Res Scribe Cutter Command Comp
lete Bit ON
00046
00047          ****
00048          " Load Measurement Action (Upper Cutter)
00049          ****
00050          " Torque Setting Pos (Load Cell Pos - 1000um)
00051 00017      MW15540 = 2;
00052 00018      MSEE MPS254;
00053 00019      MW15525 = 4;
00054 00020      MSEE MPS253;
00055 00021      MOV [CZ]ML15750;
00056
00057 00022      MW15520 = 3;                                " Load Measurement
00058 00023      MW15525 = 1;                                " UPCZ
00059 00024      MSEE MPS253;                                " Cutter Z Torque Set
00060
00061          " Mearesement Point Speed Setting
00062 00025      DL00002 = ML10800[Axis_CZ_IDX];
00063 00026      DL00006 = ML11000[Axis_CZ_IDX];
00064 00027      DL00008 = ML11200[Axis_CZ_IDX];
00065 00028      FMX tDL00002;
00066 00029      IAC tDL00006;
00067 00030      IDC tDL00008;
00068 00031      DL00004 = ML43412 * 60;
00069
00070          " Measurement Positon + 2000um
00071 00032      MW15540 = 3;
00072 00033      MSEE MPS254;
00073 00034      MVS [CZ]ML15750 FDL00004;
00074
00075 00035      TIM TMW26512;                                " Load Check Timer
00076
00077          ****
00078          " Measurement Result Calculation
00079          ****
00080 00036      MW04830 = MW15530                                " UPCZ Measurement Result Data
00081

```

```
00082          *****
00083          " Measurement Result Calculation
00084          *****
00085 00037      ML23642 = MW04830          " UPCZ Measurement Result Data Save
00086
00087          " Torque Setting Pos (Load Cell Pos - 1000um)
00088 00038      MW15540 = 2;
00089 00039      MSEE MPS254;
00090 00040      MOV [CZ]ML15750;
00091
00092          *****
00093          " Cutter Z Stand By Position
00094          *****:
00095 00041      IF MB045740 == 0;
00096 00042          MW04842 = 41;
00097 00043          MSEE MPS198;
00098 00044          MW04842 = 0;
00099 00045          IOW MW04842 == 0;
00100 00046      IEND;
00101
00102          *****
00103          " Load Mearusement Result Setting Request
00104          *****
00105 00047      MB236960 = 1;          " CZ Data Update
00106
00107 00048      MB214624 = 1;          " Load Measurement Result Display Reques
t [MP → UI]
00108 00049          IOW MB205224 == 1          " Load Mearusement Result Display Comple
te [UI → MP]
00109 00050      MB214624 = 0;          " Load Mearusement Result Display Reques
t Clear
00110 00051          ML23696 = 0;          " Load Result Data Request Clear
00111 00052          IOW MB205224 == 0          " Load Mearusement Result Display Comple
te Clear
00112
00113 00053      MB154240 = 0;          " Load Measurement
00114
00115 00054      RET;
```