

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (PLS Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name : Break Pusher Bar Start
00011 "# Function :
00012 "# Call Program :
00013 "# Sub Program :
00014 "# Func Program
00015
00016 VAR;
00017 00000 LONG IDX_BKPB1 = 64;
00018 00001 LONG IDX_BKPB2 = 65;
00019 00002 LONG IDX_BKPBZ1 = 66;
00020 00003 LONG IDX_BKPBZ2 = 67;
00021 END_VAR;
00022
00023 00004 MSEE MPS270; " Break Pusher Bar Speed, Position Updat
e Set
00024
00025 " Break Pusher Bar Receive Position Check
00026 00005 IOW (MB51000 & MB51020) | (MB050742 & (MB51023 | MB51024)) == 1;
00027
00028 " Break Pusher Bar No Commanc
00029 00006 IOW MB050694 == 1;
00030
00031 " Head X Wait
00032 00007 IOW MB045741 == 1;
00033
00034 00008 IF MB000023 == 1;
00035 00009 MB045159 = 1; " Step Mode Next Fla
00036 00010 IOW (!MB21684D | MB20544E) | MB045013 == " Step Mode
00037 00011 MB045159 = 0; " Step Mode Next Fla
00038 00012 IEND;
00039
00040 00013 IF CW00099 == 1;
00041 00014 IF MB000004 == 1;
00042 " Cutting Table Vacuum ON
00043 00015 IF GL21158 > MW15411;
00044 00016 IF !MB00201D == 1 " P Work : Dumm
00045 " [Sensor] Cutting Table All Vacuum Off
00046 00017 IF MB09023F == 1;
00047 00018 MB09049F = 1; " [Sol] Cutting Table All Vacuum
On
00048 00019 IEND;
00049 00020 IEND;
00050 00021 IEND;
00051 00022 IEND;
00052 00023 IEND;
00053
00054 " Inner Bit Reset
00055 00024 DW00001 = 0;
00056 00025 PFORK BKPBY BKPBY;
00057
00058 BKPBY:
00059 " Break Pusher Bar Y
00060
00061 00026 MB05072C = 0;
00062 00027 IF MB51003 == 0;
00063 00028 DL00026 = ML72814 + ML04800 " [Calc] BKPBY1 Breaking Position + BKPBY1 Alignment Data
00064 00029 DL00028 = ML72814 + ML04802 " [Calc] BKPBY1 Breaking Position + BKPBY2 Alignment Data
00065
00066 00030 ML72814 = DL00026;
00067 00031 ML73014 = DL00028;
00068
00069 00032 ML16128 = ML72814 " Break Pusher Bar Y1 Moving Position Wr
ite
00070 00033 ML16130 = ML73014 " Break Pusher Bar Y2 Moving Position Wr
ite
00071
00072 00034 IOW MB50790 & MB50791 == 1 " Break Pusher Bar Y Interference Check
00073
00074 00035 IOW MB50763 == 1 " Break Pusher Bar Y Start Position Movi
ng Permission
00075
00076 00036 MB05072C = 1; " Break Pusher Bar Start Position Moving
Flag Bit On
00077 00037 EOX;
00078 00038 PLD [BKPBY1][BKPBY2];
00079 00039 MOV [BKPBY1]ML16128 [BKPBY2]ML1613 " Break Pusher Bar Y Pos. Moving

```

```
00080 00040          IOW MB51003 == 1          " Break Pusher Bar Y Start Position Comp
lete Check
00081
00082 00041          MB05072C = 0;          " Break Pusher Bar Start Position Moving
Flag Bit Off
00083 00042          IEND;
00084
00085 00043          DB00010 = 1;          " Break Pusher Bar Y Start Position Movi
ng Complete
00086 00044          JOINTO Label111X;
00087
00088          BKPZBZ:
00089          " Break Pusher Bar Z
00090 00045          IF MB51023 == 0
00091 00046          DL00020 = ML27820 + ML72802 - ML27826;
00092 00047          IF ILA816 > DL00020;
00093 00048          IOW DB00010 == 1          " Break Pusher Bar Y Start Position Move
Complete
00094 00049          IEND;
00095
00096          //          IOW DB00010 == 1          " Break Pusher Bar Y Start Position Move
Complete
00097
00098 00050          ML16132 = ML73214          " Break Pusher Bar Z1 Moving Position Wr
ite
00099
00100 00051          IOW MB50773 == 1          " Break Pusher Bar Z Start Position Movi
ng Permission
00101 00052          PLD [BKPZBZ1][BKPZBZ2];
00102 00053          MOV [BKPZBZ1]ML16132 [BKPZBZ2]ML1613
00103 00054          IOW MB51023 == 1          " Break Pusher Bar Start Z Position Comp
lete Check
00104 00055          IEND;
00105
00106 00056          DB00011 = 1;          " Break Pusher Bar Z Start Position Movi
ng Complete
00107 00057          JOINTO Label111X;
00108
00109 00058          Label111X: PJOINT;
00110
00111 00059          RET;
```