

```

00001 *****
00002 ** DL Register Area - 120Word
00003 **
00004 ** DW00000 - DW00009 (Pls Use)
00005 ** DW00010 - DW00039 (Bit Use)
00006 ** DW00040 - DW00089 (Word Use)
00007 ** DW00090 - DW00119 (Timer)
00008 *****
00009
00010 "# Program Name:      :
00011 "# Function:         :
00012 "# Call Program:      :
00013 "# Sub Program:       :
00014 "# Func Program:      :
00015
00016 VAR;
00017     CONST LONG Axis_Name1 = 0;
00018     CONST LONG Axis_Name2 = 1;
00019     CONST LONG Axis_Name3 = 2;
00020 END_VAR;
00021
00022     "PLD [Axis1][Axis2][Axis3];
00023
00024 00000     PFORK Axis1 Axis2 Axis3;
00025
00026     Axis1:
00027
00028 00001         IOW MB060760 == 1                                " Unit5 Motor IL:Axis Name Standby Pos E
00029 nable
00030 00002         ML16000 = ML40030                                " Axis1 Move Data:Axis Name StandBy Pos
00031         "MOV [Axis_Name1]ML16000;
00032
00033 00003         IOW MB041000 == 1                                " Axis1 Name Pos Moving Comp Check
00034
00035 00004         JOINTO Label0X;
00036
00037     Axis2:
00038
00039 00005         IOW MB060770 == 1                                " Unit5 Motor IL:Axis Name Standby Pos E
00040 nable
00041 00006         ML16002 = ML40130                                " Axis2 Move Data:Axis Name StandBy Pos
00042         "MOV [Axis_Name2]ML16002;
00043
00044 00007         IOW MB041010 == 1                                " Axis2 Name Pos Moving Comp Check
00045
00046 00008         JOINTO Label0X;
00047
00048     Axis3:
00049
00050 00009         IOW MB060780 == 1                                " Unit5 Motor IL:Axis Name Standby Pos E
00051 nable
00052 00010         ML16004 = ML40230                                " Axis3 Move Data:Axis Name StandBy Pos
00053         "MOV [Axis_Name3]ML16004;
00054
00055 00011         IOW MB061020 == 1                                " Axis3 Name Pos Moving Comp Check
00056
00057 00012         JOINTO Label0X;
00058
00059 00013         Label0X: PJOINT;
00060
00061 00014         DL00040 = ML40012 * 60 * 1.73;                    " Axis1 Speed Setting
00062 00015         DL00042 = ML10800[Axis_Name1]                    " Axis1 Max Speed Setting
00063 00016         DL00044 = ML11000[Axis_Name1]                    " ACC
00064 00017         DL00046 = ML11200[Axis_Name1]                    " DCC
00065
00066 00018         FMX tDL00042;
00067 00019         IAC tDL00044;
00068 00020         IDC tDL00046;
00069
00070 00021         ML16000 = ML40030                                " Axis1 Move Data:Axis Name StandBy Pos
00071 00022         ML16002 = ML40130                                " Axis2 Move Data:Axis Name StandBy Pos
00072 00023         ML16004 = ML40230                                " Axis3 Move Data:Axis Name StandBy Pos
00073
00074 00024         MB061370 = 1;                                    " Unit5 Cycle1 Move Check
00075
00076         "MVS [Axis_Name1]ML16000 [Axis_Name2]ML16002 [Axis_Name3]ML16004 FDL00040 PFN;
00077
00078 00025         IOW MB061000 == 1                                " Axis1 Name Pos Moving Comp Check
00079 00026         IOW MB061010 == 1                                " Axis2 Name Pos Moving Comp Check
00080 00027         IOW MB061020 == 1                                " Axis3 Name Pos Moving Comp Check
00081
00082 00028         MB061370 = 0;                                    " Unit5 Cycle1 Move Check
00083
00084 00029     RET;

```