

```

00001      *****
00002      ** DL Register Area - 120Word
00003      **
00004      ** DW00000 - DW00009 (Pls Use)
00005      ** DW00010 - DW00039 (Bit Use)
00006      ** DW00040 - DW00089 (Word Use)
00007      ** DW00090 - DW00119 (Timer)
00008      *****
00009
00010      "# Program Name      :
00011      "# Function      :
00012      "# Call Program      :
00013      "# Sub Program      :
00014      "# Func Program      :
00015
00016      VAR;
00017          CONST LONG Axis_Name1 = 0;
00018          CONST LONG Axis_Name2 = 1;
00019          CONST LONG Axis_Name3 = 2;
00020      END_VAR;
00021
00022          "PLD [Axis1][Axis2][Axis3];
00023
00024 00000      PFORK Axis1 Axis2 Axis3;
00025
00026          Axis1:
00027
00028 00001          IOW MB065760 == 1                                " Unit6 Motor IL:Axis Name Standby Pos E
00029      nable
00030 00002          ML16000 = ML40030                                " Axis1 Move Data:Axis Name StandBy Pos
00031          "MOV [Axis_Name1]ML16000;
00032
00033 00003          IOW MB066000 == 1                                " Axis1 Name Pos Moving Comp Check
00034
00035 00004          JOINTO Label0X;
00036
00037          Axis2:
00038
00039 00005          IOW MB065770 == 1                                " Unit6 Motor IL:Axis Name Standby Pos E
00040      nable
00041 00006          ML16002 = ML40130                                " Axis2 Move Data:Axis Name StandBy Pos
00042          "MOV [Axis_Name2]ML16002;
00043
00044 00007          IOW MB066010 == 1                                " Axis2 Name Pos Moving Comp Check
00045
00046 00008          JOINTO Label0X;
00047
00048          Axis3:
00049
00050 00009          IOW MB065780 == 1                                " Unit6 Motor IL:Axis Name Standby Pos E
00051      nable
00052 00010          ML16004 = ML40230                                " Axis3 Move Data:Axis Name StandBy Pos
00053          "MOV [Axis_Name3]ML16004;
00054
00055 00011          IOW MB066020 == 1                                " Axis3 Name Pos Moving Comp Check
00056
00057 00012          JOINTO Label0X;
00058
00059 00013          Label0X: PJOINT;
00060
00061 00014          DL00040 = ML40012 * 60 * 1.732                    " Axis1 Speed Setting
00062 00015          DL00042 = ML10800[Axis_Name1]                    " Axis1 Max Speed Setting
00063 00016          DL00044 = ML11000[Axis_Name1]                    " ACC
00064 00017          DL00046 = ML11200[Axis_Name1]                    " DCC
00065
00066 00018          FMX tDL00042;
00067 00019          IAC tDL00044;
00068 00020          IDC tDL00046;
00069
00070 00021          ML16000 = ML40030                                " Axis1 Move Data:Axis Name StandBy Pos
00071 00022          ML16002 = ML40130                                " Axis2 Move Data:Axis Name StandBy Pos
00072 00023          ML16004 = ML40230                                " Axis3 Move Data:Axis Name StandBy Pos
00073
00074 00024          MB066370 = 1;                                    " Unit6 Cycle1 Move Check
00075
00076          "MVS [Axis_Name1]ML16000 [Axis_Name2]ML16002 [Axis_Name3]ML16004 FDL00040 PFN;
00077
00078 00025          IOW MB066000 == 1                                " Axis1 Name Pos Moving Comp Check
00079 00026          IOW MB066010 == 1                                " Axis2 Name Pos Moving Comp Check
00080 00027          IOW MB066020 == 1                                " Axis3 Name Pos Moving Comp Check
00081
00082 00028          MB066370 = 0;                                    " Unit6 Cycle1 Move Check
00083
00084 00029      RET;

```