



ROOFSCAN UK

Drone Roof Inspection Report


PROPERTY

12 Ocean Drive, Brighton - BN1 4ZZ

REPORT DETAILS

Date: 14 June 2026
Client: J. & M. Harrington
Ref: RS-2026-0142

ROOF TYPE	COVERING	APPROX. AGE	DEFECTS FOUND
Pitched, hipped	Concrete tile	Approx. 25 years	3




[INSERT MAIN PROPERTY / ROOF IMAGE HERE]

www.roofscanuk.co.uk | 07498 364197 | info@roofscanuk.co.uk


Contents

Executive Summary


Condition Dashboard



Overall Roof Condition



RoofScore



Summary of Findings

The roof is in generally good condition for its age. One area of concern was identified at the ridge tiles above the bay window, where mortar has begun to fail. Two further items are recommended for monitoring. No evidence of active water ingress was observed at the time of inspection.

Key Risks

The loose ridge tile section poses a risk of water ingress if not addressed before the next period of heavy rain or high wind. Left unattended, displaced tiles could also become a falling hazard.

Maintenance Overview

Recommend re-bedding and re-pointing the affected ridge tiles within the next 3 months. Gutters should be cleared ahead of autumn. A further drone inspection is recommended in 12 months.

1.0

Report Details

Scope, limitations & rating system

1.0 About This Report

Property: 12 Ocean Drive, Brighton - BN1 4ZZ

Inspection Date: 14 June 2026

Client: J. & M. Harrington

Prepared By: Takhy Ndiaye Marrero - RoofScan UK

Report Reference: RS-2026-0142

1.1 Scope

Instructions were received to attend the property and undertake a drone-based visual inspection. This report has been prepared based on drone imagery captured on-site. It does not constitute a full building survey.

1.2 Limitations

The inspection was carried out using an unmanned aerial vehicle (drone). All observations are based on visual imagery only - no physical contact with roof surfaces was made.

1.3 Traffic-Light System

Repair Required - A defect requiring remedial action.

Monitor - Warrants attention but not immediately critical.

Satisfactory - No immediate action required.

2.0

Observations & Recommendations

Drone inspection findings by element

2.0 Observations & Recommendations

Observations are made as if standing at the front of the property.

2.1 Chimneys & Leadwork

The chimney stacks are the most exposed elements and common sources of water ingress.

Inspection Limitation

Chimney elements inspected by drone only. No physical access to the stack was undertaken.

Ref 2.1.1 Ridge tiles, bay window

[INSERT DRONE IMAGE]
Replace with cropped drone photo

Repair Required

Observation

Mortar bedding to two ridge tiles above the bay window has failed, with visible cracking and a small section of displaced mortar. No tiles are currently loose, but the bedding is no longer weathertight.

Priority

Within 3 months

Ref 2.1.2 Chimney stack flaunching

[INSERT DRONE IMAGE]
Replace with cropped drone photo

Monitor

Observation

Flaunching around the base of the chimney stack shows minor hairline cracking, consistent with normal weathering. No displacement observed.

Priority

Record & monitor

2.2 Roof Coverings

The observations below relate to the primary roof covering.

Ref 2.2.1 Main roof slope, rear elevation	
[INSERT DRONE IMAGE] Replace with cropped drone photo	Satisfactory Observation Tiles are securely fixed with no evidence of slippage, cracking or moss build-up beyond normal levels for the roof's age. Priority N/A
Ref 2.2.2 Main roof slope, front elevation	
[INSERT DRONE IMAGE] Replace with cropped drone photo	Monitor Observation Covering is in good condition. A small area of moss growth was noted on the north-facing slope, typical for this orientation and not currently affecting performance. Priority Within 12 months

2.3 Rainwater Goods

The rainwater goods are critical to managing surface water away from the building fabric.

Inspection Limitation

Rainwater goods were not observed under live rainfall. Observe gutters during heavy rainfall.

Ref 2.3.1 Gutters, front elevation

[INSERT DRONE IMAGE]
Replace with cropped drone photo

Satisfactory

Observation
Gutters are securely fixed and free of visible blockages at the time of inspection.

Priority
N/A

Ref 2.3.2 Downpipe, rear elevation

[INSERT DRONE IMAGE]
Replace with cropped drone photo

Satisfactory

Observation
Downpipe is intact and correctly aligned with the gutter outlet.

Priority
N/A

2.4 Ancillary Elements

The following observations relate to elements outside the primary roof structure.

Ref 2.4.1 Soffits and fascias	
[INSERT DRONE IMAGE] Replace with cropped drone photo	Satisfactory Observation Soffits and fascias are in sound condition with no visible rot, warping or paint failure. Priority N/A
Ref 2.4.2 TV aerial mount	
[INSERT DRONE IMAGE] Replace with cropped drone photo	Satisfactory Observation Aerial mounting bracket is securely fixed to the chimney stack with no signs of movement. Priority N/A

3.0

Terms & Disclaimer

Limitations, liability & regulatory notes

ROOFSCAN UK | Drone Roof Inspection Report

3.0 Terms, Limitations & Disclaimer

3.1 Confidentiality

This report is prepared solely for the named client. No responsibility is accepted to any third party.

3.2 Scope Limitations

This is a visual-only drone inspection and is not a full structural survey.

3.3 Drone Operations

All drone operations are conducted in compliance with UK CAA regulations.

RoofScan UK | www.roofscanuk.co.uk

4.0

Schedule of Works

Summary table for contractor briefing

4.0 Schedule of Works

The table below summarises all observations. Obtain written quotations from suitably qualified contractors before any works commence.

Ref	Element	Observation Summary	Priority
2.1.1	Ridge tiles, bay window	Mortar bedding to two ridge tiles above the bay window has failed, with visible cracking and a small section of displaced mortar. No tiles are currently loose, but the bedding is no longer weathertight.	Within 3 months
2.1.2	Chimney stack flaunching	Flaunching around the base of the chimney stack shows minor hairline cracking, consistent with normal weathering. No displacement observed.	Record & monitor
2.2.1	Main roof slope, rear elevation	Tiles are securely fixed with no evidence of slippage, cracking or moss build-up beyond normal levels for the roof's age.	N/A
2.2.2	Main roof slope, front elevation	Covering is in good condition. A small area of moss growth was noted on the north-facing slope, typical for this orientation and not currently affecting performance.	Within 12 months
2.3.1	Gutters, front elevation	Gutters are securely fixed and free of visible blockages at the time of inspection.	N/A
2.3.2	Downpipe, rear elevation	Downpipe is intact and correctly aligned with the gutter outlet.	N/A
2.4.1	Soffits and fascias	Soffits and fascias are in sound condition with no visible rot, warping or paint failure.	N/A
2.4.2	TV aerial mount	Aerial mounting bracket is securely fixed to the chimney stack with no signs of movement.	N/A

End of Schedule of Works - RoofScan UK