

L = xtal_length

 $R = xtal_radius$

LC = pc_length

RC = pc_radius

LT = taper_length

RO = wrap_around_radius

LO = ditch_depth

WO = ditch_thickness

LH = hole_length

RH = hole_radius