


## GX20 Tool Head V2


### GX20 10 FM



Socket viewed  
from solder side

|    |                           |          |       |
|----|---------------------------|----------|-------|
| 1  |                           |          |       |
| 2  |                           |          |       |
| 3  | Pt1000 Temperature sensor | Red/24   | 1M    |
| 4  | PT1000 Temperature sensor | Red/24   | 1M    |
| 5  | thermistor extruder       | blue/24  | 920mm |
| 6  | thermistor extruder       | blue/24  | 920mm |
| 7  |                           |          |       |
| 8  |                           |          |       |
| 9  | Z Probe                   | white/22 | 1M    |
| 10 | Z Probe                   | white/22 | 1M    |

### GX20 6 FM



Socket viewed from  
solder side

|   |                    |                     |       |
|---|--------------------|---------------------|-------|
| 1 | Heater Cartridge + | used supplied       | 1M    |
| 2 | Heater Cartridge - | used supplied       | 1M    |
| 3 | Stepper motor A2   | Black used supplied | 940mm |
| 4 | Stepper motor A1   | Green used supplied | 940mm |
| 5 | Stepper motor B1   | Blue used supplied  | 940mm |
| 6 | Stepper motor B2   | Red used supplied   | 940mm |

Max wire size for:-  
6 Pin 16 AWG  
10 Pin 20 AWG