Off. no. 2, 1st floor, 'Gold Wings', cop. Big Bazaar, Behind Aditya Nakoda Enclave,
Above Darshan Tyres, Sinhgad Road, Parvati, Pune - 411030
Telefax - 020 - 24251225 | Cell - 9822021012 | E-mail - kamalbiyani@gmail.com





To,

ICICI Lombard Generali India Insurance Co Ltd.,

Pune 411001

Kind Attn: Mr. Chaitanya Kota

Our Ref No.: 14888/ICICI/19-20

Date: 11th September 2019

Claim No. F002224928

IMMEDIATE LOSS ADVICE

DATE OF LOSS : 5th to 15th August 2019

DATE AND TIME OF INSTRUCTION : 15th August 2019

FROM INSURER

TIME & DATE OF VISIT : 16th August 2019

PERSON CONTACTED : Mr. Sunil Patni

Mobile No. 982245256

NAME OF INSURED: Mrs. Manju Sobhachand Jain, Veebha Sunil &

ADDRESS OF THE INSURED Bhawana Sanjay Patni.

/LOCATION OF LOSS, WITH PIN At- 13/1437, Gulabkuni, Shelke mala, Ichalkaranji,

CODE Kolhapur - 416115

Address of loss location: At- 13/1437, Gulabkunj,

Shelke mala, Ichalkaranji, Kolhapur - 416115

NAME OF POLICY : Standard Fire & Special Peril Insurance Policy

POLICY NO 1001/173419044/00/000

Policy period - 18/06/2019 to 17/06/2020

Sum Insured Rs. 90,00,000.00

AFFECTED ITEM : Building

SUPPOSED CAUSE : Due to Flood/Inundation

NATURE AND EXTENT OF DAMAGE

We carried out the survey on 16th August 2019. The insured residence is located at the loss location. The Building is a class A RCC type construction with RCC slab roofing ground plus two floored. The building was fenced with BB masonry wall from all four side. The approximate area of the building was measuring about 3500 sq feet. The flood water level out side the premises was observed around 10 feet and inside the insured premises around 8 to 9 feet. The RCC beams and columns observed jolted and cracks were observed at the joints. The gaps were developed in the RCC structure and brick masonry. Internal plaster of the walls found affected. External and internal brick masonry found water affected and cracks were developed at many places. The flooring and skirting tiles observed loosen and uprooted at many places. The external wall finish and internal wall finish affected due to muddy water. Windows and door were jammed due to water in contact and were not operational. Line of action

- To provide the list of damaged items along with the repairs estimate.
- To start the cleaning activity.
- Confirm us the schedule for final inspection.

Insured was also advised to provide the requisite documents /information.

POLICY LIABILITY : Yes, loss is covered under the policy.

POLICY COVERAGE, SCOPE: STFI and allied perils are covered. Hence, the

(COVERAGE FOR PROPERTY AND operated peril is covered under the policy

MAIN PERIL OPERATION)

INSURED'S ESTIMATE OF LOSS : Rs. 22,48,000.00

PRESENTLY ESTIMATED LOSS RESERVE : Rs. 18,00,000.00

BASIS OF RESERVE : Reserves are based on our inspection.

ISSUES : -

DOES LOSS NEED FURTHER : -

DISCUSSIONS WITH INSURERS?





K. R. BIYANI KAMAL BIYANI ASSOCIATES

License No. SLA 34365 valid till 27.11.2019