

Investigation

Root cause analysis for AUD-2024-0157 — Weld Seam Inspection, Line 3.

Save Draft

Complete Investigation

INVESTIGATION
PROGRESS

Step
3 of
7

In
Progress

2 of 7 steps complete

29%

Problem Statement

Captured during audit creation — read only.

Weld seam penetration on Bracket Assembly Rev C measured below specification on Production Line 3 during second-shift inspection, resulting in three rejected units.

PLANT DEPARTMENTPRODUCT IDSEVERITY
Plant Welding LINE
3 — Line • High
Midwest 3

INVESTIGATION STEPS

✓ Why 1

✓ Why 2

○ Why 3

○ Why 4

○ Why 5

○ Root Cause

○ Corrective Action

Tip

Each Why should build directly on the previous answer. Be specific and evidence-based — avoid restating the problem statement.

FIVE WHY ANALYSIS & ROOT CAUSE



Why 1

Why did this ...

Completed



Why 2

Why did the ...

Completed



Why 3

Why did tha...

In Progress