SYNTHETIC DEMONSTRATION ? NOT CUSTOMER DATA
Incident Diagnostic ? Door interlock delayed robot route recovery
Report version 1 | Template technical report.v1
Generated 2026-07-19T00:00:00Z

Executive summary

A synthetic robot stopped at a controlled door after the fleet route request preceded the door-open confirmation. The available evidence supports an interlock delay as the leading hypothesis, while a Wi-Fi interruption remains an explicitly reviewed alternative.

Impact: One synthetic transport task paused for 214 seconds; no safety event or customer production impact is represented.
Unplanned downtime: 214 seconds

Hypotheses

[HYP-SYN-001] Door interlock response delay ? confidence 0.74
[HYP-SYN-002] Wi-Fi roaming interruption ? confidence 0.28

Timeline (each row cites immutable evidence)

2026-01-15T10:02:11Z [RAW-SYN-001] BLOCKED_PATH Robot stopped before Door D-17
2026-01-15T10:02:13Z [RAW-SYN-002] DOOR_RELEASE Fleet requested door release
2026-01-15T10:02:31Z [RAW-SYN-003] DOOR_OPEN PLC confirmed open state
2026-01-15T10:04:42Z [RAW-SYN-004] MISSION_RESUMED Robot navigation resumed
2026-01-15T10:05:45Z [RAW-SYN-005] TASK_RESUMED Synthetic transport workflow recovered

Limitations

The synthetic PLC clock has a reviewed +850 ms offset; close ordering is marked uncertain.
The controller diagnostic trace is missing, limiting causal certainty.