


General Update

- SPR
 - AC replacement week of 16th of August
 - Installation ongoing
 - Antonio Feed
 - PY-018 Installed OK
 - PY-001 installed OK
 - PY-004 issue on Y-pol
- Other
 - Control Box replaced at 2B
 - Debugged issues
 - Broken V1 feeds removed
 - Attemplifier modules construction
 - Wire harness construction for Antonio Feeds

- Antonio Feed Overview
 - 22 Antennas fully operational
 - 18 / 19 Antonio Feeds

UFS preparations:



UFS preparations:


- Crew will come to HCRO tomorrow
 - 50ft
- New add on to our agreement
 - 100ft











AC replacement:

- Power requirement



Location of Main Power distribution for HCRO with 70A fuse

#6
existing wire





AC disconnect with 60A fuse

#8
new wire (approx. 50ft)
Existing conduit is 3/4 in



AC unit







master  Front-Page / MEMOS /		 Go to file	 Add file 	
 AlexanderPollak	added memos	f72d93c	2 minutes ago	 History
..				
 2019-10 Antenna Tsys Measurement	added memos		2 minutes ago	
 2020-02 PAX Power Level Control Software	added memos		2 minutes ago	
 2020-09 ATA Dynamic Range Report	added memos		2 minutes ago	
 2020-10 RFCB-Measurement Report	added memos		2 minutes ago	
 2021-03 Interface & Rate Sheet	added memos		2 minutes ago	
 2021-04 Pointing-Calibration	added memos		2 minutes ago	
 2021-07 Antonio Feed Buildout	added memos		2 minutes ago	
 .DS_Store	added memos		2 minutes ago	
 Readme.md	Update Readme.md		10 months ago	