General Update

- SPR
 - Planning of tone measurement of RFCBs
 - Planning of power measurement after RF 4-way splitter
 - Investigate IF ripples

- General update
 - Will receive quote from LNF for 6 spare LNAs
 - Station Clock ordered
 - Components for RFSoC enclosure ordered
 - Missing optocoupler PCB design
 - IF gain Control

Antonio Feed update

- Feeds (003, 004, 008, 010, 011, 014)
 - Parts delivered for Gold Plating
 - Wire Harness about half way
- Feed 4J warmed up yesterday looks like turbo pump shut off.
- Trip to Minex on the 20th of November

Feed List		Feed Revision Overview							
Number	Installed Ant.	Tip-Link: R03	Temp S. Isolation	New Harness	Bellow Removed	Cryo Tuned	Firmware 5.4	Gold-Plated	Preconditioned Coax
<u>5C4-002</u>	Feed Lab								
<u>5C4-003</u>	Feed Lab (5B)		In Progress	In Progress	In Progress			In Progress	
<u>5C4-004</u>	Feed Lab (2E)		In Progress	In Progress	In Progress			In Progress	
<u>5C4-005</u>	2A								
<u>5C4-006</u>	4 J	Х	X	Х	х	Х	Х	Х	X
5C4-007	Feed Lab								
<u>5C4-008</u>	Feed Lab (1G)		In Progress	In Progress	In Progress			In Progress	
<u>5C4-009</u>	Minex								
<u>5C4-010</u>	Feed Lab (2B)		In Progress	In Progress	In Progress			In Progress	Needs LNA replacement
<u>5C4-011</u>	Feed Lab (3L)		In Progress	In Progress	In Progress			In Progress	
<u>5C4-012</u>	1K	Х	X	X	X	X	X	X	NA
<u>5C4-013</u>	Feed Lab (1H)	X	X	X	X	x	X	X	x
<u>5C4-014</u>	Feed Lab (2J)		In Progress	In Progress	In Progress			In Progress	
<u>5C4-015</u>	Minex								
5C4-016	Minex								
<u>5C4-017</u>	Minex								
5C4-018	2H	Х	X	X	X	X	Х	X	NA
<u>5C4-019</u>	1C		X	Х	х	Х			
5C4-020	3C	Х	Х	Х	Х	х	Х	Х	×





Cables missing

- Feed Base
 - Cryo-Cooler
 - RS232 Cable
 - Fan cable
 - Cryostat Cable (consists of 3 individual cables)

Minex

- 6 Feed Pyramids fully assembled
- 4 base plates
- 6 control board mounting sets

