

SERVICE REPORT



SRV2-TEST medium - No microphone audio in Boardroom 3.01

RAA

Job: SKS-90002

Date: 23/09/2026

CLIENT	RAA	CONTACT	Sarah Nguyen sarah.nguyen@example.com.au
SITE	1 King William St, Adelaide SA 5000	ROOM	Level 3 · Boardroom 3.01
EQUIPMENT	Cisco Room Kit Pro · Ceiling Mic Pro	CONTRACT	Ad-hoc service
TECHNICIAN	Mark Stow	ATTENDED	23 Sept 2026 Ref PO-1002

Issue reported

The client reported that participants at the far end could not hear audio from Boardroom 3.01.

Work carried out

Found the Ceiling Mic Pro offline on the codec due to PoE being disabled on switch port 14 following an IT firmware update, alongside a crushed patch lead at the wall plate. Re-enabled PoE on port 14 with IT, re-terminated the keystone jack, replaced the damaged lead with a new 2 m CAT6A patch lead, and re-paired the microphone to the codec. Confirmed full functionality via a Microsoft Teams test call with IT, verifying clear audio in both directions.

Parts and gear used

Qty	Item	Note
1	2m CAT6A Patch Lead	replaced crushed lead at wall plate

Advice for the client

- Notify SKS ahead of scheduled network switch firmware updates to ensure AV port and PoE settings are maintained.

TECHNICIAN

Mark Stow

SKS Technologies

23 Sept 2026

CLIENT ACKNOWLEDGEMENT

Name

Date

