

Header — before (screenshot)



Header — after (HD rebuild)



C1 · Classic Docket

SERVICE REPORT

No microphone audio in Boardroom 3.01

Flinders Medical Research

Job: SKS-26774

Date: 18/09/2026



CLIENT	Flinders Medical Research	CONTACT	Sarah Nguyen sarah.nguyen@fmr.org.au
SITE	1 King William St, Adelaide SA 5000	ROOM	Level 3 · Boardroom 3.01
EQUIPMENT	Cisco Room Kit Pro · Ceiling Mic Pro	CONTRACT	AV Support — Gold
TECHNICIAN	Mark Stow	ATTENDED	18 Sep 2026 · 1.5 hrs

ISSUE REPORTED

Far-end participants couldn't hear anyone in the room during Teams and Webex calls. Local playback worked, but the ceiling microphones weren't being picked up by the codec.

WORK CARRIED OUT

The Ceiling Mic Pro had dropped off the network after a recent switch firmware update turned off PoE on its port. We re-enabled PoE, replaced a damaged patch lead at the wall plate, re-paired the mic to the codec and ran a test call with your IT team — audio is clear in both directions.

PARTS & GEAR USED

QTY	ITEM	NOTE
1	CAT6A patch lead, 2 m	Replaced damaged lead at wall plate
1	RJ45 keystone insert	Wall plate re-terminated

ADVICE FOR THE CLIENT

- Let us know before any network switch firmware updates — AV ports need PoE locked on.
- Run a quick test call after network changes so issues are caught before a meeting.
- Keep a spare patch lead in the credenza for a fast swap if it happens again.

TECHNICIAN

Mark Stow

DATE: 18 SEP 2026

CLIENT ACKNOWLEDGEMENT

NAME / DATE



C2 · Numbered Scope

SERVICE REPORT

No microphone audio in Boardroom 3.01

Flinders Medical Research

Job: SKS-26774

Date: 18/09/2026



CLIENT

Flinders Medical Research

Sarah Nguyen · sarah.nguyen@fmr.org.au

SITE

1 King William St, Adelaide SA 5000

Level 3 · Boardroom 3.01

EQUIPMENT

Cisco Room Kit Pro ·

Ceiling Mic Pro

TECHNICIAN

Mark Stow

ATTENDED

18 Sep 2026

1.5 hrs on site

CONTRACT · REF

AV Support — Gold

PO-88213 · #412

01 Issue reported

Far-end participants couldn't hear anyone in the room during Teams and Webex calls. Local playback worked, but the ceiling microphones weren't being picked up by the codec.

02 Work carried out

The Ceiling Mic Pro had dropped off the network after a recent switch firmware update turned off PoE on its port. We re-enabled PoE, replaced a damaged patch lead at the wall plate, re-paired the mic to the codec and ran a test call with your IT team — audio is clear in both directions.

03 Parts & gear used

1 ×	CAT6A patch lead, 2 m	Replaced damaged lead at wall plate
1 ×	RJ45 keystone insert	Wall plate re-terminated

04 Advice going forward

- Let us know before any network switch firmware updates — AV ports need PoE locked on.
- Run a quick test call after network changes so issues are caught before a meeting.
- Keep a spare patch lead in the credenza for a fast swap if it happens again.

TECHNICIAN

Mark Stow

18 SEP 2026

CLIENT ACKNOWLEDGEMENT

NAME / DATE



C3 · Split Docket

SERVICE REPORT

No microphone audio in Boardroom 3.01

Flinders Medical Research

Job: SKS-26774

Date: 18/09/2026



CLIENT

Flinders Medical Research
Sarah Nguyen

SITE

1 King William St, Adelaide SA
5000
Level 3 · Boardroom 3.01

EQUIPMENT

Cisco Room Kit Pro ·
Ceiling Mic Pro

TECHNICIAN

Mark Stow
18 Sep 2026 · 1.5 hrs

ISSUE REPORTED

Far-end participants couldn't hear anyone in the room during Teams and Webex calls. Local playback worked, but the ceiling microphones weren't being picked up by the codec.

WORK CARRIED OUT

The Ceiling Mic Pro had dropped off the network after a recent switch firmware update turned off PoE on its port. We re-enabled PoE, replaced a damaged patch lead at the wall plate, re-paired the mic to the codec and ran a test call with your IT team — audio is clear in both directions.

PARTS & GEAR USED

QTY	ITEM	NOTE
1	CAT6A patch lead, 2 m	Replaced damaged lead at wall plate
1	RJ45 keystone insert	Wall plate re-terminated

ADVICE FOR THE CLIENT

- Let us know before any network switch firmware updates — AV ports need PoE locked on.
- Run a quick test call after network changes so issues are caught before a meeting.
- Keep a spare patch lead in the credenza for a fast swap if it happens again.

TECHNICIAN

Mark Stow

CLIENT ACKNOWLEDGEMENT

STATUS RESOLVED

SKS Technologies Pty Ltd · ABN 51 168 906 956 · 16 Fullarton Road, Norwood SA 5067 · +61 8 8362 4942 · sks.com.au



C4 · Arrow Tabs

SERVICE REPORT

No microphone audio in Boardroom 3.01

Flinders Medical Research

Job: SKS-26774

Date: 18/09/2026

✓ RESOLVED



CLIENT

Flinders Medical Research
Sarah Nguyen

SITE

**1 King William St, Adelaide SA
5000**
Level 3 - Boardroom 3.01

EQUIPMENT

Cisco Room Kit Pro · Ceiling Mic Pro

TECHNICIAN

Mark Stow

ATTENDED

18 Sep 2026
1.5 hrs on site

CONTRACT

AV Support — Gold
Ref PO-88213

01 Issue reported

Far-end participants couldn't hear anyone in the room during Teams and Webex calls. Local playback worked, but the ceiling microphones weren't being picked up by the codec.

02 Work carried out

The Ceiling Mic Pro had dropped off the network after a recent switch firmware update turned off PoE on its port. We re-enabled PoE, replaced a damaged patch lead at the wall plate, re-paired the mic to the codec and ran a test call with your IT team — audio is clear in both directions.

03 Parts & gear used

1 × CAT6A patch lead, 2 m

Replaced damaged lead at wall plate

1 × RJ45 keystone insert

Wall plate re-terminated

04 Advice going forward

- Let us know before any network switch firmware updates — AV ports need PoE locked on.
- Run a quick test call after network changes so issues are caught before a meeting.
- Keep a spare patch lead in the credenza for a fast swap if it happens again.

TECHNICIAN

Mark Stow

DATE: 18 SEP 2026

CLIENT ACKNOWLEDGEMENT

NAME / DATE



C5 · Full Form

SERVICE REPORT

No microphone audio in Boardroom 3.01

Flinders Medical Research

Job: SKS-26774

Date: 18/09/2026



CLIENT Flinders Medical Research		CONTACT Sarah Nguyen		CLIENT REF PO-88213		TICKET #412	
SITE 1 King William St, Adelaide SA 5000			ROOM Level 3 · Boardroom 3.01			EQUIPMENT Cisco Room Kit Pro · Ceiling Mic Pro	
TECHNICIAN Mark Stow		DATE ATTENDED 18 Sep 2026		TIME ON SITE 1.5 hrs		CONTRACT Gold	
JOB STATUS ☒ Resolved ☐ Follow-up required ☐ Quote to follow							
ISSUE REPORTED							01
Far-end participants couldn't hear anyone in the room during Teams and Webex calls. Local playback worked, but the ceiling microphones weren't being picked up by the codec.							
WORK CARRIED OUT							02
The Ceiling Mic Pro had dropped off the network after a recent switch firmware update turned off PoE on its port. We re-enabled PoE, replaced a damaged patch lead at the wall plate, re-paired the mic to the codec and ran a test call with your IT team — audio is clear in both directions.							
PARTS & GEAR USED							03
QTY	ITEM	SUPPLIED BY		NOTE			
1	CAT6A patch lead, 2 m	SKS		Replaced damaged lead at wall plate			
1	RJ45 keystone insert	SKS		Wall plate re-terminated			
ADVICE FOR THE CLIENT							04
- Let us know before any network switch firmware updates — AV ports need PoE locked on. - Run a quick test call after network changes so issues are caught before a meeting. - Keep a spare patch lead in the credenza for a fast swap if it happens again.							
TECHNICIAN SIGNATURE				CLIENT SIGNATURE			
Mark Stow SKS Technologies				_____ Name			
18 Sep 2026				Date			

