SAMPLE DOCUMENT - NOT A SITE-APPROVED PROCEDURE

Pump Vibration Field Summary

Document type: Troubleshooting report
Manufacturer: Example Pumps
Asset type: Centrifugal pump
Revision: Sample-PDF-01

Observed condition

Elevated vibration is an observation, not proof of bearing failure. Confirm asset identity, timestamp, reading source, and operating context.

Review topics

Compare a time window of readings with the asset-specific threshold. Review coupling, looseness, lubrication, and prior maintenance records using approved procedures.

Example evidence: timestamped vibration readings and approved prior work-order notes.

Pump Vibration Field Summary

Document type: Troubleshooting report
Manufacturer: Example Pumps
Asset type: Centrifugal pump
Revision: Sample-PDF-01

Interpretation and next step

Potential causes include imbalance, misalignment, looseness, bearing wear, or sensor issues. A qualified person should gather confirming evidence.

Evidence limits

This sample gives no alarm setpoint, acceptance criterion, or permission to intervene. Follow approved isolation and safety controls.