




NOTE: If an operator scans the VIN at any flashing station, even after stations such as Static, IMU, etc., have already been completed and marked with an OK status, all previously recorded OK statuses should be overridden and updated to NOK, irrespective of the reason for the scan.