

$$R_p := 100000 \, \Omega$$

$$R_f := 1500 \, \Omega$$

$$R_A := 100 \, \Omega$$

$$C := 4.7 \, \mu F$$

$$R_b := 1000 \, k\Omega \quad R_{b2} := R_p + R_f$$

$$R_B := \frac{R_b \cdot R_{b2}}{R_b + R_{b2}} = (9.215 \cdot 10^4) \, \Omega$$

$$T := 0.693 \cdot (R_A + 2 \, R_B) \cdot C = 0.601 \, s$$

$$f := \frac{1}{T} = 1.665 \, Hz$$

$$D := \frac{R_B}{R_A + 2 \, R_B} = 0.5$$

$$\boxed{R_p} := 0 \, \Omega$$

$$\boxed{R_A} := 100 \, \Omega$$

$$\boxed{C} := 4.7 \, \mu F$$

$$\boxed{R_f} := 1500 \, \Omega$$

$$\boxed{R_b} := 1000 \, k\Omega \quad \boxed{R_{b2}} := R_p + R_f$$

$$\boxed{R_B} := \frac{R_b \cdot R_{b2}}{R_b + R_{b2}} = (1.498 \cdot 10^3) \, \Omega$$

$$\boxed{T} := 0.693 \cdot (R_A + 2 \, R_B) \cdot C = 0.01 \, s$$

$$\boxed{f} := \frac{1}{T} = 99.183 \, Hz$$

$$\boxed{D} := \frac{R_B}{R_A + 2 \, R_B} = 0.484$$