Date of LLC:

Logistics:	☐	Management:	☐
Product:	☐	Detection:	☑
Occurence:	☑	Process:	☐

1. What was the problem?

What happened?

lasck of spring

Who detected it?

operator

Where was it detected?

CM4

How was it detected?

rejected on EOL

Why is it a problem?

lack of spring

When did it happen?

2/24/2024 12:00:00 AM (your local time)

How many parts ?

1.00

2. What is the cause?

the NOK parts was produced in the same periode of first claim of lack spring NMAP/551841/10/2023/1559
and the correctives action are implimented in place according to the action plan
the root cause is that the Flow of production rework parts is not efficient and the location of the station Rework

3. Description of the applied modification

BEFORE	AFTER
No integrate the rewokr jail **No separation he rework station and put it outside the production line**	**integrate the rewokr jail** **separate the rework station and put it outside the production line**

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

***For occurence**
-implimentation specific jail for the rework station
-separation rewrok station and production line and put it outside the production line
***For non detection**
-paasing parts on electrical test and vision test with lack spring and see the results

CHECKING

What is the method (who, what, how) for the countermeasures?

Who : AVO
What :
***/For occurence : - verification the rework opeartion done only in the rework station outside the production line**
***/For non detection :**
-check the detection of lack spring by the electrcial test and vision test

SIGNALING

What is the countermeasure supposed to do or make or h detecting a non conformity ?

In case of detection of NOK parts with lack of spring in the production line : alert and block all stock for sorting + Alert and block the parts in transit

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☐	g. Visual aids are posted:	☑
b. All documents have been updated and has been validated with the operators:	☐	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☐	j. Operators can correctly describe what they must do:	☐
e. Maintenance instructions:	☐	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☐		

An evidance of modification:
- Layout___Flow_chart_line (1).pdf
- layer audit in rework station.pdf

6. Potential applicability

LLC Applicability Product:	**Brush mounting plate assy**
LLC Applicability Line / process:	**CM4**
LLC Applicability Plant:	**AVO**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER

Author: Dudek Dominik
Position: SQA Engineer
Phone: +48 12 297 27 86
Fax:
Email: dominik.dudek@nidec-ma.com

CLAIM RECEIVER

Name: Haggui Marwen
Position: Customer Quality
Phone: +21656057189
Fax:
Email: marwen.haggui@avocarbon.com

IMMEDIATE ACTIONS REQUIRED AT NIDEC

PROBLEM DESCRIPTION

lack of spring

DESCRIPTION OF SORTING/REWORK

QUANTITY AND PART NUMBERS CONCERNED

Parts at Nidec plant: 3,214.00
Parts at Nidec logistics platfrom: 0.00
Parts at Nidec's customer (C1): 0.00
Parts in transport: 0.00
Part Number & Description: Brush mounting plate assy (503-773-99-99)

delevery for week 09

Suspected delivery notes and batches#:

SORTING COMPANY CHOSEN TO DO THE SORTING/REWORK

Company Name:
Company Address:
Company Website:
Phone:

COMMENTS FROM NIDEC

All costs for semi-finished goods and finished goods with nok components will be invoiced to the supplier. Nok components will be returned to the supplier.

UPLOAD SIGNED FILE