Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C2 : Production claim**

Problem description: **lack of DMC**

Claim reference: **NMAP/551841/1/2024/1659**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/1/2024**	9:00:02 AM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**2/5/2024**	3:38:33 PM (your local time)	(QR) D2-D
D4 Default Due Date :	**2/5/2024**	9:00:02 AM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**3/19/2024**	10:53:11 AM (your local time)	D
D5-D6 Default Due Date:	**2/14/2024**	9:00:02 AM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**3/20/2024**	1:04:27 PM (your local time)	D5-D
D7-D8 Default Due Date:	**2/14/2024**	9:00:02 AM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**3/20/2024**	1:52:57 PM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	3/20/2024	Marwen Haggui
D1	1/31/2024	Dominik Dudek
D4 Validation	3/19/2024	Dominik Dudek
D2	3/19/2024	Marwen Haggui
D2-D3 Validation	2/6/2024	Dominik Dudek
D3	3/19/2024	Marwen Haggui
D4	3/19/2024	Marwen Haggui
D5	3/20/2024	Marwen Haggui
D5-D6 Validation	3/20/2024	Dominik Dudek
D6	3/20/2024	Marwen Haggui
D7	3/20/2024	Marwen Haggui
D7-D8 Validation	3/22/2024	Dominik Dudek
8D closed	3/22/2024	Dorota Siekaniec
8D Closing	3/22/2024	Dorota Siekaniec
Creation	1/31/2024	Dominik Dudek

15 Result(s)

Steps rejected

0 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Date of Claim:	**1/31/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/1/2024**
Claim reference:	**NMAP/551841/1/2024/1659**	Author:	**DUDEK Dominik**	Update of QR:	**2/1/2024**
Status:	**Closed**	Type:	**C2 : Production claim**		
		CLAIM PPM:	0.00		

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description:	**lack of DMC**	What happened?:	**lack of DMC**
Part Number & Description:	Brush mounting plate assy (503-852-99-99)	Why is it a problem?:	**lack of DMC, rejected on DMC scanner station**
Traceability of nok parts:	**batch 2401191, ASN 180382594**	When did it happen? :	**1/30/2024** 12:00:00 AM (your local time)
Recurrence:	**Recurrent defect**	Who detected it?:	**operator**
Defect S/R:	**No**	Where was it detected? :	**CM4 line**
		How was it detected?:	**visually**
		How many parts ?:	**1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen	✉	• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile ℹ
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **lack of DMC**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **Regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **All reference CM4**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	1,207.00	0.00	1.00	1/31/2024	2401191	Nidec
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	0.00	0.00	0.00	2/5/2024		
Parts at supplier / supplier platform	12,000.00	12,000.00	0.00	2/5/2024		Delevery for Week 06
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **'100 Sorted regarding lack DMC**

First contained shipment information: **first deevery secured will be for week 06**

How are the ok paletts identified?: **With orange identification (standard NIDEC)**

How are the ok parts identified? :: Securing identification.pdf

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
display quality alert	Not required	Supplier	1/31/2024	1/31/2024
QRQC meeting with all the team	Not required	Supplier	1/31/2024	1/31/2024

2 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**1/31/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/1/2024**
Claim reference:	**NMAP/551841/1/2024/1659**	Created by:	**DUDEK Dominik**	Update of QR:	**2/1/2024**
Status:	**Closed**	Type:	**C2 : Production claim**	Date of D4-D8:	**2/7/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

Method : Jail management : Part with missing DMC mixed with good parts due to that part was escaped from the jail (NOK Vision test) and mixed with good parts because :
1-the transfet chute of nok part from the unloading clamp to the jail is not fixed and allow to drop NOK parts oustside the jail
2- the is lack training of opeartor due the management of parts on floor

HOW WAS THE DEFECT REPRODUCED ?

'Re-integration of evacuated parts in the electrical test once no visual problem is detected in the parts(Parts missing DMC) --> the control vision reject these parts --> rejection takes place in the prison --> the prison is damaged (upper side of transfer chute)--> the parts are thrown on the floor

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

the parts was picked up from the floor and didn't passed on control station

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate
update the design of the tansfer chute in the eletrical test to be tottaly cover and don't allow drop the NOK parts	hamza jbelli	2/19/2024	2/19/2024	
training session for all opeartor with mention forbidding to pick up all dropped parts on the flow and each dropped parts will be traited by quality agent	training departement	2/5/2024	2/5/2024	

2 Result(s)