LESSON LEARNED CARD

Site:	Assymex	**Type:**	**Detection**	**CIN:**	18765
Production Line:	Assemblies	**Department:**	**Quality**	**SIN:**	18765
Product:	Trico plastic	**LLC Author:**	Daniel Morales	**Date:**	17/08/2024

WHAT WAS THE PROBLEM? (5W + 2H)

What happened?
To the moment to assembled the male terminal in the brushcard,

Why is it a problem?
Cause a innoperative motor in the production line or with

When did it happen?
25/07/2024

Who detected it?
Operator of customer production line

Where was detected?
Production line / Tester

How was detected?
During the EOL tester in the customer production line (Applying

How many?
2

WHAT IS THE SYMPTOM?

There is a gap between terminals and plastic

There is not a gap between terminals and plastic

BEFORE

Working Instruction talks about the condition of out-of-position terminals, but does not emphasise

AFTER

Updated inspection instruction Op 105 (Inspection of terminales)

WHAT WE LEARNED?

ITEM (Control Factor)	METHOD (Control Point)		STANDARD
			What is Conform?
Method deployed in the work instruction to inspection terminal whit gage is not clear	**What?**	Correct method to verify terminals out position	Verify 100% with the terminals gage the correct position of terminals according the work instruction Rev F
	Where?	Trico plastic production line	
	When?	17/08/2024	
	Who?	Operator	**What is Non-Conform?**
	How?	Verify 100% with the terminals gage the correct position of terminals	Not Verify 100% with the terminals gage the correct position of terminals according the work instruction Rev E
	How Many?	100% produced parts	