AVO Carbon INDIA	8D REPORT	Fromat no:F/QAD/8D/09 Rev no:00 Rev date:16.08.2022

Customer Name : **Lucas TVS**

8D-no: 4 **Submit Date:** 03.02.2024

Status: Closed

Title: Head damage **Supplier:** AVO Carbon india Pvt ltd

Part No: **26718346** AVO Part #5751-01 **Place:** Chennai-98

Reported Date:22.01.2024

Editor: P.Kalaiselvan **Supplier Agent:** Mr.Ramkumar

D1 Team

Member		Phone	E-Mail	Department
1	Gayathri.N	+91 44 42926571	gayathti.n@avocarbon.com	Quality -HOD
2	Sridhar	+91 44 42926530	sridhar.b@avocarbon.com	Manufacturing-HOD
3	Suresh.P	+91 44 42926573	suresh.p@avocarbon.com	Quality
4	Ramkumar.P	+91 44 42926502	ramkumar.p@avocarbon.com	Marketing
5	Sundaresan.R	+ 914442926521	sundaresan.r@avocarbon.com	Process Engg-HOD
6	Sriram.S	+ 914442926541	sriram s@avocarbon.com	Production

D2 Problem Description

Problem no: 1 **Quantity** 5650

Problem Date: 17.01.2024 **Tested Quantity** 5648

Manufacturing Date/ Month: 10.01.2024 **Failure Quantity** 2

Repeated Failure: [ ] Yes [x] No

Compliant Text: **Head damage**

D3 Immediate

	Title	Responsible	Plan End
1	**100% sorting to be done**	A. Senthil	Immediate

D4 Causes analysis

Supposed Root cause

Root cause	Responsible	Plan End
When the brush is ejected in the pilling machine after the brush is campacted, it hits the iron OK basket with some force. Because of this, the nipple-shaped narrow angle head on Part#8346 breaks into the iron basket &Operators handling of collection baskets is not improved	P.Kalaiselvan	25.01.2024

D5 possible remedial action(s)

Title	Responsible	Plan End
Soft material mat should be placed in the collection basket	Mr.Parthipan	30.01.2024

D6 Remedial Action(s)

Title	Responsible	Plan End
Operators should be trained on how to handle baskets full of brushes.	Suresh.A	03.02.2024

D7 Preventive Measures

Control Plan ,First off / Inprocess Inspection

Title	Responsible	Plan End
Congratulations to everyone in the CFT team	P.Kalaiselvan	03.02.2024

D8 Final Discussion

Before	After
Brush hit on the area	

When the brush is ejected in the pilling machine after the brush is campacted, it hits the iron OK basket with some force.
Because of this, the nipple-shaped narrow angle head on Part#8346 breaks into the iron basket