Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C2 : Production claim**

Problem description: **short circiut between soldering pads**

Claim reference: **NMAP/551841/5/2024/1762**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**5/21/2024**	2:19:13 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**5/21/2024**	1:04:43 PM (your local time)	(QR) D2-D3
D4 Default Due Date :	**5/23/2024**	2:19:13 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**9/4/2024**	9:11:50 AM (your local time)	D4
D5-D6 Default Due Date:	**6/3/2024**	2:19:13 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**9/6/2024**	3:12:42 PM (your local time)	D5-D6
D7-D8 Default Due Date:	**6/3/2024**	2:19:13 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**10/9/2024**	9:02:18 AM (your local time)	D7-D8



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	10/9/2024	Marwen Haggui
D1	5/20/2024	Dominik Dudek
D4 Validation	9/4/2024	Dominik Dudek
D2	9/4/2024	Marwen Haggui
D2-D3 Validation	5/22/2024	Dominik Dudek
D3	9/4/2024	Marwen Haggui
D4	9/4/2024	Marwen Haggui
D5	9/6/2024	Marwen Haggui
D5-D6 Validation	9/9/2024	Dominik Dudek
D6	9/6/2024	Marwen Haggui
D7	10/9/2024	Marwen Haggui
D7-D8 Validation	10/9/2024	Dominik Dudek
8D closed	10/11/2024	Dorota Siekaniec
8D Closing	10/11/2024	Dorota Siekaniec
Creation	5/20/2024	Dominik Dudek

15 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D2-D3 Validation	5/21/2024	Dominik Dudek	update requaired - details in mail
D4 Validation	8/20/2024	Dominik Dudek	Please add factor 5 to FTA (as direct link) and then do the analysis in 5Why's. Aslo please correct factor 4 in 5Why's (this analyze have no

D4 Validation	8/23/2024	Dominik Dudek	Please do necesery corection. Details in email.

3 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Date of Claim: **5/20/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **5/21/2024**

Claim reference: **NMAP/551841/5/2024/1762**
Author: **DUDEK Dominik**
Update of QR: **5/21/2024**

Status: **Closed**
Type: **C2 : Production claim**

CLAIM PPM: 0.00

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **short circiut between soldering pads**
What happened?: **short circiut between soldering pads**

Part Number & Description: Brush Mounting Plate Assy (503-779-99-99)
Why is it a problem?: **rejected on EOL**

Traceability of nok parts: **Batch 231205, ASN180390745**
When did it happen? : **5/19/2024** 11:00:00 PM (your local time)

Recurrence: **Recurrent defect**
Who detected it?: **quality technician**

Defect S/R: **No**
Where was it detected? : **CM3**

How was it detected?: **by analysis**

How many parts ?: **1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::



1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Bechikh Wissal		• wissal.bechikh@avocarbon.com	wissal.bechikh@avocarbon.com	+216 58598711			Customer Quality	Supplier	Active
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **short circiut between soldering pads**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **(503-779-99-99)**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☑

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	0.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	25,318.00	0.00	0.00	5/20/2024	Supplier	
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	30,000.00	30,000.00	0.00	5/20/2024	Supplier	first the Pallet Number N° 175 , Batch number 2312071.
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding short circiut between soldering pads**

First contained shipment information: **first the Pallet secured with Number N° 175 , Batch number 2312071.**

How are the ok paletts identified?: **Orange NIDEC identiifcation**

How are the ok parts identified? :: Securing identification regadring short circuit PCB.pdf

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Display quality flash on CM3/4 area	Required	Supplier	5/20/2024	5/20/2024
QRQC meeting	Required	Supplier	5/20/2024	5/20/2024

2 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Creation Date: **5/20/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **5/21/2024**

Claim reference: **NMAP/551841/5/2024/1762**
Created by: **DUDEK Dominik**
Update of QR: **5/21/2024**

Status: **Closed**
Type: **C2 : Production claim**
Date of D4-D8: **8/8/2024**

CLAIM PPM: 0.00

D4-D8 evaluation score: 75
Update of D4-D8:

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

1-During the validation of automatic sodlering PCBA , we need to make the operation of soldering of PCBA mannually , the opeartor slight movement to solder the second point without clean the iron --> a llitle tin Fell down between the two soldering points
2-Operator of rework not concentrate and aware about the procedure "Retest all reworked parts"

HOW WAS THE DEFECT REPRODUCED ?

the opeartor slight movement to solder the second point without clean the iron --> a llitle tin Fell down between the two soldering points

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

Defect not properly detected due to visual control of short circuit

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment field
in case working with back up solution , updated the work instruction of mannuel soldering with mention the cleaning of iron each soldering points	hajer jafri	8/21/2024	8/21/2024	PH180 Soudure Etain manuelle CM3 (back up solution).p
Diplay procedure of prohibition any rework in the production line and the flow parts in case of rework	marwan haggui	8/21/2024	8/21/2024	PROCEDURE soudure etain ENg.pdf