

FINAL COMMENT LOG

Originating Office: AFS-110		Document Title/Description: MMEL A-320 Rev 31, Airbus SAS, A318, A319, A320, and A321 Series, All Models			POC and Phone Number: Mark Farrell, 206-231-3990		Suspense Date: 10/14/2024
Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response	
AED	06/25/24	IV	HoC	Updates to 23-42-01 omitted from HoC.	Add 23-42-01 to HoC for updated proviso.	Added 23-42-01 to HoC.	
AED	06/05/24	32-1	32-31-01	Issues with item resolved.	Reinstate item relief into draft to include recommended changes as well as listing all items into provisos that are considered inoperative.	Reinstated item relief into draft with changes.	
AED	06/05/24	78-9	78-31-01	Issues with item resolved.	Reinstate item relief into draft. Update item by moving Note 2 to a proviso and add a considered inoperative proviso.	Reinstated item relief into draft. Updated item by moving Note 2 to a proviso and adding a considered inoperative proviso.	
John J McDermott AFS-220-3 Concur with Comment	5/28/24	23-23 Pdf 93	23-73-03-04 Lavatory Smoke Detection System (Indication on PTP/FAP)	Policy Letter (PL31): Item remark missing information per PL 31 Policy section #7	Revise to include "Relief moved to XXXXX Revision XX" per PL 31.	Partially concur. Deleted reference subitems with "Relief moved" statement IAW PL-31 Policy item 7.	
John J McDermott AFS-220-3 Concur with Comment	5/28/24	23-23 Pdf 93	23-73-03-05 Drain Masts (Indication on PTP/FAP)	Policy Letter (PL31): Item remark missing information per PL 31 Policy section #7	Revise to include "Relief moved to XXXXX Revision XX" per PL 31.	Partially concur. Deleted reference subitems with "Relief moved" statement IAW PL-31 Policy item 7.	
John J McDermott AFS-220-3 Concur with Comment	5/28/24	23-25 Pdf 93	23-73-05 Prerecorded Announcem ent and Music Reproducer	Policy Letter (PL31): Item remark missing information per PL 31 Policy section #7	Revise to include "Relief moved to XXXXX Revision XX" per PL 31.	Partially concur. Deleted reference item with "Relief moved" statement IAW PL-31 Policy item 7.	
John J McDermott AFS-220-3 Concur with Comment	5/28/24	22-2 Pdf 59	22-10-07 Autopilot FMA Indications on PFD	Policy Letter (PL31): Item remark missing information per PL 31 Policy section #7	Revise to include "Relief combined with XXXXX (Relief Title) Revision X" per PL 31.	Partially concur. Deleted reference item with "Relief combined" statement IAW PL-31 Policy item 7.	

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
John J McDermott AFS-220-3 Concur with Comment	5/28/24	25-21 Pdf 145	25-60-12 Overwater Survival Kits	Policy Letter (PL31): Item remark missing information per PL 31 Policy section #7	Revise to include "Relief combined with XXXXX (Relief Title) Revision X" per PL 31.	Partially concur. Deleted reference item with "Relief combined" statement IAW PL-31 Policy item 7.
John J McDermott AFS-220-3 Concur with Comment	5/29/24	33-5 Pdf 310	33-20-02-01 All Cargo, Supernumerary/Courier Area Lighted Information Signs	Notice: "Supernumerary" now considered "authorized persons" on all cargo aircraft per Notice N8900.669	Revise to include "authorized persons" where appropriate	Concur. Updated subitem title IAW N8900.669.
Robert Laurion AFS-330	6/3/24	22-7	22-81-01 item 1)	Mod applicability was added and not indicated with change bars.	Recommend adding the change bars.	Concur. Added change bars as appropriate.
Robert Laurion AFS-330	6/3/24	23-8	23-42-01	Proviso was changed as reflected by change bars; however, the Highlights of Change, Page IV does not contain an Explanation of Change for 23-42-01.	Recommend adding 23-42-01 to the Highlights of Change, Page IV, Explanation of Change.	Concur. Updated HoC.
Robert Laurion AFS-330	6/3/24	28-45	28-40-09 item 5)	Question whether the dispatch condition and proviso for 5) since it is covered in 5)a).	If the condition and proviso for 5) is not needed, recommend removal.	Concur. Corrected typo. Dispatch condition only applies to subitem with model applicability.
Robert Laurion AFS-330	6/3/24	28-46	28-40-09 item 6)	Question whether the dispatch condition and proviso for 6) is need since it is covered in 6)a).	If the condition and proviso for 6) is not needed, recommend removal.	Concur. Corrected typo. Dispatch condition only applies to subitem with model applicability.
Robert Laurion AFS-330	6/3/24	34-16	34-40-13	This item was added to the MMEL; however, the Highlights of Change, Page VI, does not contain an Explanation of Change for 34-40-13.	Recommend adding 34-40-13 to the Highlights of Change, Page VI, Explanation of Change as new item.	Concur. Updated HoC.
AFS-800				No comments.		
Clement Chaurat Airbus	05/29/24	22-4	22-66-01	Should it be "a/c without eRudder Mod" or "all aircraft except A321neo XLR"?		For manual consistency, for this item, will retain use of Mod/MP applicability as opposed to model applicability.
Clement Chaurat Airbus	05/29/24	25-1	25-00-00	FYI this fault message is enabled by the installation of ELT DT (Mod 166219 / MP K32599), in case you would like to replace the if installed symbol by the Mod number.		Concur. Removed asterisks and added Mod applicability. However, removed 25-00-00 from MMEL. Will review again for R32. See subsequent comment for 25-00-00 1).

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Clement Chaurat Airbus	05/29/24	27-11	27-64-01	All A320-200 with sharklets (installed either via Mod 160500 or Mod 160080) have Mod 26334 or Mod 26335. So you can either delete Mod 26334 and Mod 26335 or replace by "With Mod 26334 or Mod 26335".		Concur. Corrected Mod applicability as recommended for without Mods 26334 and 26335.
Clement Chaurat Airbus	05/29/24	27-21	27-93-01 2)	"Except A321neo XLR" should be added since ELAC 2 is NO GO for XLR/eRudder.		Concur. Made correction to Mod applicability.
Clement Chaurat Airbus	05/29/24	27-24	27-94-01 1)b)	Add "A321 without eRudder". The MMEL project mentions "all without Mod. 163323 (eRudder)".		Concur. Made correction to Mod applicability.
Clement Chaurat Airbus	05/29/24	27-29	27-94-01 2)b)	It should be "A321 except A321neo XLR"		Concur. Made correction to Mod applicability.
Clement Chaurat Airbus	05/29/24	27-32	27-94-01 3)	As per SA00FM2300633, it should mention "SEC 3 (Aircraft without Mod. 163323 (eRudder)) since SEC 3 is removed on A/C with eRudder.		Concur. Added Mod applicability.
Clement Chaurat Airbus	05/29/24	27-33	27-94-02 1)a)	It should be "Aircraft without Mod 163323/ MP P20703 (eRudder)" because this update is related to eRudder and not XLR specifically		Removed model and added Mod applicability.
Clement Chaurat Airbus	05/29/24	27-33	27-94-02 1)b)	Should be "Aircraft with Mod 163323/ MP P20703 (eRudder).		Removed model and added Mod applicability.
Clement Chaurat Airbus	05/29/24	27-33	27-94-02 2)a)	Should be "Aircraft with Mod 163323/ MP P20703 (eRudder).		Removed model and added Mod applicability.
Clement Chaurat Airbus	05/29/24	27-33	27-94-02 2)b)	Should be "Aircraft with Mod 163323/ MP P20703 (eRudder).		Removed model and added Mod applicability.
Clement Chaurat Airbus	05/29/24	28-8	28-21-02 2)a)	Provisos updated to add "or is not installed" for FWD ACT		Revised provisos as recommended.
Clement Chaurat Airbus	05/29/24	28-13	28-25-03 3)b)	Provisos updated to add "or is not installed" for FWD ACT		Revised provisos as recommended.
Clement Chaurat Airbus	05/29/24	28-25	28-40-02 1)d)	Provisos updated to add "or is not installed" for FWD ACT		Revised provisos as recommended.
Clement Chaurat Airbus	05/29/24	28-41	28-40-06 3)h)	Provisos updated to add "or is not installed" for FWD ACT		Revised provisos as recommended.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Clement Chaurat Airbus	05/29/24	30-1 and 30-3	30-11-01 1) and 3)	The only difference between sub item 1) and sub-item 3) is the content of the (o) procedure: as mentioned on the MMEL Change project, the (o) procedure for 321neo XLR provides information to the flight crew regarding the applicable limitations in case of inadvertent icing conditions and severe ice accretion. This is additional information compared to the existing (o) procedure from sub-item 1). I just realized that the provisos are actually the same between sub-item 1) and sub-item 3). Therefore, there is may be no need to have two separate sub-items and both could be merged.		Updated model applicability for subitem 1) and removed subitem 3) as recommended.
Clement Chaurat Airbus	06/12/24	30-6 and 30-7	30-31-01	As a result of updated safety methodology, reconfigure item and update previously proposed relief to ensure there is no relief for the F/O and STBY Probe Heat Computers on the A321neo XLR.		Updated item relief to reflect that for the F/O and STBY Probe Heat Computers on the A321neo XLR.
Clement Chaurat Airbus	06/24/24	30-8 thru 30-11	30-31-02 30-31-03	What is the reason for duplicating items 30-31-02 Pitot Heaters and 30-31-03 Static Port Heaters for XLR and non-XLR? These items are unchanged for XLR.		Partially concur. The only difference between the two subitems for each item is that for the XLR takeoff with flaps in CONF 1A+F is prohibited where for all other models not having ETOC the restriction is for CONF 1+F. Reconfigured items to add model applicability within provisos, i.e. "Takeoff in CONF 1+F (CONF 1A+F for A321neo XLR) is prohibited...".
Clement Chaurat Airbus	06/12/24	30-12	30-31-04	As a result of updated safety methodology, update model applicability to ensure item relief is NO GO for A321neo XLR.		Added model applicability for all models except A321neo XLR..

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Clement Chaurat Airbus	06/24/24	32-1	32-31-01 2)	Typo in the applicability of sub-item 2): "A319neo/A320neo/A321neo with Mod 165148/MP J4604 and without Mod 171984/MP P22484"	Replace "A319neo/A320neo/A321neo with Mod 165148/MP J4604 and without Mod 171984/MP P22484" By "A319neo/A320neo/A321neo with Mod 165148/MP J4604 and without Mod 171984/MP P22484"	Concur. Adjusted Mod applicability as recommended.
Clement Chaurat Airbus	05/29/24	32-4	32-42-03 1)a)	It should be "Aircraft without.		Corrected Mod applicability.
Clement Chaurat Airbus	05/29/24	32-5	32-42-03 1)b)	highlight that the condition "with Mod 171984/ MP P22484" must apply to both: - A319neo/A320neo/A321neo with Mod 165148/ MP J4604 and - A319neo/A320neo/A321neo with Mod 170252/ MP J7041 (BSCU L4.11) Is it clear the way it is currently written? Or should it state "all with Mod 171984/ MP P22484" ?		Updated Mod applicability for clarity.
Clement Chaurat Airbus	05/29/24	32-6	32-42-03 1)c)	Typo.		Corrected typo.
Clement Chaurat Airbus	05/29/24	32-7	32-42-03 2)b)	Same comment as with 32-42-03 1)b).		Updated Mod applicability for clarity.
Clement Chaurat Airbus	05/29/24	32-8	32-42-03 2)c)	Typo.		Corrected typo.
Clement Chaurat Airbus	06/12/24	34-8	34-10-01 4)	Remove proposed ADR 2 relief for A321neo XLR as a result of updated safety methodology conclusions.		Updated item relief to reflect that for A321neo XLR, item is NO GO.
Clement Chaurat Airbus	06/12/24	34-8	34-10-01 5)	Remove proposed ADR 3 relief for A321neo XLR as a result of updated safety methodology conclusions.		Updated item relief to reflect that for A321neo XLR, item is NO GO.
Clement Chaurat Airbus	05/29/24	34-16	34-40-09	"P" is missing in front of MP number : P15323.		Corrected

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Clement Chaurat Airbus	06/12/24	34-18	34-42-01 1) and 2)	Update Notes with additional Mod applicability. Note is applicable to all aircraft except: - aircraft with EGPWS -006 (Mod. 155145 / P13063) or - aircraft with T3CAS (Mod 39146 / P10960 or Mod 152353 / P18041) or - aircraft with T2CAS Std3 (152920 / P12603)		Updated Notes with Mod applicability as recommended.
Clement Chaurat Airbus	05/29/24	78-9	78-31-01 1)	Typo.		Corrected typo.
Clement Chaurat Airbus	06/24/24	78-9	78-31-01 2)	Typo in the applicability of sub-item 2): "A319neo/A320neo/A321neo without Mod. 165148/MP J4604 or A319neo/A320neo/ A321neo with Mod 165148/MP J4604 and with Mod 171984/MP P22484"	Replace "A319neo/A320neo/A321neo with Mod. 165148/MP J4604 or A319neo/A320neo/ A321neo with Mod 165148/MP J4604 and with Mod 171984/MP P2248" By "A319neo/A320neo/A321neo without Mod. 165148/MP J4604 or A319neo/A320neo/ A321neo with Mod 165148/MP J4604 and with Mod 171984/MP P22484"	Concur. Adjusted Mod applicability as recommended.
Pete Moll United	6-21-24	22-6	22-76-01	In the "Item" title, the T.O. SURV pb-sw has a period after the "O", and should not be based on the Airbus MMEL and guidance. This should be listed without this period, such as: T.O SURV pb-sw (With Mod. 162728/ MP P20485)	Recommend removing the extra period after the "O" in Item for T.O Example: T.O SURV pb-sw (With Mod. 162728/ MP P20485)	Concur. Corrected typo to align item title with Airbus MMEL.
Pete Moll United	6-21-24	22-6	22-76-02	In the "Item" title, the T.O. SURV pb-sw has a period after the "O", and should not be based on the Airbus MMEL and guidance. This should be listed without this period, such as: T.O. SURV pb-sw OFF Light (With Mod. 162728/ MP P20485)	Recommend removing the extra period after the "O" in Item for T.O Example: T.O SURV pb-sw OFF Light (With Mod. 162728/ MP P20485)	Concur. Corrected typo to align item title with Airbus MMEL.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Pete Moll United	6-21-24	25-1	25-00-00 1)	For this Class II Mx message item, Fault(s) indicated by ELT, this has been given a category D repair interval. All other Class II Mx message items in the MMEL are either Cat C, or Cat A 10-days. Recommend that this be changed to a Cat C repair interval.	For this Class II Mx message item, Fault(s) indicated by ELT, this has been given a category D repair interval. All other Class II Mx message items in the MMEL are either Cat C, or Cat A 10-days. Recommend that this be changed to a Cat C repair interval.	Partially concur. The relief is for aircraft with the Mod that installs ELT-DT. Further research into the item shows that item should have proviso along with associated (M) Procedure for aircraft with Mod. Will remove relief from R31 for now until additional justification can be obtained, then reintroduce for subsequent R32.
Pete Moll United	6-21-24	25-20	25-60-08	Within MMEL Rev.29, there was an item of relief for Flashlights that aligned with PL-125 (No Passengers are carried proviso set), then, with MMEL Rev.30, this relief was removed, and not certain why? Recommend adding a third proviso set for this Flashlight item that would pick up the relief that was previously deleted in MMEL Rev.29, and then would align with PL-125 as well. If this is not possible to add this in this revision, then could this be considered for the next MMEL revision?	Within MMEL Rev.29, there was an item of relief for Flashlights that aligned with PL-125 (No Passengers are carried proviso set), then, with MMEL Rev.30, this relief was removed, and not certain why? Recommend adding a third proviso set for this Flashlight item that would pick up the relief that was previously deleted in MMEL Rev.29, and then would align with PL-125 as well. If this is not possible to add this in this revision, then could this be considered for the next MMEL revision?	Concur. Exceptions for flight without passengers (PL-125) were inadvertently omitted with R30 as a result of making changes to relief per the PL-132.
Pete Moll United	6-21-24	25-20	25-60-09	Proviso step b), there appears to be an extra space before the word 'Location'. Recommend removing the extra space here.	Proviso step b), there appears to be an extra space before the word 'Location'. Recommend removing the extra space here.	Concur. Corrected typo.
Pete Moll United	6-21-24	25-20	25-60-09	Within MMEL Rev.29, there was an item of relief for Megaphones that aligned with PL-125 (No Passengers are carried proviso set), then, with MMEL Rev.30, this relief was removed, and not certain why? Recommend adding a second proviso set for this Megaphone item that would pick up the relief that was previously deleted in MMEL Rev.29, and then would align with PL-125 as well. If this is not possible to add this in this revision, then could this be considered for the next MMEL revision?	Within MMEL Rev.29, there was an item of relief for Flashlights that aligned with PL-125 (No Passengers are carried proviso set), then, with MMEL Rev.30, this relief was removed, and not certain why? Recommend adding a third proviso set for this Flashlight item that would pick up the relief that was previously deleted in MMEL Rev.29, and then would align with PL-125 as well. If this is not possible to add this in this revision, then could this be considered for the next MMEL revision?	Concur. Exceptions for flight without passengers (PL-125) were inadvertently omitted with R30 as a result of making changes to relief per the PL-132.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Pete Moll United	6-21-24	32-1	32-31-01	This item for the Landing Gear Control and Interface Unit No. 2 (LGCIU 2) is now showing as "Deleted". This was not discussed as such in the FOEB meeting. Recommend adding this item back in here, and then also make all of the systems that are affected when this is on MEL, as "Considered Inoperative" items.	This item for the Landing Gear Control and Interface Unit No. 2 (LGCIU 2) is now showing as "Deleted". This was not discussed as such in the FOEB meeting. Recommend adding this item back in here, and then also make all of the systems that are affected when this is on MEL, as "Considered Inoperative" items.	Concur. Reinstated relief as recommended.
Pete Moll United	6-21-24	32-6	32-42-03 1) c)	In the MMEL Item, There is a question mark ? after the mod number 171984. Replace the question mark with a slash, example: A319neo/A320neo/ A321neo with Mod 165148/ MP J4604 or Mod 170252/ MP J7041 (BSCU L4.11) and without Mod 171984/ MP P22484	In the MMEL Item, There is a question mark ? after the mod number 171984. Replace the question mark with a slash, example: A319neo/A320neo/ A321neo with Mod 165148/ MP J4604 or Mod 170252/ MP J7041 (BSCU L4.11) and without Mod 171984/ MP P22484	Concur. Corrected typo.
Pete Moll United	6-21-24	32-8	32-42-03 2) c)	In the MMEL Item, There is a question mark ? after the mod number 171984. Replace the question mark with a slash, example: A319neo/A320neo/ A321neo with Mod 165148/ MP J4604 or Mod 170252/ MP J7041 (BSCU L4.11) and without Mod 171984/ MP P22484	In the MMEL Item, There is a question mark ? after the mod number 171984. Replace the question mark with a slash, example: A319neo/A320neo/ A321neo with Mod 165148/ MP J4604 or Mod 170252/ MP J7041 (BSCU L4.11) and without Mod 171984/ MP P22484	Concur. Corrected typo.
Pete Moll United	6-21-24	46-1	46-20-01 1), 2), 3), 4)	This section and items are not in alignment with PL-121. Would there be an opportunity of changing all of this section and items, to align with PL-121? If this is an option to do, then the PL table at the beginning of this MMEL needs to also be updated. If not, then could this be considered in the next revision?	This section and items are not in alignment with PL-121. Would there be an opportunity of changing all of this section and items, to align with PL-121? If this is an option to do, then the PL table at the beginning of this MMEL needs to also be updated. If not, then could this be considered in the next revision?	Concur. However, will consider recommendation for R32.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Pete Moll United	6-21-24	52-7	Proposed possible new item 52-50-04	Would there be a opportunity to add new MMEL relief for the "Installed Physical Secondary Barrier (IPSB)"? This would be the same/similar to what is being proposed by Boeing for the 737MAX draft MMEL Rev.6. The example would be like, or similar to this: Cat C relief: (O) May be inoperative provided: a) Barrier is secured in the fully stowed position, and b) Alternate procedures are established and used. (M)(O) May be inoperative provided: a) Barrier is removed, and b) Alternate procedures are established and used. Cat D relief: (O) May be inoperative provided: a) Operations do not require its use, and b) Barrier is secured in the fully stowed position. (M) May be inoperative provided: a) Operations do not require its use, and b) Barrier is removed. If this is not an option for this revision, could this be considered for the next MMEL revision?	Would there be a opportunity to add new MMEL relief for the "Installed Physical Secondary Barrier (IPSB)"? This would be the same/similar to what is being proposed by Boeing for the 737MAX draft MMEL Rev.6. The example would be like, or similar to this: Cat C relief: (O) May be inoperative provided: a) Barrier is secured in the fully stowed position, and b) Alternate procedures are established and used. (M)(O) May be inoperative provided: a) Barrier is removed, and b) Alternate procedures are established and used. Cat D relief: (O) May be inoperative provided: a) Operations do not require its use, and b) Barrier is secured in the fully stowed position. (M) May be inoperative provided: a) Operations do not require its use, and b) Barrier is removed. If this is not an option for this revision, could this be considered for the next MMEL revision?	Concur. However, will consider recommendations for R32.
Pete Moll United	6-21-24	71-2	71-00-00 2)	Within the Remarks or Exceptions and the Note for this item, it appears there are numbers in this Note, (possibly inadvertently added) that should not be in here? Example: NOTE: Dispatch with maintenance status messages displayed on ECAM is 79-35-04 permitted without CFDS interrogation.	Recommend correcting this Note to remove the numbers that should not be in here, example: NOTE: Dispatch with maintenance status messages displayed on ECAM is permitted without CFDS interrogation.	Concur. Typo made in draft document. No change from R30 for this subitem.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Pete Moll United	6-21-24	78-9	78-31-01 1), 2)	This item for the REVERSER CTL FAULT Caution on ECAM EWD is now showing as "Deleted". This was not discussed as such in the FOEB meeting. Recommend adding this item back in here, and then also recommend that the associated Thrust Reverser is "Considered Inoperative", such as was recommended in the FOEB meeting as well.	This item for the REVERSER CTL FAULT Caution on ECAM EWD is now showing as "Deleted". This was not discussed as such in the FOEB meeting. Recommend adding this item back in here, and then also recommend that the associated Thrust Reverser is "Considered Inoperative", such as was recommended in the FOEB meeting as well.	Concur. Reinstated relief as recommended.
Delta	6-4-2024	34-16	34-40-13	New item is being added to MMEL but not listed on Highlights of Change section.	Recommend adding item to Highlights of Change section	Concur. Corrected with new item added to HoC.
Gary Jackman Alaska Airlines	06/24/2024	23-8	23-42-01	Intent of this Ground External Horn relief item is to ensure avionics ventilation is monitored only when both conditions (1) aircraft is on ground and (2) aircraft electrical network is supplied, are met. Reference Airbus A320 MMEL 23-40-01 DU Ops. Proc. ID 00008960.0001001. Remarks and Exceptions should state when monitoring is required. Use of word "the" should be removed from Remarks and Exceptions language.	Recommend updating MMEL Remarks and Exceptions language as follows: "(O) May be inoperative provided avionics equipment ventilation is monitored in cockpit while aircraft is on ground and aircraft electrical network is supplied."	Concur. Modified proviso to include provisos listed in OEM recommended (O) Procedure.
Gary Jackman Alaska Airlines	06/24/2024	24-23	24-30-09 Item 2	Remove word "the" from Remarks and Exceptions	Delete word "the" so that Remarks and Exceptions for item 24-30-0 item 2) reads as follows: "May be inoperative provided ground external horn is considered inoperative."	Concur. Modified proviso as recommended.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	06/24/2024	25-1	25-00-00-1)	New FAA MMEL Rev. 31 item 25-00-00-1) appears to be based on Airbus MMEL guidance item 25-00-1 DU dispatch item ID 00026331.0001001. There are a few items for MAINTENANCE messages displayed on the STATUS SD page that have proviso condition(s) in both FAA MMEL and Airbus MMEL guidance as a condition of deferral relief (see CH 71 items). Airbus MMEL guidance indicates this ELT fault indicates may have a condition of deferral as listed in a NOTE prior to the start of the deferral guidance. This Airbus MMEL guidance NOTE states a spurious (false and not actually valid) fault should be disregarded provided it was confirmed false by troubleshooting within the previous 28 days. This Airbus guidance lists a Trouble Shooting Manual (TSM) reference which indicates an (M) procedure for FAA MEML deferral relief may be warranted. While this commentor fully understands this is embedded in Airbus guidance a NOTE, the listing of this guidance is presented as a condition of deferral allowance. This NOTE presentation may warrant further review to determine if this needs to be included in FAA MMEL item relief as a condition of deferral.	Consideration may be needed to change Remarks and Exceptions language to something similar to: “(M) May displayed provided fault is confirmed false by troubleshooting with previous 28 days.”	Concur. However, as the commenter has described, this proposed new item on the FAA MMEL should be researched further to ensure accuracy and that it properly complies with FAA policy. Further justification should be obtained. Thus, since R31 is a revision primarily being worked to list MMEL relief for new and revised items related to the A321neo XLR, 25-00-00 is being removed from R31 and may be reintroduced for the subsequent R32, which is also currently being developed.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	06/24/2024	25-26	25-61-01-6)	(1) FAA A320 Family MMEL Rev. 30 lists this LF-ULB item 25-61-01-3) for Category D relief and contains an “or missing” allowance. While it is understood that FAA MMEL PL-120 Rev. 4 did not contain an “or missing” provision in the Remarks and Exception language for Category D relief, there is no United States CFR that requires a Low-Frequency Underwater Locator Beacon/Device (LF-ULB / LF-ULD) to be installed. Therefore, an “or missing” statement should be added to the Category D relief item Remarks and Exception just like is already included in the Category C relief item. (2) For LF-ULB Category C MMEL relief, preference is to use PL-125 language and delete the drafted “One or more” portion and simply state “May be inoperative or missing.”	Add “or missing” to CAT D item and delete “one or more” from CAT C item as follows: 25-61-01-6) Low Frequency Underwater Locator Beacon (LF-ULB) CAT D - INS “-“ - REQ “-“ May be inoperative or missing provided operations do not require its use.” CAT C - INS “-“ - REQ 0 May be inoperative or missing.	Concur. Modified provisos as recommended.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	06/24/2024	Intro page XIII as Compared Throughout Individual Chapter Listing Pages	Throughout	Items associated with FAA MMEL PL-125 have either been inadvertently deleted or not added in previous FAA A320 MMEL Revisions. This creates a disparity between the FAA A320 Family MMEL "FAA MMEL Policy Application Record" (at the beginning of the MMEL in Pages VIII to XIII) vs. what has actually been incorporated into the FAA A320 Family MMEL. Items listed in FAA MMEL PL-125 need to be added into the FAA A320 MMEL to provide a balance between what the FAA MMEL Policy Applications Record states as being accomplished "as applicable," and what is listed in the chapter listings for item relief. The following PL-items are already listed in FAA A320 Family MMEL Rev. 31 for PL-125 equipment relief without passengers: - Door Slides – 25-61-02 - Interior Emergency Lighting – 35-50-09 - Interiors Emergency Lighting – 35-50-09 - Escape Path Markings – 35-50-03 - Flight Attendant Seats – 25-22-01 - Printed Supp. Safety Info. – 25-90-01 The following items need to be added into FAA A320 Family MMEL Rev. 31 to provide PL-125 equipment relief without passengers: - Megaphones, - Exit Marking, and - Flashlights & Holders (cabin) While it is fully understood that it is not reasonable to list all affected sequence items numbers of the associated PL in the MMEL Policy Application Record, there may be benefit to listing the main "Affected Item Sequence Numbers" associated with PL-125 in the Application Record. This could be accomplished in manner similar to item listed for PL-132 on same page number XIII.	(1) Add affected Item numbers to PL-125 Application Record, and (2) Add the following items to Rev. 31 to fully align FAA A320 Family MMEL "FAA MMEL Policy Application Record" and FAA MMEL PL-125, and 25-60-09 Item 2 (under main 25-60-09 item listing) Megaphones CAT C -- INS "-" -- REQ 0 (O) May be missing or inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used. 35-50-10 Exit Markings CAT C -- INS "-" -- REQ 0 (O) May be missing or inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used. 25-60-08 Item 3 (under main 25-60-08 item listings) Flashlights and Holders (Cabin) CAT C -- INS "-" -- REQ 0 (O) May be missing or inoperative provided: a) No passengers are carried, b) A maximum of 19 persons are carried as authorized by 14 CFR for non-passenger-carrying operations, and c) Alternate procedures are established and used. <i>(Please note, due to assumed potential requirements for pilots to possess a flashlight during flight, title of this item specifically only contains a "(cabin)" identification.)</i>	Concur. Listed all items affected by PL-125 on PL application record as recommended.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	06/24/2024	27-8	27-51-01-1)-a) and 27-51-01-1)-b)	(1) In opening statement of each Flap Channel MMEL 27-51-01-1) item a) and b), the acronym "SFCS" is not used in Airbus MMEL 27-51-01A guidance DU dispatch item ID 00008340.0001001 and 00008340.0001002. Airbus guidance uses acronym "SFCC" for these MMEL items and states "SFCC 2 flap channel may be inoperative provided....(list of provisos)." (2) Airbus guidance for these items only recommends SFCC 1 "flap" WTB to be tested at MEL application time and then once each flight day. FAA MMEL relief needs to be updated show only "flap" WTB testing is required, and an every flight inspection is not recommended by Airbus. Suggest using existing FAA MMEL "before next flight and then once each flight day" language to align to Airbus recommendation. (3) Proviso containing "minimum idle on ground" does not have the word "function" in the Airbus MMEL guidance or in FAA MMEL item 73-20-03. Word "function" should be removed from FAA MMEL proviso. (4) Proviso "Spoiler surfaces 2 and 4 operate normally" is not a requirement of Airbus MMEL guidance. If this is an added mandate based on CFR 14 requirements, then it is recommended to add this to the end of any required Airbus guidance provisos. (5) Airbus MMEL guidance for these items drive to DU ops proc ID 00009044.0001001 which states "For aircraft with RNP AR capability, <i>RNP AR operations are not permitted.</i>" When Airbus publishes this MMEL ops. proc. limitation, FAA MMEL provisos typically contain a proviso "Approach minimums do not require its use." Consideration to add this proviso to this FAA MMEL is suggested. (6) There is a wide variance of proviso language and proviso listing sequence between the FAA MMEL and the Airbus MMEL guidance This wide variance between FAA MMEL and Airbus MMEL creates significant difficulties for both operators and local FAA (CMO) administrators during the MEL update and approval process. Stronger alignment between FAA MMEL and Airbus MMEL guidance for proviso both language and listing sequence is greatly needed.	Recommend re-word, re-sequence, and add new proviso (for approach minimums) into Remarks and Exceptions for each MMEL item as listed below: 27-51-01-1)-a) (M)(O) SFCC 2 may be inoperative provided: a) SFCC 2 Flap Channel is deactivated, b) Slats and flaps operate normally on SFCC 1, c) SFCC 1 flap WTB is verified to operate normally before next flight and then once each flight day, d) All ELACs, SECs, LGCIUs, RAs, FACs, and ADIRs are operate normally, e) Minimum idle on ground is considered inoperative, and f) Approach minimums do not require its use. 27-51-01-1)-b) (M)(O) SFCC 2 may be inoperative provided: a) SFCC 2 Flap Channel is deactivated, b) OAT is below ISA+35 °C c) Slats and flaps operate normally on SFCC 1, d) SFCC 1 flap WTB is verified to operate normally before next flight and then once each flight day, e) All ELACs, SECs, LGCIUs, RAs, FACs, and ADIRs are operate normally, f) Minimum idle on ground is considered inoperative, and f) Approach minimums do not require its use.	Concur. However, will consider these recommendations for R32. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	06/24/2024	27-9	27-51-01-1)-c)	Item 27-51-01-1)-c) is a new item with many similarities to item 27-51-01-1)-b) listed above. This new “-c)” item does not have Airbus MMEL guidance that is readily viewable to this commenter, but appears to be very similar in nature to “-b).” Because of this very similar nature between “-b)” and “-c)” items, it is recommended to review Airbus MMEL guidance to ensure stronger alignment between FAA MMEL and Airbus MMEL guidance.	See recommendation for 27-51-01-1)-b) above and apply same provisos re-wording and proviso re-sequencing into Remarks and Exceptions as needed.	Concur. However, will consider recommendations for R32. 27-51-01 1) c) applies to aircraft with eRudder. The only difference with this subitem and 27-51-01 1) b) is that with eRudder, the FACs are replaced with FMGCs. But with this, the item is still affected similarly as per the previous comments for this item.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	27-9	27-51-01-2)-a)	(1) In opening statement of Slat Channel MMEL 27-51-01-2) item a), acronym "SFCS" is not used in Airbus MMEL 27-81-01A guidance DU dispatch item ID 00008341.0001001 Airbus guidance uses acronym "SFCC" for these MMEL items and states "SFCC 2 slat channel may be inoperative provided....(list of provisos)." (2) Airbus guidance for these items only recommends SFCC 1 "slat" WTB to be tested at MEL application time and then once each flight day. FAA MMEL relief needs to be updated show only "slat" WTB testing is required, and an every flight inspection is not recommended by Airbus. Suggest using existing FAA MMEL language "before next flight and then once each flight day" to align to Airbus recommendation. (3) Relief for this item is listed as item number 27-51-01-2) in FAA MMEL and is listed as item number 27-81-01 in Airbus MMEL guidance. This variance in numbering between FAA and Airbus publications creates confusion for operators while developing and maintaining MEL relief and for local FAA CMO administrators when approving an operator's MEL. Renumbering of this Slat Channel item will also better align to existing relief item 27-81-01 for Slat WTB Solenoid, which will need to move to item listing number 27-81"-02" when Slat Channel relief is moved, and will align to FAA MMEL guidance. (4) Airbus MMEL guidance for this item (DU ops proc ID 00009045.0001001) states "For aircraft with RNP AR capability, <i>RNP AR operations are not permitted.</i>" When Airbus publishes this MMEL ops. proc. limitation, FAA MMEL provisos typically contain a proviso "Approach minimums do not require its use." Consideration to add this proviso to this FAA MMEL is suggested. (5) This wide variance between FAA MMEL and Airbus MMEL creates significant difficulties for both operators and local FAA (CMO) administrators during the MEL update and approval process. Stronger alignment between FAA MMEL and Airbus MMEL guidance for proviso both language and listing sequence is greatly needed.	Renumber, re-word, re-sequence, and add new proviso (for approach minimums) for SFCC Slat Channel FAA MMEL relief as follows: 27-81-01-a) SFCC Slat Channel CAT C – INS 2 – REQ 1 (M)(O) SFCC 2 Slat Channel may be inoperative provided: a) SFCC 2 Slat Channel is deactivated, b) Slats and flaps operate normally on SFCC 1, c) SFCC 1 slat WTB is verified to operate normally before next flight and then once each flight day, d) All ELACs, SECs, LGCIUs, RAs, FACs, and ADIRs are operate normally, and e) Takeoff is not performed in 1+F. and f) Approach minimums do not require its use.	Concur. However, will consider these recommendations for R32. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	27-10	27-51-01-2)-b)	Item 27-51-01-2)-b) is a new item with many similarities to item 27-51-01-2)-a) listed above. This new “-b)” item does not have Airbus MMEL guidance that is readily viewable to this commenter, but appears to be very similar in nature to “-a).” Because of this very similar nature between “-a)” and “-b)” items, it is recommended to review Airbus MMEL guidance to ensure stronger alignment between FAA MMEL and Airbus MMEL guidance. It is also recommended to align numbering of FAA MMEL and Airbus MMEL guidance.	See recommendation for 27-51-01-2)-a) above and apply same item re-numbering, proviso re-wording, proviso re-sequencing, and additional proviso (for approach minimums) into Remarks and Exceptions as needed.	Concur. However, will consider these recommendations for R32.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
	6/24/24	27-10	27-51-02	(1) Airbus MMEL guidance for this item only recommends SFCC 1 “flap” WTB to be tested at MEL application time and then once each flight day. FAA MMEL relief needs to be updated show only “flap” WTB testing is required, and an every flight inspection is not recommended by Airbus. Suggest using existing FAA MMEL language “before next flight and then once each flight day” to align to Airbus recommendation. (2) Airbus MMEL guidance for item 27-51-02 (DU ops proc ID 00020759.0001001) states “For aircraft with RNP AR capability, <i>RNP AR operations are not permitted.</i>” When Airbus publishes this MMEL ops. proc. limitation, FAA MMEL provisos typically contain a proviso “Approach minimums do not require its use.” Consideration to add this proviso to this FAA MMEL is suggested. Addition of this proviso provides reasoning for the existing “(O)” in this item. (3) Opening statement in Remarks and Exception should be re-worded for better alignment to Airbus MMEL guidance. This alignment will greatly help both operators during MEL development and maintenance, and for local FAA (CMO) administrators during the MEL update and approval process.	Recommending updating item 27-51-02 Remarks and Exceptions as follows: (M)(O) One or two solenoids associated with SFCC 2 may be inoperative provided: a) SFCC 1 flap WTB is verified to operate normally before next flight and then once each flight day, and b) Approach minimums do not require its use.	Concur. However, will consider these recommendations for R32. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it’s current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	27-16	27-81-01	(1) See above comment on item 27-51-01-2)-b) to renumber this item as item 27-81-02. This renumbering is needed to prevent variance in numbering between FAA and Airbus publications which creates confusion for operators while developing and maintaining MEL relief and for local FAA CMO administrators when approving an operator's MEL. (2) Airbus guidance for these items only recommends SFCC 1 “slat” WTB to be tested at MEL application time and then once each flight day. FAA MMEL relief needs to be updated show only “slat” WTB testing is required, and an every flight inspection is not recommended by Airbus. Suggest using existing FAA MMEL language “before next flight and then once each flight day” to align to Airbus recommendation	Re-number, reword, and re-sequence Slat Wing Tip Brakes Solenoid as recommended below: 27-81-01 Slat Wing Tip Brakes Solenoid CAT C – INS 4 – REQ 0 (M)(O) One or two solenoids associated with SFCC 2 may be inoperative provided: a) SFCC 1 slat WTB is verified to operate normally before next flight and then once each flight day, and b) Approach minimums do not require its use.	Concur. However, will consider these recommendations for R32.
Gary Jackman Alaska Airlines	6/24/24	32-1	32-31-01	Relief associated with Landing Gear Control and Interface Unit No. 2 (LGCIU 2) has been deleted from FAA MMEL Rev. 31 without a clear understanding why. This LGCIU 2 deferral relief remains the Airbus MMEL Guidance. There were five versions of this FAA MMEL relief in Rev. 30. MMEL relief for LGCIU 2 needs to be reinstated in Rev. 31 or reasoning provided why this relief is being deleted from the FAA MMEL while relief remains in Airbus MMEL guidance.	Reinsert FAA MMEL relief for LGCIU 2 in Rev. 31 for all five mod. variants.	Concur. Reinstated item relief into draft with changes.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	32-4 to 32-8	32-42-03 All mod-variants for Channel 1, System 1, Channel 2, and System 2	Updated FAA MMEL relief contains language that is not used in Airbus MMEL guidance for BSCU relief items. FAA MMEL item relief uses phrasing “Channel / System” in both item titles and item provisos. In Airbus MMEL guidance, BSCU item relief only states “Channel” or “System” depending on mod-variant. There is never a usage of both “Channel” and “System” within the same Airbus MMEL BSCU guidance. Airbus MMEL BSCU guidance for DU items 00007739.0001001, .0002001, .0003001, and .0004.0001 do not contain a proviso to have landing gear remain extended for 1 minute after takeoff. Airbus MMEL guidance for these above listed DU's do not contain a listing for an (O) that would drive an Ops. Proc. for a process to keep the gear extended or what needs to be accomplished if an emergency procedure needs to be accomplished during this critical flight time. There is a significant variance between FAA MMEL relief item language and Airbus MMEL guidance language for BSCU deferral relief. This variance creates significant confusion for both operator and local FAA CMO administrators while developing and approving operator MEL relief. Better alignment between FAA MMEL and Airbus MMEL guidance language is needed before further changes to BSCU deferral relief is accomplished.	Recommend no changes to BSCU relief in Rev. 31 until all commentors have applicable time to submit proposals to ensure proper alignment between FAA MMEL relief and Airbus MMEL guidance relief.	The primary purpose for revision to this item is to ensure correct Mod/model applicability for aircraft having certain BSCU Standards and to relieve some of the restrictions for aircraft with newer BSCU standards installed. Further revision to this item will be considered for R32. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	34-15	34-38-01	Relief for SBAS Landing System (SLS) is listed as item number 34-38-01 in FAA MMEL and is listed as item number 34-30-07 in Airbus MMEL guidance. This variance in numbering between FAA and Airbus publications creates confusion for operators while developing and maintaining MEL relief and for local FAA CMO administrators when approving an operator's MEL. Both FAA and Airbus numbering for this relief item need to align in order to prevent confusion. Delete word "the" from Remarks and Exception language in listing of the Category D relief.	Recommend changing FAA MMEL item number and Remarks and Exception language as follows: "34-30-07 CAT C – INS 2 – REQ 0 One May be inoperative CAT D – INS 2 – REQ 0 (O) One or both may be inoperative provided approach procedures are not based on SLS." Please note: CAT C relief was included in the above recommended change simply due to associated main item number change. There are no recommendations to change Remarks and Exception language for the CAT C item.	Concur. Removed the "the's" from proviso. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	34-16	34-40-13	FAA MMEL item 34-40-13 is a new item for ATSAW Function. In Airbus MMEL guidance this item is listed as number 34-40-09. Variance in numbering between FAA and Airbus publications creates confusion for operators while developing and maintaining MEL relief and for local FAA CMO administrators when approving an operator's MEL. Both FAA and Airbus numbering for these relief items need to align in order to prevent confusion. Item number 34-40-09 is already in use in the FAA MMEL for ROW/ROP relief. Since Airbus MMEL guidance lists this item as 34-40-10, FAA MMEL numbering for ROW/ROP should change to 34-40-10. Item number 34-40-10 is already in use in the FAA MMEL for ROW/ROP pb-sw OFF Light. Since Airbus MMEL guidance lists this item as 34-01-03-01, FAA MMEL numbering for ROW/ROP pb-sw OFF light should change to 34-01-03-01 (or 34-01-03 item a) if forth ATA code number sequence "-01" is not used in FAA MMEL publications). Since current FAA MMEL 34-40-11-1), 34-40-11-2) items on this page are associated with the above ROW/ROP and since Airbus MMEL guidance for these items is listed as 34-01-03-02A and 34-01-03-02B, then FAA MMEL numbering should change for these items to 34-01-03-02A and 34-01-03-02B (or 34-01-03-b) and 34-01-03-c) if forth ATA code number sequence "-01" is not used in FAA MMEL publications). Since current FAA MMEL 34-40-12 for RWY COND Rotary Selector is listed in Airbus MMEL guidance as number 34-40-11, then FAA MMEL numbering should change for this item to 34-40-11.	Renumber all items listed in Rev. 31 draft page 34-16 to ensure FAA MMEL and Airbus MMEL guidance aligns as follows: 34-01-03-a) *** ROW/ROP pb-sw OFF Light CAT D – INS 1 – REQ 0 (O) May be inoperative 34-01-03-b) *** ROW/ROP pb-sw OFF Position CAT C – INS 1 – REQ 0 (O) May be inoperative 34-01-03-c) *** ROW/ROP pb-sw ON Position CAT D – INS 1 – REQ 0 May be inoperative provided ROW/ROP is considered inoperative. 34-40-09 *** ATSAW CAT D – INS 1 – REQ 0 May be inoperative 34-40-10 *** Runway End Overrun Warning/Runway End Overrun Protection (ROW/ROP) CAT D – INS 1 – REQ 0 May be inoperative 34-40-11 *** RWY COND Rotary Selector CAT D – INS 1 – REQ 0 May be inoperative provided ROW/ROP is considered inoperative.	Concur. However, will consider these recommendations for R32. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Gary Jackman Alaska Airlines	6/24/24	36-25	36-22-18-3)	On previous page 36-24 for FAA MMEL item 36-22-18-2), an “(“ was added because it was missing in Rev. 30 on the “(M)” listing. Item 36-22-18-3) on page 36-25 is also missing the “(“ on the “(M)” listing.	Add “(“ in Remarks and Exception for item 36-22-18-3) on page 36-25 to fully show “(M)”.	Concur. Corrected typos.
Gary Jackman Alaska Airlines	6/24/24	78-9	78-31-01	Relief associated with REVERSER CTL FAULT Caution on ECAM EWD has been deleted from FAA MMEL Rev. 31 without a clear understanding why. This deferral relief is still listed in Airbus MMEL guidance 78-09-01 as DU dispatch item ID items 00016199.0001001, .0002001, and .0005001. REVERSER CTL FAULT deferral relief needs to be reinstated in the FAA MMEL. Variance in numbering between FAA and Airbus publications creates confusion for operators while developing and maintaining MEL relief and for local FAA CMO administrators when approving an operator's MEL. ECAM Alert REVERSER CTL FAULT deferral relief needs to be re-listed as main item number 78-09-01 for alignment between FAA MMEL and Airbus MMEL guidance. MMEL relief for REVERSER CTL FAULT Caution on ECAM EWD needs to be reinstated in Rev. 31 or reasoning provided why this relief is being deleted from the FAA MMEL while relief remains in Airbus MMEL guidance.	Reinsert REVERSE REVERSER CTL FAULT Caution on ECAM EWD MMEL relief as item number 78-09-01.	Concur. Reinstated item relief into draft with changes. Note: The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Tim.Kane JetBlue	7/11/22	25-20	25-60-09	This item was deleted in error from R30. C / - / 0 (O) May be inoperative or missing provided: a) No passengers are carried, b) A maximum of 19 persons authorized by 14 CFR for non-passenger-carrying operations are carried, and c) Alternate procedures are established and used. Megaphones: PL-132 combines PLs 43, 47, 73, and 75 regarding emergency equipment. It does not eliminate the remarks or exceptions provided by PL-125 Equipment Relief without Passengers. In this case PL-132 would add a new set of exceptions not eliminate the existing from PL-125. It is imperative that PL-125 remarks or exceptions are retained. Providing MMEL relief for these items allows operators the ability to position aircraft to another location and still carry cargo, crew members and other authorized persons I.A.W. 14CFR as referenced in PL-125 In addition, R29 correctly indicated the number required for dispatch in column 3 per 14CFR121.309 (f) Megaphones. Each passenger-carrying airplane must have a portable battery-powered megaphone or megaphones readily accessible to the crewmembers assigned to direct emergency evacuation, installed as follows: (1) One megaphone on each airplane with a seating capacity of more than 60 and less than 100 passengers, at the most rearward location in the passenger cabin where it would be	C / - / 0 (O) May be inoperative or missing provided: a) No passengers are carried, b) A maximum of 19 persons authorized by 14 CFR for non-passenger-carrying operations are carried, and c) Alternate procedures are established and used. 1) Passenger Configuration D / - / 2 Any in excess of those required by 14 CFR may be inoperative or missing provided: a) Inoperative megaphone is removed from the passenger cabin, b) Associated placard is removed or obscured, and c) Required distribution is maintained. 2) Cargo Configuration D / - / 0 May be inoperative or missing.	Concur. Reinstated inadvertently removed relief for non-passenger carrying operations and cargo configuration.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
				readily accessible to a normal flight attendant seat. However, the Administrator may grant a deviation from the requirements of this subparagraph if he finds that a different location would be more useful for evacuation of persons during an emergency. (2) Two megaphones in the passenger cabin on each airplane with a seating capacity of more than 99 passengers, one installed at the forward end and the other at the most rearward location where it would be readily accessible to a normal flight attendant seat. Prior response from FCL_MMEL_A-320_Rev-30 Non Concur. Will consider for Rev 31 when proposal is sent		
Tim.Kane JetBlue	06/13/24	32-1	32-31-01	LGCIU 2- Deleted in error.	Restore MMEL item(s) 32-31-01 1), 2), 3), 4), 5)	Partially concur. Reinstated item relief into draft with changes.
Tim.Kane JetBlue	06/13/24	32-1	32-31-02	Landing Gear Retraction System (Except A321neo XLR) no relief for XLR	Some explanation for this "(Except A321neo XLR)" is needed because at some point an XLR aircraft will need to be repositioned with gear down.	Concur. However, the A321neo XLR Revenue Flight with Landing Gear Down (RFLGD) program with AFM Supplement will not be certified until after type certification. With type certification and approval of the RFLGD program, this restriction for A321neo XLR may be removed with R32.
Tim.Kane JetBlue	06/13/24	32-1	32-33-01	Landing Gear Gravity Extension System (Except A321neo XLR)- no relief for XLR	Some explanation for this "(Except A321neo XLR)" is needed because at some point an XLR aircraft will need this relief	Concur. However, the A321neo XLR Revenue Flight with Landing Gear Down (RFLGD) program with AFM Supplement will not be certified until after type certification. With type certification and approval of the RFLGD program, this restriction for A321neo XLR may be removed with R32.
Tim.Kane JetBlue	06/13/24	78-9	78-31-01	REVERSER CTL FAULTCaution on ECAM EWD- Deleted	Restore MMEL item(s) 78-31-01 1), 2)	Concur. Reinstated item relief into draft with changes.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Benjamin Woods Hawaiian Airlines	06/24/2024	ALL page impacted with this revision		For each MMEL item revised in the FAA MMEL Rev 31, the FAA should align the MMEL numbers & sequence numbers with the EASA (Airbus OEM) MMEL. Aligning the numbering scheme would significantly reduce confusion when managing an operator's MEL for both the operator and the related FAA CMO. Additionally, since each operator is permitted to deviate from the FAA MMEL numbering, this alignment between the FAA MMEL and EASA/Airbus MMEL will not trigger/require significant revisions of an operator's MEL. However, it will solve a major problem and source of confusion in the industry. Ultimately, the entire FAA MMEL needs to be rewritten for better alignment in both numbering and content with the EASA/Airbus MMEL. Correcting the variance in MMEL numbering is a good first step.	For each item revised in the FAA MMEL Rev 31, the FAA should align the MMEL numbers & sequence numbers with the EASA/Airbus (OEM) MMEL. This would begin to correct this known problem before a larger rewrite/alignment project can be accomplished.	Concur. The FAA A320 MMEL and the EASA/Airbus MMEL have evolved separately for several years now and has resulted in the MMELs being on somewhat divergent paths with development of format and item relief language. One of the causes for the differences is Airbus has evolved to an electronic format whereas the FAA MMEL has maintained through the years it's current flat document format, i.e. MS Word Tables with an alphanumeric outline format. There are plans to renumber the A320 and A330 FAA MMELs to better align them with the EASA/Airbus versions. Though the FAA is still bound by the current MS Word Table format, the Airbus item numbering format can be adopted to these FAA MMELs (refer to A350 MMEL). The problem, of course, is that we will need to do a complete rewrite of the A320 and A330 FAA MMELs. Additionally, along with the format change, the relief for many/most items will need to be reevaluated to some extent in order to bring the relief remarks and exceptions into a better alignment for each of the items.

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
Benjamin Woods Hawaiian Airlines	06/24/2024	24-23	32-42-03 Item 1 a)	The MMEL deferral options for BSCU Channel 1/System 1 [items 1) “a)”, “b)”, “c)"] are only applicable for “Aircraft with Mod. 165148/ MP J4604” installed. Therefore, there is not a deferral option available for aircraft WITHOUT Aircraft with Mod. 165148/ MP J4604. However, the EASA/Airbus MMEL has deferral options for aircraft without Mod. 165148/ MP J4604.	Resolve this discrepancy between the FAA MMEL and EASA/Airbus MMEL. It seems item 1) a) should apply to aircraft with Mod. 165148/ MP J4604 installed.	Concur. The relief listed in 32-42-03 1) a) is for aircraft “without” Mod 165148/MP J4604. Corrected typo.