

DEF GENERAL INSURANCE LTD.

FNOL Registration Form

FNOL Date 10-Jul-2026

FNOL Registration Number FNOL-2026-0012

Member ID MEM-1012

Policy Number POL-2024-012

Vehicle Registration Number PB10IJ3345

Vehicle Make Honda

Vehicle Model Amaze

Vehicle Year 2022

Incident Date and Time 29-Jun-2026 16:55

Incident Type ACCIDENT_OWN

Incident Location GT Road (NH-1), Near Chheharta, Amritsar – 143001

Damage Description The insured vehicle was stationary in slow-moving traffic on GT Road when a Tata Ace goods carrier (PB02ZZ8812) rear-ended the vehicle at low speed. The rear bumper and boot lid were damaged. The impact caused the boot to jam shut. No airbag deployment. Damage was confined to the rear of the vehicle. No injuries to driver or passenger.

Third-Party Involved Yes – Tata Ace (PB02ZZ8812) was at fault

Third-Party Vehicle Reg. PB02ZZ8812 (Tata Ace goods carrier)

Third-Party Injury Reported No

FIR Filed No – amicable settlement between parties at scene, TP acknowledged fault

Legal Notice or Tribunal Ref. No

Claim Type Preferred Cashless

Preferred Garage Honda Authorised Workshop – Chheharta, Amritsar

Adjuster ID ADJ-112

Note on add-ons CONSUMABLES_COVER active – engine oil and brake fluid replacement costs claimable.

PA_PASSENGERS active – all occupants covered.

Declaration: I confirm that the information provided above is true and correct to the best of my knowledge. I understand that any misrepresentation may result in the rejection of this claim.

Claimant signature: _____ Date: _____

GOVERNMENT OF INDIA — MINISTRY OF ROAD TRANSPORT AND HIGHWAYS
REGISTRATION CERTIFICATE (SMART CARD FORMAT)

Issued by: Regional Transport Office, Amritsar (PB-10)

Registration Number PB10IJ3345

Registration Date 22-Mar-2022

Owner Name [Masked – MEM-1012]

Address [Masked – Amritsar, Punjab]

Vehicle Class Motor Car (LMV)

Make Honda Cars India Ltd.

Model Amaze V 1.2 Petrol

Body Type Sedan

Fuel Type Petrol

Engine Displacement 1199 cc

Engine Number L12B8123456

Chassis Number MAKGN3330NM789012

Colour Radiant Red Metallic

RTO PB-10 (Amritsar)

Registration Valid Upto 21-Mar-2037

Fitness Valid Upto 21-Mar-2027

Insurance Policy No. POL-2024-012

Insurance Valid Upto 14-Apr-2025

Hypothecation None

PUC Valid Upto 18-Sep-2026

Issued by Registering Authority. This is a digitally signed document. Verify at <https://parivahan.gov.in>.

GOVERNMENT OF INDIA — MINISTRY OF ROAD TRANSPORT AND HIGHWAYS
DRIVING LICENCE

Issued by: Regional Transport Office, Amritsar (PB-10)

Licence Number PB-10-2019-0078901

Name [Masked – MEM-1012]

Blood Group B+

Issue Date 15-Nov-2019

Valid (Non-Transport) Upto 14-Nov-2039

Valid (Transport) Upto 14-Nov-2034

Authorised Classes MCWG (Motorcycle with Gear) only

Issuing RTO PB-10 (Amritsar)

Licence Status ACTIVE

DL valid on incident date 29-Jun-2026 – YES, licence active, but authorised only for MCWG (motorcycle); does not hold authorisation for a Motor Car

Nominated Driver on POL-2024-012 Yes – DRV-015 matches this licence holder

This is a digitally signed document issued under the Motor Vehicles Act 1988. Verify at <https://sarathi.parivahan.gov.in>.

VEHICLE DAMAGE PHOTOGRAPH LOG

FNOL-2026-0012 · PB10IJ3345 (Honda Amaze 2022) · 29-Jun-2026

Photographs captured at scene by adjuster using authorised mobile application. This log is the photographic evidence record for this claim.

#	Filename / Timestamp	View	Observation
1	IMG_20260629_172312 29-Jun-2026 17:23	Rear – full	Rear bumper cracked across full width and partially displaced. Boot lid dented along lower edge – boot jammed shut. Rear number plate bent.
2	IMG_20260629_172328 29-Jun-2026 17:23	Rear – close-up	Boot lid hinge area buckled on left side. Tail lamp assemblies intact. Exhaust tip undamaged.
3	IMG_20260629_172344 29-Jun-2026 17:24	Engine bay – fluids	Minor engine oil seepage from dislodged filler cap. Brake fluid reservoir cap also dislodged – minor fluid loss. CONSUMABLES_COVER add-on active.
4	IMG_20260629_172400 29-Jun-2026 17:24	Front – full	Front bumper cracked and displaced. Bonnet buckled. Driver-side front airbag deployed – airbag module visible, deployed and unretracted. This damage pattern is not consistent with a low-speed rear-end collision.

Total photographs 4

Photo quality Clear – daylight conditions

Vehicle position Stationary at scene – not moved prior to photography

Adjuster observation Rear-end damage (bumper, boot lid) is consistent with the reported low-speed rear collision. However, the front bumper and bonnet also show fresh impact damage, and the driver-side front airbag has deployed – neither is consistent with the claimant's account of a rear-only, low-speed impact with no airbag deployment. This front-end damage and airbag deployment do not match the reported incident and require further verification before inclusion in this claim. CONSUMABLES_COVER add-on active – engine oil and brake fluid replacement costs claimable if verified as incident-related. NCB 50% will reset on claim settlement as NCB_PROTECT is not active on this policy – adjuster to inform claimant.