

ABC GENERAL INSURANCE LTD.

FNOL Registration Form

FNOL Date	12-May-2026
FNOL Registration Number	FNOL-2026-0001
Member ID	MEM-1001
Policy Number	POL-2024-001
Vehicle Registration Number	MH02AB4419
Vehicle Make	Maruti
Vehicle Model	Swift
Vehicle Year	2019
Incident Date and Time	12-May-2026 15:40
Incident Type	ACCIDENT_WITH_THIRD_PARTY
Incident Location	Andheri West Signal, S.V. Road, Mumbai – 400058
Damage Description	Vehicle was stationary at red light when a Honda Activa (MH02EF7734) coming from behind failed to brake and collided with the rear of the insured vehicle. Rear bumper severely damaged, boot lid dented, tail lights broken on both sides.
Third-Party Involved	Yes
Third-Party Vehicle Reg.	MH02EF7734
Third-Party Injury Reported	No
FIR Filed	Yes
FIR Number	MH-ANW-2026-4421
Police Station	Andheri West Police Station, Mumbai
Legal Notice or Tribunal Ref.	No
Claim Type Preferred	Cashless
Preferred Garage	Maruti Authorised Service Centre, Andheri West
Adjuster ID	ADJ-101

Declaration: I confirm that the information provided above is true and correct to the best of my knowledge. I understand that any misrepresentation may result in the rejection of this claim.

Claimant signature: _____ Date: _____

GOVERNMENT OF INDIA — MINISTRY OF ROAD TRANSPORT AND HIGHWAYS

REGISTRATION CERTIFICATE (SMART CARD FORMAT)

Issued by: Regional Transport Office, Mumbai West (MH-02)

Registration Number	MH02AB4419
Registration Date	18-Oct-2019
Owner Name	[Masked — MEM-1001]
Address	[Masked — Mumbai, Maharashtra]
Vehicle Class	Motor Car (LMV — Light Motor Vehicle)
Make	Maruti Suzuki India Ltd.
Model	Swift VXi
Body Type	Saloon
Fuel Type	Petrol
Engine Displacement	1197 cc
Number of Cylinders	4
Seating Capacity	5 (including driver)
Unladen Weight	865 kg
Engine Number	K12M1234567
Chassis Number	MA3FJEB1SKF123456
Colour	Pearl Arctic White
RTO	MH-02 (Mumbai West)
Registration Valid Upto	17-Oct-2034
Fitness Valid Upto	17-Oct-2024
Insurance Policy No.	POL-2024-001
Insurance Valid Upto	14-Jan-2025
Hypothecation	HDFC Bank Limited, Fort, Mumbai — Charge registered
PUC Valid Upto	11-Nov-2026
National Permit	Not applicable

Issued by Registering Authority, MH-02. This is a digitally signed document. Verify at <https://parivahan.gov.in>.

MUMBAI POLICE — FIRST INFORMATION REPORT
Under Section 154 Cr.P.C.

FIR Number	MH-ANW-2026-4421
Police Station	Andheri West Police Station
District	Mumbai Suburban
State	Maharashtra
Date of FIR	12-May-2026
Time of FIR	17:30 hrs
Date of Incident	12-May-2026
Time of Incident	15:40 hrs
Place of Incident	Near Andheri West Signal, S.V. Road, Mumbai – 400058

COMPLAINANT DETAILS

Name	[Masked — MEM-1001]
Address	[Masked — Mumbai, Maharashtra]
Phone	[Masked]
Vehicle Reg.	MH02AB4419 (Maruti Swift, 2019)

INCIDENT DESCRIPTION

The complainant states that on 12-May-2026 at approximately 15:40 hrs, his vehicle (Maruti Swift, MH02AB4419) was stationary at the Andheri West signal on S.V. Road when a Honda Activa bearing registration number MH02EF7734 approaching from behind failed to apply brakes in time and collided with the rear of the complainant's vehicle. As a result, the rear bumper was severely damaged, the boot lid was dented, and both tail light assemblies were broken. The rider of the Honda Activa was cooperative at the scene. No injuries were reported by either party.

Third-Party Vehicle	MH02EF7734 — Honda Activa
Third-Party Driver	Details noted — cooperation obtained at scene
Injuries	None reported
Witnesses	One bystander — contact noted
Sections Invoked	Motor Vehicles Act 1988 — Section 134 (duty to give information)
FIR Status	Registered
Officer in Charge	Sub-Inspector, Andheri West PS [Badge on file]

Signature of Officer: _____ Stamp: _____

This is a computer-generated FIR copy. Valid without physical signature as per Maharashtra Police Digital Records Act.

VEHICLE DAMAGE PHOTOGRAPH LOG

FNOL-2026-0001 · MH02AB4419 (Maruti Swift 2019) · 12-May-2026 · MH02AB4419 (Maruti Swift 2019) · IMG_202605

Photographs captured at scene by adjuster ADJ-101 using authorised mobile application.

This log is the photographic evidence record for this claim. Each entry records the filename, timestamp, GPS location, view angle, and damage observed.

#	Filename	Timestamp	GPS	View	Damage observed
1	IMG_20260512_154512	12-May-2026 15:45	19.1346° N, 72.8268° E	Rear — full	Rear bumper completely displaced. Boot lid pushed inward approx. 4 cm. Rear number plate bent.
2	IMG_20260512_154534	12-May-2026 15:45	19.1346° N, 72.8268° E	Rear — close-up	Both tail lamp assemblies shattered. Bumper mounting bracket visible. No fuel leak.
3	IMG_20260512_154601	12-May-2026 15:46	19.1346° N, 72.8268° E	Rear underside	Rear floor pan minor dent. Tow hook intact. No structural frame damage visible.
4	IMG_20260512_154623	12-May-2026 15:46	19.1346° N, 72.8268° E	Right side — full	No damage to right side, doors, or front. Impact confined to rear.
Total photographs		4			
Photo quality		Clear — daylight conditions			
Vehicle position		Stationary at scene — not moved prior to photography			
Adjuster observation		Damage is consistent with a rear-end collision. No pre-existing damage observed on undamaged panels.			