Generated 2026-10-25 14:57

Vehicle Identification (Visual Estimate)

Likely a Peugeot 207-era compact hatchback, with low confidence. The swept-back headlamp, rounded front end, and bumper styling are consistent with that general design, but the image shows only part of the vehicle and no clearly readable manufacturer badge. This is an uncertain visual estimate, not a verified make or model.

Summary

The image shows substantial damage to the visible front-side area, especially the front door and front fender. The front tire also appears deflated or collapsed. Several YOLO dent detections overlap in the same areas, so they should not be interpreted as separate confirmed impacts.

Damage by Category

- Body panels: Severe deformation and creasing are visible on the front door and front fender. The lower side/rocker area also appears damaged. YOLO returned five dent detections, including overlapping detections around these panels; the three strongest have confidence scores of approximately 0.61-0.74.
- Wheel and tire: The front tire appears collapsed against the ground, consistent with the YOLO "tire flat" detection, though that detection has low confidence (0.32). The wheel and tire assembly should be inspected directly.
- Alignment or adjacent components: Panel gaps and the area around the front wheel arch appear disturbed. Possible damage to mounting points or nearby components cannot be confirmed from this view.

Severity Assessment

High visible damage severity. The door and fender are extensively deformed, and the apparent flat tire may prevent safe driving. The extent of hidden structural, suspension, or mechanical damage is unknown.

Assessment Rationale (Brief)

The photograph shows pronounced crushing and creasing across the front-side door and fender, consistent with the clustered high-confidence dent detections. The visible tire collapse supports, but does not independently verify, the lower-confidence flat-tire detection. Overlapping detection boxes may represent the same damaged areas.

Repair Recommendations

- Do not drive the vehicle until the tire, wheel, and steering/suspension are inspected.
- Have a qualified repairer assess the door, fender, rocker area, panel gaps, and their mounting points.
- Inspect the wheel, tire, suspension, steering, and alignment for impact damage.
- Check behind the damaged panels for concealed structural or component damage before determining repairs.

Limitations

This assessment is based on one exterior image and supplied YOLO detections. It cannot confirm hidden damage, structural measurements, tire condition, or repairability. The detection boxes may overlap or include false positives, and the vehicle identification remains an uncertain visual estimate.

Image Evidence

segmented_damage.jpg

