

INDUSTRIAL BRAIN	Incident Report	Doc ID: Incident_Report_IR204
	Effective: 2023-01-01	Rev: 1.0

Incident Report: IR-204

Date: 2023-12-02 **Time:** 14:30 **Reporter:** Maria Gonzalez (Operations)

Incident Description

At 14:30, Unit 4 experienced a sudden partial shutdown. The control room received a high-temperature alarm for Pump P-101, immediately followed by a motor overload trip on Motor M-22. Field operators reported a loud grinding noise and smoke coming from the outboard bearing housing of P-101.

Immediate Actions Taken

- Locked out Motor M-22 at the MCC.
- Isolated Pump P-101 suction and discharge valves.
- Shifted cooling water load to the backup pump (P-102).

Initial Damage Assessment

Pump P-101 shaft is completely seized. Motor M-22 smells of burnt insulation but stator windings might be intact.

Prepared By / Technician

Approved By / Supervisor