

INDUSTRIAL BRAIN	Inspection Report	Doc ID: Inspection_Report_Nov2023
	Effective: 2023-01-01	Rev: 1.0

Routine Vibration Inspection Report

Date: 2023-11-12 **Inspector:** Sarah Connor **Assets Audited:** Unit 4 Rotating Equipment

Findings

1. **Compressor C-07:** Vibration at 0.08 in/s (Normal).
2. **Pump P-101:** Detected elevated vibration on the outboard bearing.
3. Reading: **0.21 in/s**
4. According to SOP-03, this is in the Warning/Alert threshold.
5. Accompanying thermal scan showed bearing housing at 78°C (elevated).
6. **Motor M-22:** Normal vibration, but drawing slightly higher amps than usual (58A).

Recommendation: Open a work order to inspect the P-101 outboard bearing immediately.

Prepared By / Technician

Approved By / Supervisor