

|                     |                       |                         |
|---------------------|-----------------------|-------------------------|
| INDUSTRIAL<br>BRAIN | Work Order            | Doc ID: Work_Order_9942 |
|                     | Effective: 2023-01-01 | Rev: 1.0                |

## Work Order: WO-9942

---

**Status:** OPEN (Delayed) **Created:** 2023-11-14 **Priority:** High **Asset:** Pump P-101

**Description:** Elevated vibration detected (0.21 in/s) by Sarah Connor. Suspected bearing issue. **Action Required:** Perform vibration spectrum analysis and prepare to replace outboard bearing.

**Updates:** - 2023-11-16 (*John Smith*): We do not have the FM-5000 replacement bearing in stock. Ordered from FlowMaster. ETA is Dec 5th. - 2023-11-20 (*Alex Chen*): Operations cannot spare the pump right now. We will run it to failure or until parts arrive, whichever comes first. Monitor closely.

---

Prepared By / Technician

---

Approved By / Supervisor