Tabla II Distribución de Poisson (puntual)

	r	0	1	2	3	4	5	6	7	8	9	10	11	12
	λ	7			2							H		
		.9048	.0905	.0045	.0002	.0000								
	2	.8187	.1637	.0164	.0011	.0001	.0000							
	3	.7408	.2222	.0333	.0033	.0002	.0000							
	4	.6703	.2681	.0536	.0072	.0007	.0001	.0000						
	5	.6065	.3033	.0758	.0126	.0016	.0002	.0000		rythropromoty and area trades both decrees	nere de la managent de la lace de la company			and the state of t
	6	.5488	.3293	.0988	.0198	.0030	.0004	.0000	0000					
	7	.4966	.3476	.1217	.0284	.0050	.0007	.0001	.0000					
	8 9	.4493	.3595 .3659	.1438	.0383 .0494	.0077	.0012	.0002	.0000					
	.0	.4066 .3679	.3679	.1647	.0494	.0111 .0153	.0020	.0003	.0000	.0000				
	.1	.3329	.3662	.2014	.0738	.0203	.0031	.0003	.0001	.0000		ACTIVITY OF THE STATE OF THE ST	******************************	
	.2	.3012	.3614	.2169	.0736	.0260	.0043	.0008	.0001	.0000				
	.3	.2725	.3543	.2303	.0998	.0324	.0084	.0012	.0002	.0001	.0000			
	.4	.2466	.3452	.2417	.1128	.0395	.0111	.0026	.0005	.0001	.0000			
	.5	.2231	.3347	.2510	.1255	.0471	.0141	.0025	.0008	.0001	.0000			
	.6	.2019	.3230	.2584	.1378	.0551	.0176	.0047	.0011	.0002	.0000	***************************************	The state of the s	Management of American Strategics and American
	.7	.1827	.3106	.2640	.1496	.0636	.0216	.0061	.0015	.0003	.0001	.0000		
	.8	.1653	.2975	.2678	.1607	.0723	.0260	.0078	.0020	.0005	.0001	.0000		
	.9	.1496	.2842	.2700	.1710	.0812	.0309	.0098	.0027	.0006	.0001	.0000		
	.0	.1353	.2707	.2707	.1804	.0902	.0361	.0120	.0034	.0009	.0002	.0000		
-	2	.1108	.2438	.2681	.1966	1082	.0476	.0174	.0055	.0015	.0004	.0001	.0000	Marine de la companya
	4	.0907	.2177	.2613	.2090	.1254	.0602	.0241	.0083	.0025	.0007	.0002	.0000	
	.6	.0743	.1931	.2510	.2176	.1414	.0735	.0319	.0118	.0038	.0011	.0003	.0001	.0000
	.8	.0608	.1703	.2384	.2225	.1557	.0872	.0407	.0163	.0057	.0018	.0005	.0001	.0000
	.0	.0498	.1494	.2240	.2240	.1680	.1008	.0504	.0216	.0081	.0027	.0008	.0002	.0001
3.	2	.0408	1304	.2087	.2226	.1781	.1140	.0608	.0278	.0111	.0040	.0013	.0004	.0001
3.	4	.0334	.1135	.1929	.2186	.1858	.1264	.0716	.0348	.0148	.0056	.0019	.0006	.0002
3.	.6	.0273	.0984	.1771	.2125	.1912	.1377	.0826	.0425	.0191	.0076	.0028	.0009	.0003
3.	.8	.0224	.0850	.1615	.2046	.1944	.1477	.0936	.0508	.0241	.0102	.0039	.0013	.0004
4.	.0	.0183	.0733	.1465	.1954	.1954	.1563	.1042	0595ء	.0298	.0132	.0053	.0019	.0006
5.	.0	.0067	.0337	.0842	.1404	.1755	.1755	.1462	.1044	.0653	.0363	.0181	.0082	.0034
- 6.		.0025	.0149	.0446	.0892	.1339	.1606	.1606	.1377	.1033	.0688	.0413	.0225	.0113
	.0	.0009	.0064	.0223	.0521	.0912	.1277	.1490	.1490	.1304	.1014	.0710	.0452	.0264
8.		.0003	.0027	.0107	.0286	.0573	.0916	.1221	.1396	.1396	.1241	.0993	.0722	.0481
9.		.0001	.0011	.0050	.0150	.0337	.0607	.0911	.1171	.1318	.1318	.1186	.0970	.0728
→ ,10	0.0	.0000	.0005	.0023	.0076	.0189	.0378	.0631	.0901	.1126	.1251	.1251	.1137	.0948
	r	13	14	15	16	17	18	19	20	21	22	23	24	
manufacture and the fact that	١					***************************************								
5.		.0013	.0005	.0002			10					22		
6.		.0052	.0022	.0009	.0003	.0001								
7.	1	.0142	.0071	.0033	.0014	.0006	.0002	.0001						
8.	- 1	.0296	.0169	.0090	.0045	.0021	.0009	.0004	.0002	.0001				
9.		.0504	.0324	.0194	.0109	.0058	.0029	.0014	.0006	.0003	.0001		an area as	
10	.0	.0729	.0521	.0347	.0217	.0128	.0071	.0037	.0019	.0009	.0004	.0002	.0001	enementy serven de mineral mente plante de