

100% U.S. Based Manufacturing With Facilities Located in Aurora, CO, Tempe, AZ, & Maple Grove, MN



FreeDFM Viewer 2.0

ī

Modify Specs		Viewer (Click Update Quote to cha	ange Active Quote to	Iteration Specs Selected)	Specs	
Input Parameters —		-		Divers Hole		Original	
Copper Outers:	1 oz ▼			<u>Plugin Help</u>		Outer Copper: 1	
Copper Inners:	0.5 oz ▼				☑ s1		.005
11						Inner Copper: 0	
Material Thickness:	0.062" ▼				☑ m1		.005
Croata Now C	Quote Iteration	-			☑ I1	Min 0	.005
Create New C	audie iteration	_			☑ Ib	Trace/Space:	
A ative Overte	000070460F066700	$\neg \parallel$			№ m2	Thickness:	.062
Active Quote	0030734605266722						.028
Quote	5266722				№ s2		
PART NUMBER	1				☑ drp	Pricing *(Pricin	a is h
MATERIAL TYPE	FR4					Tricing (Friesis	9 15 5
MATERIAL THICK	0,062					Standard Pricing—	
COPPER_OUTERS	1				Trace/Space Thresholds	Qty Same Day	1-D
COPPER_INNERS	0				01 02 03 04 05		\$167
TRACE	0.005				FIRST BACK NEXT	10 \$127.22	\$88.7
SM_HOLE	0.028				To view a list of potential	50 \$27.99	\$20.2
LAYER	2				manufacturing problems with	150 Call Us	Call (
DIMENSION_1	6				this project that FreeDFM has	Tooling NRE = \$0	.00
DIMENSION_2	4				detected, please select a Trace/Space Threshold value.		
PLATING	LFSolder				Trace/opace Trice/icia Talaci	Custom Pricing	
TRACEINNER	0.008					0	
GOLD	None				Problems Automatically	Qty Day 1-0	Day
MOUNTS_TOP	109 0				Fixed by FreeDFM.com™	5 \$480.51 \$393	3 36 \$
MOUNTS_BOTTOM PITCH	0,02				To view a list of potential	10 \$257,30 \$210	
SOLDER SIDES	2				manufacturing problems with this project that FreeDFM has	50 \$97.88 \$79	
SOLDER TYPE	LPI				fixed, please click here.	150 Call Us \$49.	_
. –							
ROUTE POINTS	4					Liouning Hitz #20	=======================================
TAB_ROUTE_ARRAY	No					4	
SCORING	No	¥				1	
SILKSCREEN_SIDES ROUTE_POINTS TAB_ROUTE_ARRAY	2 4 No					Tooling NRE= S	

^{*} This pricing is based on the design rule check values used to prepare your custom FreeDFM report. Any DFM issues that were identified that are not resolved before placing your order may result in your order being placed on CAM hold and potentially requiring a price change. If you would prefer a quote prepared for the design without fixing the reported issues please contact your sales representative.