

Quarterly Maintenance Report

Section 1: Track Inspection Summary

A total of 42 track segments were inspected during Q2.

3 segments were flagged for follow-up repair work.

Section 2: Sensor Readings

Average rail temperature: 28.4 degrees C

Maximum vibration reading: 4.7 mm/s

No anomalies exceeded safety thresholds this quarter.

Section 3: Recommendations

Schedule repair crews for the 3 flagged segments within 30 days.

Recalibrate vibration sensors on line B before next quarter.