

SOP: Chemical Storage Handling and Safety Procedure

Section 1.0: Caustic Ingestion and Unloading

Safe handling procedure for caustic soda unloading operations.

Section 2.0: Personal Protective Equipment

Operators must wear full chemical-resistant suits, face shields, and rubber boots. A safety shower and eyewash station must be inspected and confirmed functional within 10 meters of the work area before unloading starts.