

SOP: Substation Electrical Maintenance Procedure

Section 1.0: Electrical Substation Safety

Applies to high voltage breaker servicing.

Section 2.0: Safety Protocol

No work shall start without a valid electrical isolation permit. The technician must wear dielectric gloves and safety boots. Isolation must be locked out, tagged out, and verified using a calibrated voltage tester.