

SOP: Hot Work Permit Procedure

Section 1.0: Scope of Hot Work

Covers operations involving welding, cutting, grinding, and open flames in the plant premises.

Section 2.0: Combustible Management

To prevent fires, all combustible materials, oil drums, and rags must be cleared from a radius of 5 meters around the hot work spot. Any items that cannot be moved must be covered with fire-retardant blankets.