

The Factories Act, 1948

Section 36.1: Egress and Manhole

No person shall enter or be permitted to enter any chamber, tank, vat, pipe, flue or other confined space in any factory in which any gas, fume, dust or vapor is likely to be present so as to involve risk of persons being overcome thereby, unless it is provided with a manhole of adequate size or other effective means of egress.

Section 36.2: Gas Free Certification

No person shall enter any such confined space until a competent person has examined the space, certified in writing that the space is free from dangerous gas, fume, dust or vapor, and that the person entering wears a suitable breathing apparatus and a safety belt securely attached to a rope, the free end of which is held by a person outside.

Section 37: Explosive Gas Controls

Where any process in a factory gives rise to dust, gas, fume or vapor of such character and to such extent as to be likely to explode on ignition, all practicable measures shall be taken to prevent such explosion by: (a) effective isolation of the process, and (b) exclusion or effective enclosure of all possible sources of ignition.