




It should be recognized that cable depths shown on this map may be unreliable as the cables were installed and the relative position of cables may also have changed due to the alteration of original landmarks.

GI6 SW