

F 72

2
1
2

It should be recognized that cable depths shown on this map may be unreliable as the ground level may have changed since the cables were installed and the relative position of cables may also have changed due to the alteration of original landmarks.

J18 SW